

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Fax: 62564315

Date : 26 January 2018

TO MOTOR CLAIM DEPT

MSIG INSURANCE PTE LTD

16 Raffles Quay #24-01


Hong Leong Building

Singapore 048581

Vehicle No: EF88G
Model: MERCEDES BENZ E300 AMG
Chassis: WDD2383482F015198
Policy No: A29021463QMY
Date of Accident: 24/01/2018

ESTIMATE

QTY	DESCRIPTION	UNIT	S\$	AMOUNT S\$
1	FRONT BONNET	—		Per \$1,390.00 ✓
1	FRONT FENDER LH	—		Per \$620.00 ✓
1	FRONT FENDER INNER SHIELD FRONT LH	—		Per \$72.00 ✓ \$65.00
8	FRONT FENDER INNER SHIELD CLIP	—	\$6.00 \$4.00	Per \$32.00 ✓ \$48.00
1	FRONT HEADLAMP LH	—		CM \$3,475.00 ✓
1	FRONT HEADLAMP LED MODULE LH	—		\$365.00 ? X
1	FRONT HEADLAMP CONTROL MODULE LH	—		\$390.00 ? ✓
1	FRONT BUMPER	—		Buc lens \$1,175.00 ✓
1	FRONT BUMPER SIDE GARNISH LH	—		Per \$55.00 ✓
1	FRONT BUMPER SIDE RETAINER LH	—		CM \$13.00 ✓
1	FRONT BUMPER INNER SUPPORT FRAME	—		CM \$37.00 ✓ ?
10	FRONT BUMPER CLIP	—	\$6.00	Per \$60.00 ✓
8	FRONT BUMPER RIVET	—	\$6.00	Per \$48.00 ✓
1	FRONT BUMPER LOWER CENTRE GRILLE	—		Per \$89.00 ✓ ?
1	FRONT BUMPER TOP RUBBER SEAL	—		Per \$18.00 X
1	FRONT BUMPER TOP BEAM	—		CM \$127.00 ✓
1	FRONT BUMPER INNER SPONGE	—		\$108.00 ? ✓
1	FRONT BUMPER REINFORCEMENT	—		\$312.00 ? ✓
1	FRONT BUMPER LOWER UNDER COVER	—		Per \$150.00 X
1	FRONT GRILLE	—		\$266.00 ? ✓
1	FRONT GRILLE LOGO EMBLEM	—		\$83.00 ? ✓
1	FRONT GRILLE LOGO EMBLEM BASE	—		\$45.00 ? ✓ \$162.00
1	FRONT GRILLE CHROME MOULDING	—		CM \$398.00 ✓
1	FRONT GRILLE TOP BRACKET	—		\$205.00 ? ✓
1	FRONT SUPPORT PANEL	—		R \$490.00 X
1	FRONT BRACE PANEL	—		R \$49.00 ✓ ?
SUB TOTAL				\$10,072.00 \$9013.00
COST +10%				\$1,007.20 \$901.30
PARTS TOTAL				\$11,079.20 \$9914.30



For NLS
Not Authorized
Resurvey B4 paint
Ex B7odh
5 days

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date : 31 January 2018

**TO MOTOR CLAIM DEPT
MSIG INSURANCE PTE LTD**

Vehicle No: EF88G

16 Raffles Quay #24-01

Model: MERCEDES BENZ E300 AMG

Hong Leong Building

Chassis: WDD2383482F015198

Singapore 048581

Policy No: A29021463QMY

Date of Accident: 24/01/2018

SUPPLEMENTARY

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER LOWER CENTER GRILLE CHROME GARNISH	/	\$278.00
1	FRONT BUMPER LOWER UNDER LH SIDE COVER	/	\$53.00
		SUB TOTAL	\$331.00
		COST +10%	\$33.10
		SUB TOTAL	\$364.10

WINSON

Total

\$364.10

①

P - 9914.30

L - 1780

S - 364.10

12058.40

(350)

+ 180

11868.40

P/P

keneth

9904.40

1610

364.10

11878.50

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date : 26 January 2018

TO MOTOR CLAIM DEPT

MSIG INSURANCE PTE LTD

16 Raffles Quay #24-01

Hong Leong Building

Singapore 048581

Vehicle No: EF88G

Model: MERCEDES BENZ E300 AMG

Chassis: WDD2383482F015198

Policy No: A29021463QMY

Date of Accident: 24/01/2018

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

\$1,000.00

600/

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$1,000.00

750/

TO TUFF KOTE / ANTI-RUST

nn \$40.00 X

TO CHECK WIRING, REPLACED WITH FOCUS HEADLAMP &
WATER LEAKAGE TEST

\$80.00

20/

→ TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD

\$350.00

7/

TO DISMANTLE & REPLACED AIRCON SYSTEM, VACUUM WITH FL
AIRCON GAS/OIL

TO DISMANTLE & REPLACED RADIATOR WITH HIGH PRESSURE TE

TO DISMANTLE & REPLACED FRONT BUMPER PARKING SENSOR

\$80.00

60/

LABOUR TOTAL

\$2,790.00

1780.00 /

WINSON

Total

\$13,869.20

1610

↑
Kenneth giving \$180 only.
ok?? accept?? 28/6/18