

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2881/01/18 Your Ref: Date: 26th JAN 2018

M/S BEST GARB SERVICE
BLK 406, #10-834
SEMBAWANG DRIVE, S (750406)

Estimate cost of repair to SUBARU XV 1.6 (A) MPV - SKS 9626 E

1 pc front bumper		DIS \$ 659.40	✓
8 pcs front bumper clips	@ \$ 3.40	27.20	✓
1 pc front bumper towing bar cover		18.00	✓
2 pcs front bumper o/s & n/s side retainer	@ \$ 26.00	52.00	✓
1 pc front bumper o/s fog lamp garnish		31.00	✓
1 pc front bumper sponge damper		79.20	✓
1 pc front bumper reinforcement		288.00	✓
1 pc o/s head lamp assy		900.00	✓
1 pc front grille frame moulding		304.00	✓
1 pc front support panel		520.00	✓
1 pc front number plate & frame		50.00	✓

Less 20% \$ 2,928.80
\$ 585.76
\$ 2,343.04

To wiring check up & adjust headlight alignment.	50.00	20
To remove & refix air cond parts & refill R134 gas.	11 150.00	X
To check & adjust front wheel alignment & balancing.	11 120.00	X
To respray Tuff-Kote on all affected accident parts.	11 50.00	X
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front fender & necessary parts, to weld, renew & align above parts.	750.00	400
To putty & respray painting on all affected accident parts.	900.00	600
	\$ 4,363.04	

Dollars : Four Thousand Three Hundred Sixty Three And Cents Four Only.

HUP MOTOR TRADING & SERVICE

- KK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Ackd
2/1/18
3 day
to hup motor trading & service
29/1/18