

INS CASE OWNER

Zuhaidah

CC 6/III18001703

1 Uys 3 9

ASSIGNMENT

Surveyor:

MARCUS

DOI:

29/01/18

Date / Time:

29/01/18

Registered in Merimen:

29/01/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHA 1161L

Name of Insured:

CTPL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

22/01/18

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

Claim No.:

MCT18010810

Policy No.:

MCOM0015

Make / Model:

HYUNDAI I40

Place of Accident:

KPE (TPE) B4 TAMPINES

If NO, Driver Name / Age: YU KWANG MENG

OI GIA REPORT: ☒ YES / NO : TP GIA REPORT: ☒ YES / NO

Driver Tel No.:

(V/L ☒ YES / NO)

Insured Liability: %

Final ? Yes / No

SKH 1760K



INSRS:

WSP: Hup motor

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost

S\$ 7900

(6 days)

Reduction:

58

%

Email ☐Call ☒

FINAL SETTLEMENT

Date/Time:

19/02/18

Confirm with:

David

Email ☒Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost

S\$ 7,900.00

Loss of Rental (LOR): 120

S\$

840.00

(7 days)

Loss of Use (LOU):

S\$

0

x

(7 days)

Loss of Income (LOI):

S\$

0

x

(7 days)

LOR only ☒ LOU only ☐

S\$

0

x

(7 days)

GIA/LTA Search

S\$

7.45

Medical

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$ 8,747.45

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

S\$

8,747.45

Name 1:

Hup Motor Trading & Service

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT
22/02/18

RECEIVED 2 FEB 2018

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKH 1760Kat Workshop m/s hup ntu-

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L7A 7660

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKH 1760K Yr Regn: 11/12Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAIMake: Mer Benz E250A cc 1796Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 104701 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2120472A602344Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 245/40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ContinentalFront 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 28/1/18 D.O.I. 29/1/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date	Time	Action / Instruction
30/1/18		Confirmed w/s 47900 with David.

Date/Time, File Pass to? *

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC6/III18001703/Uys3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 29-01-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1161L	Veh. Inspected	SKH 1760K	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	29/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/01/2018	Inspection Date	29/01/2018	
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2695G
Vehicle Details	
Vehicle No.:	SKH1760K
Vehicle to be Exported:	No
Intended De-registration Date:	30 Jan 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E250 A
Primary Colour:	Silver
Manufacturing Year:	2012
Engine No.:	27186030453159
Chassis No.:	WDD2120472A602344
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$44,940.00
Original Registration Date:	12 Nov 2012
First Registration Date:	12 Nov 2012
Transfer Count:	0
Actual ARF Paid:	\$44,940.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Nov 2022
PARF Rebate Amount:	\$31,458.00
Intended COE Rebate Details	
COE Expiry Date:	11 Nov 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$95,034.00
COE Rebate Amount:	\$45,202.00
Total Rebate Amount:	\$76,660.00

The information contained herein is correct as at 30 Jan 2018

OK

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2882/01/18

Your Ref:

Date: 29th JAN 2018

Madam Ang Beng Choo
Blk 113, #07-35
Rivervale Walk,
Singapore 540113

Estimate cost of repair to MERCEDE BENZ E250 (A) Saloon - SKH 1760 K

1 pc front o/s door	Body	\$ 2,070.00	✓
1 pc front o/s door moulding	rer	93.00	✓
1 set front o/s door frame sticker	rer	86.00	✓
1 pc front o/s door weatherstrip	rer	280.00	✓
1 pc front o/s door side mirror casing cover	rer	287.30	α
1 pc rear o/s door	Body	2,125.00	✓
1 pc rear o/s door moulding	D.S	93.00	✓
2 pcs rear o/s door top & low hinge (\$ 135.00 + \$ 158.00)	rer	293.00	α
1 pc rear o/s door weatherstrip	rer	280.00	✓
1 set rear o/s door frame sticker	rer	86.00	✓
1 pc rear o/s door glass regulator	rer	1,293.00	α
1 pc rear o/s door glass channel	rer	166.00	α
30 pcs front & rear o/s door inner trim board clips	u \$ 9.00	270.00	α
1 pc rear o/s fender	rer	2,200.00	α
8 pcs rear o/s fender inner garnish clips	u \$ 9.00	72.00	α
1 set rear windscreen glass repair kit	rer	1,377.00	α
1 pc fuel tank lid panel	rer	271.00	α
1 pc rear bumper	Depo/rep	1,462.00	✓
1 pc rear bumper o/s side retainer	rer	58.00	✓
8 pcs rear bumper clips	u \$ 9.00	72.00	✓
1 pc o/s rocker panel sideskirt garnish	rer	687.00	✓
8 pcs o/s rocker panel sideskirt garnish clips	u \$ 9.00	72.00	✓
2 pcs front & rear o/s sport rim	u \$ 694.00	1,388.00	1 pc
		\$ 15,081.30	8158
	Less 10%	\$	10%
		\$	7342.20

To wiring check up for affected wiring system,	50.00	30
To check & adjust wheel balancing & alignment.	180.00	80
To remove & refix rear windscreen glass & necessary parts.	200.00	α
To diagnose & reset door centre locking & air-bag sensor code.	150.00	50
To remove & refix front & rear o/s door inner trim board cover, glass, motor, regulator, moulding, channel, inner lock, hinge, handle, checker, weatherstrip & necessary parts.	300.00	160
To remove & refix fuel tank, hose, pipe & necessary parts.	150.00	60

Balance C/P.....

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2882/01/18

Your Ref: _____

Date: 29th Jan 2018

Madam Ang Beng Choo.,

Balance B/F..... \$

To remove & refix carpet, floor mat, garnish, floor board cover,
tool set & necessary parts, to enable repair rear o/s fender,
o/s rocker panel & necessary parts.

150.00 60

To respray Tuff-Kote on all affected accident parts.

150.00 80

Labour charge to remove, refix & pump sealant for o/s rocker
panel side skirt.

150.00 80

Labour charge to remove & cut out damaged parts, to jack, straighten
& knocking out rear o/s fender, o/s rocker panel, centre door pillar
& necessary parts, to weld, renew & align above parts.

1,800.00 800

To putty & respray Painting on all affected accident parts.

2,000.00 1200

\$ 18,353.17

Dollars :

HUP MOTOR TRADING & SERVICE



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Print Received Message

This mail is associated with :

***SKH1760K (MCT18010850)
[SHA1161L]**

TP

ANG BENG CHOO

Jan 28 2018 6:00PM

[COMFORT TRANSPORTATION PTE LTD]

Hup Motor Trading & Service

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 13/02/2018 14:06 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8747.45) - SKH1760K - Claim Handler: Zuhaidah Bte Samsuri

Approved:8747.45:Please negotiate LOR @ \$100 per day (rented veh Toyota Altis). Please upload 'after repair' photos and rental bill. Thanks.

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE Email : hupmotor@gmail.com

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 WEB SITE: http://hupmotor.com.sg Reg. No. 378091/00W

Our Ref: TF 2882/01/18 Your Ref: Date: 7th February 2018

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
64, Cecil Street, #05-00, IOB Bldg.
Singapore 049711

Dear Sirs,

RE : ACCIDENT ON 28/01/18 ALONG K.P.E. TOWARDS SENGKANG
INVOLVING : SKH 1760 K & YOUR INSURED : SHA 1161 L

We act for Mdm Ang Beng Choo., NRIC No : S1512695G
Who is the registered owner of Veh. No : SKH 1760 K Which was involved
in the above accident with Veh. No : SHA 1161 L Which we understand
is insured with you.

Your appointed surveyor had surveyed our client's damaged vehicle and
we had repaired the vehicle.

The accident was clearly caused by your insured's negligence, I am,
therefore, seeking compensation from you for my financial losses as
itemised below : -

Cost of repair	\$ 7,900.00
Car rental for 7 days (1 day X \$ 120.00)	840.00
LTA Search Fee & GIA-RMC Search Fee	7.45
Survey Fee	0.00

\$ 8,747.45
=====

We have enclosed copies of relevant documents to support my client's
claim, There was no receipt enclosed, as my client's did not pay us
any single amount.

Your prompt settlement of our claim would be much appreciated.

Yours faithfully,

HUP MOTOR TRADING & SERVICE

Mr David Ang B. Y.

Encl : Final Bill, Car Rental Bill, LTA Search Fee, Owner Authorisation
Letter, GIA Report, Survey Report & Ins. Cert.

Remark : Kindly acknowledge receipt.

Note : Car rental total 7 days, dur to 04/02/18 was Sunday, Not working day,
Client vehicle was Mercedes Benz, We provide only Toyota Altis
SAVE AS COST

TO : M/S INDIA INTERNATIONAL INSURANCE PTE. LTD.

AUTHORIZATION TO ACT

I, Mdm Ang Beng Choo (S1512695G) ("the third party claimant")

of Blk 113, #07-35, Rivervale Walk, S (540113) (address),

owner of SKH 1760 K (vehicle no.) hereby authorize

Hup Motor Trading & Service,

("The workshop") to act for me with respect to my claim for

repair costs and/or rental and/or loss of use ("claim") for my

Vehicle No. SKH 1760 K that was damaged pursuant to the

accident which occurred on 28/01/18 (date) along K.P.E.

Towards Sengkang (location)

involving Vehicle No/s SHA 1161 L

("The accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 31st day of January (month) 20 18 (year)

HUP MOTOR TRADING & SERVICE

洪明珠 Owner Of SKH 1760 K
Mdm Ang Beng Choo (S1512695G)

Signed by "the third party claimant"

[Signature]
Signed by "the workshop"

EXPRESS SETTLEMENT

DISCHARGE VOUCHER

III-Direct Settlement (PODS)

India Ref: NCT12010250

Claimant Ref: SKH 1760K

We, Hup Motor Trading & Service ("the workshop") hereby confirm that we have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 7,900.00 (repair cost), S\$ 840.00 (loss of rental), S\$ 7.45 (search fee), vehicle no SKH 1760K that was damaged pursuant to the accident which occurred on 28/01/18 (date) at KPE LPE before Tampines (location) involving vehicle no SHA 1161L (insured vehicle). This is pursuant to the inspection conducted on 29/01/18 (date) at "the workshop".

We confirm that we are authorized by the owner Ang Beng Choo ("the third party claimant") of vehicle no SKH 1760K to make the claim as set out in the above paragraph and we have full authority to settle the matter on his/her behalf in a manner that we deem fit. We enclose herein the letter of authority given by "the third party claimant".

We further confirm that we will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SKH 1760K (vehicle no.) as a result of the accident.

We confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We authorize you to pay the total amount of S\$ 8,747.45 to Hup Motor Trading & Service

Dated this 27 day of February 2018

CLAIMANT: **HUP MOTOR TRADING & SERVICE**

Signature: _____

Name: ANG BENQ YUEN

NRIC: S1547254E

Address: BUKIT #08-1096
YONG KUN PARK RD # (760241)

Nationality: SINGAPOREAN

Occupation: MANAGER

WITNESS: _____

Signature: _____

Name: _____

NRIC: _____

Address: _____

Nationality: _____

Occupation: _____



Signed by appointed Surveyor

LKK AUTO CONSULTANTS PL
51 Ubi Ave 1, #01-25
Paya Ubi Industrial Park
Singapore 408933
Tel: 6256 3561

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2882/01/18 Your Ref: _____ Date: 7th February 2018

Madam Ang Beng Choo
Blk 113, #07-35
Rivervale Walk,
Singapore 540113

Cost of repair to MERCEDE BENZ E250 (A) Saloon - SKH 1760 K

To supply front o/s door, moulding, sticker, weatherstrip, rear o/s door, moulding, sticker, weatherstrip, rear bumper, side retainer, clips, o/s sideskirt garnish, clips, sport rim & necessary parts.

To wiring check up for affected wiring system, to check & adjust wheel alignment & balancing, to diagnose & reset door centre locking system & air-bag sensor code.

To remove & refix front & rear o/s door inner trim board cover, glass, regulator, motor, channel, hinge, moulding, weatherstrip, inner lock, handle, checker & necessary parts, including remove & refix fuel tank, hose, pipe & necessary parts.

To remove & refix cushion seat, carpet, floor mat, garnish, floor board cover, tool set & necessary parts, including remove, refix & pump sealant for o/s rocker panel sideskirt.

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear o/s fender, o/s rocker panel, o/s centre door pillar panel & necessary parts, to weld, renew & align above parts.

To putty & respray painting on all affected accident parts, including respray Tuff-Kote on all affected accident parts.

Lump Sum Repair : \$ 7,900.00
=====

Dollars : Seven Thousand And Nine Hundred Only.

HUP MOTOR TRADING & SERVICE

.....




專營連善必甲出租
汽車修理
汽車保險賠償服務
嘉賓多授權服務中心

國家汽車服務

NATIONAL AUTOMOBILE SERVICE

Block 5033, Ang Mo Kio Industrial Park 2, #01-279
(off Ang Mo Kio Avenue 3) Singapore 569536
TEL: 6482 5577 (3 Lines) FAX: 6482 5000
TOWING SERVICE: 9182 8211 (After 10.30pm)
Reg. No: 062389/00M



TRUCK RENTAL
MOTOR REPAIR
INSURANCE CLAIMS
AGENCY
AUTHORISED CASTROL
SERVICE CENTRE

车辆出租合同 VEHICLE RENTAL AGREEMENT

Date: 3/1/18
Owner: NATIONAL AUTOMOBILE SERVICE ("the owner")
Hirer: Madam Ang Beng Choo (Owner Of SKH 1760 K)
Address: Blk 113, #07-35, Rivervale Walk, S (540113)
NRIC / Co. Reg. No: S1512695G
Tel: 96772982 (Driver) Fax: H/P: 96573348 (Owner)

Owner and Hirer have agreed to enter into this Vehicle Rental Agreement for the motor vehicle described below and upon the terms and conditions contained on both sides of this document. Hirer acknowledges having read and understood all the terms and conditions and signifies acceptance upon signing.

Vehicle Reg. No: SLK52186 TOYOTA ALTIS		Agreement No.: 56470	
Driver's Particulars		Odometer: 16936 (+ fuel)	
Name: Mr Ng Chee Sai		Date & Time Out: 3/1/18 10:10hrs	
Address: As Above		Date & Time In: 07/02/18 10:30hrs	
I/C No: S2553790D	Dr/Licence No: S2553790D	Hour @\$	
Date of Issue: 28/11/2010 YOD: 06/06/84	Occupation: Director	7 Days @\$ 120-00	\$ 840-00
Date of Birth: 09/10/1956	Tools: Spare Tyre: 01w 01w	Wks @\$	
		Mths @\$	

Third Party Claim

In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive). Hirer unconditionally agrees to pay Owner \$5000 excess for collision/damage to first party, (i.e.) comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.

Own Vehicle Damage

Hirer is responsible for the first \$5000 excess for collision/damage to first party, (i.e.) NATIONAL AUTOMOBILE SERVICE (including windscreens) plus loss of earnings while damaged vehicle is under repair.

Authorised Driver

Hirer shall pay additional excess of \$51500 if the Authorised Driver is below the age of 25 or is above 65 years old or has less than 2 years driving experience.

Driver Not Cover By Insurance

General Exception: Insurance policy does not cover against any driver aged below 22 and/or above 70 years old and/or with driving experience of 1 year and below.

Deposit (Refundable): NIL
Sub-Total: \$ 840-00
Balance To Pay: \$ 840-00

PETROL/DIESEL AT YOUR OWN EXPENSE
FOR LOCAL USE ONLY

NATIONAL AUTOMOBILE SERVICE

Authorised Signature

Hirer's Signature

Enquire Vehicle & Owner Information (Vehicle No. SHA1161L As At 28 Jan 2018 / 18:05:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: HL/HMT/18

Current Owner Details

Owner ID Type: Company
Owner ID: 199303821R
Owner Name: COMFORT TRANSPORTATION PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 383
Registered Street Name: SIN MING DRIVE
Registered Unit No.: -
Registered Building Name: GAS BUILDING
Registered Postal Code: 575717

Current Vehicle Details

Vehicle No.: SHA1161L
Make Description/Model: HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Insurance Company Name: INDIA INT'L INS PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2018 Edit Reg		29 Jan 2018 00:00 Edit Adj Rpt	\$57,900.00 Edit Estimates	\$57,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R									
Main Claimant: ANG BENG CHOO , ID: S1512695G									
Vehicle Reg. No.:		SKH1760K	Date of Loss:	28/01/2018 18:00 - :59					
Claim Type:		TP / MCT18010850	Policy/Cover Note No.:	MCOM0015					
Vehicle Reg. No. (Insured):		SHA1161L	Policy No. (Claimant):	M493855					
		Excess:							
Repairer: Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120, 528838 Tampines - Tel: 67840039/98154655									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]									
Claimant's Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 07/02/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (13/02/2018): Alert - Adj Mandate Approved (\$8747.45) - SKH1760K - Claim Handler: Zuhaidah Bt... - III_SG (09/02/2018): Alert - Adj Mandate Maintained - SKH1760K - Claim Handler: Zuhaidah Bte Samsuri - III_SG (01/02/2018): Alert - Adj Mandate Approved (\$0.00) - SKH1760K - Claim Handler: Zuhaidah Bte S...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKH1760K (MCT18010850)**
[SHA1161L]

TP

ANG BENG CHOO

Jan 28 2018 6:00PM

[COMFORT TRANSPORTATION PTE LTD]

Hup Motor Trading & Service

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images									3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	29/01/18 18:46	Chassis Number							 Load JPG	☒	
2	29/01/18 18:46	Odometer Reading							 Load JPG	☒	
3	29/01/18 18:46	General View							 Load JPG	☒	
4	29/01/18 18:46	General View							 Load JPG	☒	
5	29/01/18 18:46	General View							 Load JPG	☒	
6	29/01/18 18:46	General View							 Load JPG	☒	
7	29/01/18 18:46	General View							 Load JPG	☒	
8	29/01/18 18:46	General View							 Load JPG	☒	
9	29/01/18 18:46	General View							 Load JPG	☒	
10	29/01/18 18:46	General View							 Load JPG	☒	
11	29/01/18 18:46	General View							 Load JPG	☒	
12	29/01/18 18:46	General View							 Load JPG	☒	
13	29/01/18 18:46	General View							 Load JPG	☒	
14	29/01/18 18:46	General View							 Load JPG	☒	
15	29/01/18 18:46	General View							 Load JPG	☒	
16	29/01/18 18:46	General View							 Load JPG	☒	
17	29/01/18 18:46	General View							 Load JPG	☒	
18	29/01/18 18:46	General View							 Load JPG	☒	
19	29/01/18 18:46	General View							 Load JPG	☒	
20	29/01/18 18:46	General View							 Load JPG	☒	
21	29/01/18 18:46	General View							 Load JPG	☒	
22	29/01/18 18:46	General View							 Load JPG	☒	
23	29/01/18 18:46	General View							 Load JPG	☒	
24	29/01/18 18:46	General View							 Load JPG	☒	
25	29/01/18 18:46	General View							 Load JPG	☒	
26	29/01/18 18:46	General View							 Load JPG	☒	
27	29/01/18 18:46	General View							 Load JPG	☒	
28	29/01/18 18:46	General View							 Load JPG	☒	
29	29/01/18 18:46	General View							 Load JPG	☒	
30	29/01/18 18:46	General View							 Load JPG	☒	
31	29/01/18 18:46	General View							 Load JPG	☒	
32	29/01/18 18:46	General View							 Load JPG	☒	
33	29/01/18 18:46	General View							 Load JPG	☒	
34	29/01/18 18:46	General View							 Load JPG	☒	
35	29/01/18 18:46	General View							 Load JPG	☒	

36	29/01/18 18:46	General View	1	Load JPG	☒
37	29/01/18 18:46	General View	1	Load JPG	☒
38	29/01/18 18:46	General View	1	Load JPG	☒
39	29/01/18 18:46	General View	1	Load JPG	☒
40	29/01/18 18:46	General View	1	Load JPG	☒
41	29/01/18 18:46	General View	1	Load JPG	☒
42	29/01/18 18:46	General View	1	Load JPG	☒
43	29/01/18 18:46	General View	1	Load JPG	☒
44	29/01/18 18:46	General View	1	Load JPG	☒
45	29/01/18 18:46	General View	1	Load JPG	☒
46	29/01/18 18:46	General View	1	Load JPG	☒
47	29/01/18 18:46	General View	1	Load JPG	☒
48	29/01/18 18:46	General View	1	Load JPG	☒
49	29/01/18 18:46	General View	1	Load JPG	☒
50	29/01/18 18:46	General View	1	Load JPG	☒
51	29/01/18 18:46	General View	1	Load JPG	☒
52	12/02/18 09:16	Reinspection Photo	1	Load JPG	☒
53	12/02/18 09:16	Reinspection Photo	1	Load JPG	☒
54	12/02/18 09:16	Reinspection Photo	1	Load JPG	☒
55	12/02/18 09:16	Reinspection Photo	1	Load JPG	☒

Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/01/18 15:07	TP ESTIMATE + TP GIA REPORT + LTA SEARCH	1 Load PDF	
2	02/02/18 12:12	TP ESTIMATE- MARKED	1 Load PDF	
3	08/02/18 17:23	WORKSHOP INVOICE	1 Load PDF	
4	08/02/18 17:23	RENTAL RECEIPT	1 Load PDF	
5	08/02/18 17:23	LOD	1 Load PDF	
6	08/02/18 17:23	LTA SEARCH	1 Load PDF	
7	26/02/18 10:25	DISCHARGE VOUCHER	1 Load PDF	
8	26/02/18 10:25	AUTHORISATION TO ACT FORM	1 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	30/01/18 09:03	Singapore Accident Statement	1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18001703/UYS3Q2

Date: 26/02/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle No: SKH1760K

Insured Vehicle No: SHA1161L

Date of Loss: 28/01/2018

Nature of Claim: TP

Claim No: MCT18010850

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH1760K	Engine No:	27186030453159
Make & Model:	MERCEDES-BENZ E250, 1.8 (A)	Chassis No:	WDD2120472A602344
Reg. Date:	12/11/2012 (Man. Year: 2012)	Odometer:	104701 km
Colour:	Silver		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,573.17	7,342.20	6,230.97	45.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,280.00	2,570.00	2,710.00	51.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,853.17	9,912.20	8,940.97	47.42
Approved Total (Overridden) (S\$)		7,900.00		
Nett Amount (S\$)	18,853.17	7,900.00	10,953.17	58.10
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,747.45		

INSPECTION

Date of Assignment: 29/01/2018

Date Inspected: 29/01/2018 Inspected At:

Hup Motor Trading & Service (HQ)
Blk 9004 Tampines Street 93, #01-120
Singapore 528838

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** Jasmine Khine Phoo Wai

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2018)
Parts: 143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKH1760K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S DOOR	Badly Dented	2,070.00 FL	*2,070.00 FL
2	1		*FRONT O/S DOOR MOULDING	Necessary	93.00 FL	*93.00 FL
3	1		*FRONT O/S DOOR FRAME STICKER	Necessary	86.00 FL	*86.00 FL
4	1		*FRONT O/S DOOR WEATHERSTRIP	Necessary	280.00 FL	*280.00 FL
5	1		*FRONT O/S DOOR SIDE MIRROR CASING COVER	Not Necessary	287.30 FL	*- FL
6	1		*REAR O/S DOOR	Badly Dented	2,125.00 FL	*2,125.00 FL
7	1		*REAR O/S DOOR MOULDING	Distorted	93.00 FL	*93.00 FL
8	2		*REAR O/S DOOR TOP & LOW HINGE	Serviceable	293.00 FL	*- FL
9	1		*REAR O/S DOOR WEATHERSTRIP	Necessary	280.00 FL	*280.00 FL
10	1		*SET REAR O/S DOOR FRAME STICKER	Necessary	86.00 FL	*86.00 FL
11	1		*REAR O/S DOOR GLASS REGULATOR	Not Necessary	1,293.00 FL	*- FL
12	1		*REAR O/S DOOR GLASS CHANNEL	Not Necessary	166.00 FL	*- FL
13	1		*FRONT & REAR O/S DOOR INNER TRIM BOARD CLIPS (30 PCS)	Not Necessary	270.00 FL	*- FL
14	1		*REAR O/S FENDER	Repair	2,200.00 FL	*- FL
15	8		*REAR O/S FENDER INNER GARNISH CLIPS	Not Necessary	72.00 FL	*- FL
16	1		*SET REAR WINDSCREEN GLASS REPAIR KIT	Not Necessary	1,377.00 FL	*- FL
17	1		*FUEL TANK LID PANEL	Repair	271.00 FL	*- FL
18	1		*REAR BUMPER	Deep Cut / Warped	1,462.00 FL	*1,462.00 FL
19	1		*REAR BUMPER O/S SIDE RETAINER	Necessary	58.00 FL	*58.00 FL
20	8		*REAR BUMPER CLIPS	Necessary	72.00 FL	*72.00 FL
21	1		*O/S ROCKER PANEL SIDESKIRT GARNISH	Torn	687.00 FL	*687.00 FL
22	8		*O/S ROCKER PANEL SIDESKIRT GARNISH CLIPS	Necessary	72.00 FL	*72.00 FL
23	1		*FRONT & REAR O/S SPORT RIM	Rear Cut	1,388.00 FL	*694.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	15,081.30	8,158.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,508.13	815.80
Total Parts (\$\$)	13,573.17	7,342.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	50.00	30.00
2	TO CHECK & ADJUST WHEEL BALANCING & ALIGNMENT	New	180.00	80.00
3	TO REMOVE & REFIX REAR WINDSCREEN GLASS & NECESSARY PARTS	New	200.00	0.00
4	TO DIAGNOSE & RESET DOOR CENTRE LOCKING & AIR-BAG SENSOR CODE	New	150.00	50.00
5	TO REMOVE & REFIX FRONT & REAR O/S DOOR INNER TRIM BOARD COVER ,GLASS ,MOTOR ,REGULATOR ,MOULDING ,CHANNEL ,INNER LOCK ,HINGE,HANDLE ,CHECKER ,WEATHERSTRIP & NECESSARY PARTS	New	300.00	160.00
6	TO REMOVE & REFIX FUEL TANK ,HOSE ,PIPE & NECESSARY PARTS	New	150.00	60.00
7	TO REMOVE & REFIX CARPET ,FLOOR MAT ,GARNISH ,FLOOR BOARD COVER,TOOL SET & NECESSARY PARTS ,TO ENABLE REPAIR REAR O/S FENDER,O/S ROCKER PANEL & NECESSARY PARTS	New	150.00	60.00
8	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	150.00	80.00
9	LABOUR CHARE TO REMOVE ,REFIX & PUMP SEALANT FOR O/S ROCKER PANEL SIDE SKIRT	New	150.00	50.00
10	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK,STRAIGHTEN & KNOCKING OUT REAR O/S FENDER ,O/S ROCKER PANEL ,CENTRE DOOR PILLAR & NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	1,800.00	800.00
11	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	2,000.00	1,200.00
Gross Labour Cost (S\$)			5,280.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >