

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2882/01/18

Your Ref: _____

Date: 29th JAN 2018

Madam Ang Beng Choo
Blk 113, #07-35
Rivervale Walk,
Singapore 540113

Estimate cost of repair to MERCEDE BENZ E250 (A) Saloon - SKH 1760 K

1 pc front o/s door	Body	\$ 2,070.00	✓
1 pc front o/s door moulding	ner	93.00	✓
1 set front o/s door frame sticker	ner	86.00	✓
1 pc front o/s door weatherstrip	ner	280.00	✓
1 pc front o/s door side mirror casing cover	ner	287.30	✓
1 pc rear o/s door	Body	2,125.00	✓
1 pc rear o/s door moulding	D-S	93.00	✓
2 pcs rear o/s door top & low hinge (\$ 135.00 + \$ 158.00)	Su	293.00	✓
1 pc rear o/s door weatherstrip	ner	280.00	✓
1 set rear o/s door frame sticker	ner	86.00	✓
1 pc rear o/s door glass regulator	ner	1,293.00	✓
1 pc rear o/s door glass channel	ner	166.00	✓
30 pcs front & rear o/s door inner trim board clips	@ \$ 9.00	270.00	✓
1 pc rear o/s fender	ner	2,200.00	✓
8 pcs rear o/s fender inner garnish clips	@ \$ 9.00	72.00	✓
1 set rear windscreen glass repair kit	ner	1,377.00	✓
1 pc fuel tank lid panel	ner	271.00	✓
1 pc rear bumper	Deep cut/repair	1,462.00	✓
1 pc rear bumper o/s side retainer	ner	58.00	✓
8 pcs rear bumper clips	@ \$ 9.00	72.00	✓
1 pc o/s rocker panel sideskirt garnish	ner	687.00	✓
8 pcs o/s rocker panel sideskirt garnish clips	@ \$ 9.00	72.00	✓
2 pcs front & rear o/s sport rim	@ \$ 694.00	1,388.00	1 pc
		\$ 15,081.30	8158
	Less 10%		10%
			7342.20
To wiring check up for affected wiring system,		50.00	30
To check & adjust wheel balancing & alignment.		180.00	80
To remove & refix rear windscreen glass & necessary parts.	ner	200.00	✓
To diagnose & reset door centre locking & air-bag sensor code.		150.00	50
To remove & refix front & rear o/s door inner trim board cover, glass, motor, regulator, moulding, channel, inner lock, hinge, handle, checker, weatherstrip & necessary parts.		300.00	160
To remove & refix fuel tank, hose, pipe & necessary parts.		150.00	60
	Balance C/P.....	\$	

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2882/01/18

Your Ref: _____

Date: 29th Jan 2018

Madam Ang Beng Choo.,

Balance B/F..... \$

To remove & refix carpet, floor mat, garnish, floor board cover,
tool set & necessary parts, to enable repair rear o/s fender,
o/s rocker panel & necessary parts.

150.00 60

To respray Tuff-Kote on all affected accident parts.

150.00 80

Labour charge to remove, refix & pump sealant for o/s rocker
panel side skirt.

150.00 80

Labour charge to remove & cut out damaged parts, to jack, straighten
& knocking out rear o/s fender, o/s rocker panel, centre door pillar
& necessary parts, to weld, renew & align above parts.

1,800.00 800

To putty & respray Painting on all affected accident parts.

2,000.00 1200

18,853.17

Dollars : -

HUP MOTOR TRADING & SERVICE

.....

LKK Auto Consultants hence notify
the Reparer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: