

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2882/01/18

Your Ref:

Date: 29th JAN 2018

Madam Ang Beng Choo
Blk 113, #07-35
Rivervale Walk,
Singapore 540113

Estimate cost of repair to MERCEDE BENZ E250 (A) Saloon - SKH 1760 K

1 pc front o/s door		\$ 2,070.00
1 pc front o/s door moulding		93.00
1 set front o/s door frame sticker		86.00
1 pc front o/s door weatherstrip		280.00
1 pc front o/s door side mirror casing cover		287.30
1 pc rear o/s door		2,125.00
1 pc rear o/s door moulding		93.00
2 pcs rear o/s door top & low hinge (\$ 135.00 + \$ 158.00)		293.00
1 pc rear o/s door weatherstrip		280.00
1 set rear o/s door frame sticker		86.00
1 pc rear o/s door glass regulator		1,293.00
1 pc rear o/s door glass channel		166.00
30 pcs front & rear o/s door inner trim board clips @ \$ 9.00		270.00
1 pc rear o/s fender		2,200.00
8 pcs rear o/s fender inner garnish clips @ \$ 9.00		72.00
1 set rear windscreen glass repair kit		1,377.00
1 pc fuel tank lid panel		271.00
1 pc rear bumper		1,462.00
1 pc rear bumper o/s side retainer		58.00
8 pcs rear bumper clips @ \$ 9.00		72.00
1 pc o/s rocker panel sideskirt garnish		687.00
8 pcs o/s rocker panel sideskirt garnish clips @ \$ 9.00		72.00
2 pcs front & rear o/s sport rim @ \$ 694.00		1,388.00
		\$ 15,081.30
	Less 20%	\$ 3,016.26
		\$ 12,065.04

To wiring check up for affected wiring system, 50.00

To check & adjust wheel balancing & alignment. 180.00

To remove & refix rear windscreen glass & necessary parts. 200.00

To diagnose & reset door centre locking & air-bag sensor code. 150.00

To remove & refix front & rear o/s door inner trim board cover, glass, motor, regulator, moulding, channel, inner lock, hinge, handle, checker, weatherstrip & necessary parts. 300.00

To remove & refix fuel tank, hose, pipe & necessary parts. 150.00

Balance C/F..... \$ 13,095.04

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2882/01/18 Your Ref: _____ Date: 29th Jan 2018

Madam Ang Beng Choo.,

Balance B/F..... \$ 13,095.04

To remove & refix carpet, floor mat, garnish, floor board cover,
tool set & necessary parts, to enable repair rear o/s fender,
o/s rocker panel & necessary parts. 150.00

To respray Tuff-Kote on all affected accident parts. 150.00

Labour charge to remove, refix & pump sealant for o/s rocker
panel side skirt. 150.00

Labour charge to remove & cut out damaged parts, to jack, straighten
& knocking out rear o/s fender, o/s rocker panel, centre door pillar
& necessary parts, to weld, renew & align above parts. 1,800.00

To putty & respray Painting on all affected accident parts. 2,000.00

\$ 17,345.04
=====

Dollars : Seventeen Thousand Three Hundred Forty Five And Cents Four Only.

HUP MOTOR TRADING & SERVICE

.....
