

Surveyor

REF: CSI/SPF 18001707 / C v682

Special Instruction:

14,433.98

From (Person): Abdul Rahman of SPF Date/Time: 29/01/2018
Estimated Cost: Bill to:

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SJA 9495Y Insured: QX 823P
at Workshop m/s Borneo Motor Tel: QX 486D
of 17 Ubi Road 4

Policy No: Claim No: AEMD 105/009/2017/017
Sum Insured: Excess:
Make of Veh: D.O.A. 10.02.2017
(Client's Record)

Do Not Findline
H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT
Date/Time: Confirmed with Final Fig days (Red \$ / %; Original days)
Date/Time: Submit Final Fig 13,484.70, 10 days (Red \$ / %; Original days)

Date/Time	Action/Instruction
	SJA 9495Y - Q3 / FCL / 4406016 / Right
	QX 486D - CSI / SPF 18001707 / Q3
	DOA d: 21/03/14
	DOF: 03/06/2016
	*The repair cost is fair & reasonable. But the repair margin
	19/1/2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :
Salvage Value :
Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

300

1) Date/Time 20/1-2018 File Pass to 2) Date/Time File Return to
3) Date/Time File Pass to 4) Date/Time File Return to
5) Date/Time File Pass to 6) Date/Time File Return to