

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: AEMD/105/009/2017/017

Date: 27th February 2018

Our Ref: CS1/SPF18001707/Cvbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section
(Singapore Police Force)

1 Mount Pleasant Road
Blk 8 Old Police Academy
Singapore 298333
(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO.: SJA 9495Y INSURED VEHICLE NO: QX 823P ACCIDENT ON 10/02/2017

We thank you for your instruction on 29/01/2018.

We acknowledge receipt of the following documents:-

- Automobile Inspection Report of SJA 9495Y from M/s Borneo Motors (Singapore) Pte
   Ltd
- b) Singapore Accident Statement of Vehicles SJA 9495Y.
- c) Colour damaged vehicle photographs of SJA 9495Y.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: SJA 9495Y

Make & Mode

: Toyota Camry-2.4 (A)

Year of Registration

: 2007

Chassis Number

: MR053BK4007019376



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

- Our finding is that the repair cost of \$13,489.70 (before GST) quoted by M/s Borneo Motors (Singapore) Pte Ltd is fair & reasonable.
- We recommend that the repairs of the entire damage require about <u>10 (Ten)</u> working days to complete.