

ASS. REC. BY

REF: CS/MSG18001708/ Krd3/

Special Instruction

Surveyor:
Menmen

Kenneth

ASSIGNMENT (Office)

From (Person)

Irene Tan

of

MSIG

Date/Time

29/1/18 @ 3:00pm

Estimated Cost

Bill to:

OD / ☒ IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGU 5334K

Insured:

FBF 2572Y

at Workshop in/s

Kian Teong Auto Care

Tel:

9178 6498 / 6455 6268

of B1K 176, Sin Ming Drive # 01-08

Policy No:

28842144VMF

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/01/2018

CA / REV / REP. / REV 24 HRS w/p

30/1/2018

H.O.D. Endorsement:

Date/Time: 3:06pm @ 29/1/2018

Person Contacted:

Wendy

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

☒

Estimate

SGU 5334K - CS/MSG11016327/K

D.O.A. = 11/08/2011

FBF 2572Y - X

31/1/18

Sent preli thru Menmen

LL Pay @ 2000/- , 5 days (Red: \$3165.80, 61%.)

MSIG

30/1/18

SGU5334K

08/16

General One

00179 NS THREE CORP (SVA) (M) (M)

Consentance No

SGU5334K

Inspection No

Kian Teong

Blk 176, Sin Ming Drive #01-08

Insured

Policy No

Date of Ins

Sum Insured


Excess

Damage Report

Vehicle No

Policy Condition

Remark: The van has commenced its repair at the time of inspection.



Date of Vehicle Issue

O/C Accident Report

Consistent? (Yes or No)

O/C Police Report

Consistent? (Yes or No)

Est. Repair

4-5 days

Fee

Yes or No

Lift Date

1.B.17

Fee

Yes or No

O/C REV

REP

24 HRS

lwp

Date

Person Contacted

Vehicle IN/OUT

Date Time Action Instruction

31/1 File pass to Catherine

RECEIVED 11 JUN 2018

Site/Inspection

typist



Prelim. Report

Final Report

Days Of Repair

5

Resurvey No. of this

1

On-the-spot repair

Add Fee:

One day

Two days

Three days

Four days

Five days

Record Referral

Vehicle No

7P

82000

Type of Vehicle Van Long Wheel Base

Type of Trailer

Make

Honda Vezel

1496

Color

M. P. White

Insured (Std. No. N4

Ex. Rating

36621

Insured (Std. No. N4

Eng. No

O/C

RUI

1116186

Gear (Std. No. N4) Gear (Std. No. N4)

Steering (Std. No. N4) Jammed Locked Burnt

Brakes (Std. No. N4) Jammed Locked Burnt

Mod. No. (Std. No. N4) (Std. No. N4)

Tyre Size

215/60R16

R.

BS (Std. No. N4) EXNOVA (Std. No. N4) JDA (Std. No. N4) MID (Std. No. N4) OHTS (Std. No. N4) RIR (Std. No. N4)

TOYO YOKO (Std. No. N4)

Front

Rear

Rear

5

Rear

4

Lift

5

Lift

4

O/C

28/1/18

O/C

30/1/18

Survey Report

✓

Dealer/Damage Fee (Std. No. N4) Fee (Std. No. N4) Fee (Std. No. N4) Fee (Std. No. N4) Fee (Std. No. N4)

Near O/S

The U/C (Std. No. N4) Chassis/Frame (Std. No. N4) Body Structure affected (Std. No. N4)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2018		29 Jan 2018 15:00 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	DOMINO'S PIZZA SINGAPORE PTE LTD, Co. Reg. No.: 200900719D		
Main Claimant:	WU HAN YI, ID: S8133130H		
Vehicle Reg. No.:	SGU5334K	Date of Loss:	28/01/2018 12:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	28842144VMF (Comprehensive) Coverage: 01/11/2017 - 31/10/2018
Vehicle Reg. No. (Insured):	F8F2572Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Kian Teong Auto Centre (HQ) BLK 176 SIN MING DRIVE #01-08 SIN MING AUTOCARE, 575721 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/01/2018]		
Adj Asg. Remarks:	Please assign to Kenneth Kong		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS


[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



MSIG

MSIG Insurance (Singapore) Pte. Ltd. (SIA Reg. No. 209412212G)
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg



KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08, Sin Ming AutoCare
Singapore 575721
Tel: 64556268 Fax: 64555166

TO: MSIG INSURANCE

DATE: 29/01/2018

ATTN: MOTOR CLAIM DEPT

OUR REF:

TEL:

FAX: 62257402

RE: PRE-REPAIR SURVEY

Please find attached accident report for your reference and kindly arrange your surveyor to drop
by our workshop on at the above address for pre-inspection. Our insured vehicle is SCU5334K
and your insured vehicle number is FBF2572Y.

Kindly please assist and advice if your client has made an accident report and liability on the
case.

Your kind assistance on above matter would be appreciated

Thanks & Regards,

Wendy Siew – Mobile : 91786498



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18001708/Krd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 29-01-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBF 2572Y	Veh. Inspected	SGU 5334K	
Policy No.	28842144VMF	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAN)	Assign Date	29/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/01/2018	Inspection Date		
Survey held at	KIAN TEONG AUTO CENTRE BLK 176 SIN MING DRIVE #01-08 SIN MING CARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 31 Jan 2018

Preliminary Advice

Insured Vehicle No	: FBF2572Y	Accident Date	: 28/01/2018
TP Vehicle No	: SGU5334K	Assignment Date	: 29/01/2018
Make	: HONDA VEZEL	Est. Duration of Repair	: 5.00
Date of Inspection	: 30/01/2018		
Inspection At	: KIAN TEONG AUTO CENTRE (HQ) BLK 176 SIN MING DRIVE #01-08 SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,608.00 (Labour only)
Revised Amount	:S\$	940.00 (Labour only)
Check Items (Estimated)	:S\$	1,080.00
Total	:S\$	2,020.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

KIAN TEONG AUTO CENTRE

Blk.176 Sin Ming Drive #01-08

Sin Ming AutoCare Singapore 575721

Tel No. : 64556268 Fax No. : 64555166

E-Mail : info@ktauto.com.sg

Website : www.ktauto.com.sg

Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

Not Authorised
1. B7
Resony B7pain
4-5 days

MSIG INSURANCE (SINGAPORE) PTE LTD

4 SHENTON WAY,

#21-01 SGX CENTRE 2, SINGAPORE 068807

Attention : Motor Claim Department

Contact : 68277660 / 65942555 Fax No. : 62256371 / 62257402

Estimate : ES000425

Date : 30/01/2018

Vehicle Num. : SGU 5334 K

Make/Model : HONDA VEZEL-2016

Chassis/Eng# : RU11116186/L15B4036192

Accident Date : 30/01/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	REAR BUMPER <i>But</i>		
3.		REAR BUMPER REINFORCEMENT <i>7</i>		
4.		REAR BUMPER CLIPS <i>mu</i>		
5.	RH	REAR END PANEL <i>7</i>		
6.	1	REAR BUMPER COVER <i>side mu</i>		
7.	1	REAR BOOTH LID <i>But</i>		
8.	1	REAR WINDSCREEN MOULDING <i>mu</i>		
9.	N	REAR WINDSCREEN SEALANT <i>mu</i>		28.00
9.	BOX	REAR EXHUAUST MUFFLER <i>?</i>		

List Total S\$:

28.00

1.	1 SET	NETT ITEMS :		
		REVERSE SENSOR		

mu 220.00 *2000.00*

Nett Total S\$:

220.00

LABOUR :

LABOUR FEES:

PROVISION OF LABOUR TOOLS AND CONSUMABLES

TO KNOCK AND RE-ALIGN ALL DAMAGED PARTS

TO REMOVE AND CHANGE ALL DAMAGED PARTS

TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS

TO CHECK ALL ELECTRICAL WIRING

TO CHECK ALL LIGHTING UNIT

TO REMOVE AND REFIT REAR WINDSCREEN TO FACILATE REPAIR

1,080.00 *7*

980.00 *600*

120.00 *200*

180.00 *1200*

Labour Total S\$:

2,360.00

E. & O.E.

Total S\$: 2,608.00

for KIAN TEONG AUTO CENTRE

Please do not hesitate to contact us at the above number if there is any other further quire.

We thank you for your kind attention. Your prompt reply is greatly appreciated.

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08
Sin Ming AutoCare Singapore 575721
Tel No. : 64556268 Fax No. : 64555166
E-Mail : info@ktauto.com.sg
Website : www.ktauto.com.sg
Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

MSIG INSURANCE (SINGAPORE) PTE LTD
4 SHENTON WAY,
#21-01 SGX CENTRE 2, SINGAPORE 068807

Attention : Motor Claim Department

Contact : 68277660 / 65942555 Fax No. : 62256371 / 62257402

Estimate : ES000425

Date : 30/01/2018

Vehicle Num. : SGU 5334 K

Make/Model : HONDA VEZEL-2016

Chassis/Eng# : RU11116186/L15B4036192

Accident Date : 30/01/2018

Claim No. :

Reference :

Policy No. :

Not Authored

11 Sep 8 2000h

Repairing After Point

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|-------|-------------------------------------|--|--|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 1 | REAR BUMPER | | |
| 3. | 1 SET | REAR BUMPER REINFORCEMENT <i>NV</i> | | |
| 4. | | REAR BUMPER CLIPS | | |
| 5. | RH | REAR END PANEL | | |
| 6. | 1 | REAR BUMPER COVER <i>NV</i> | | |
| 7. | 1 | REAR BOOTH LID | | |
| 8. | BOX | REAR WINDSCREEN MOULDING <i>NV</i> | | |
| 9. | VEZEL | REAR EXHAUST MUFFLER <i>NV</i> | | |
| | | EMBLEM | | |

List Total S\$:

- | | | | | |
|----|-------|-------------------------|--|--|
| 1. | 2 | NETT ITEMS : | | |
| 2. | 1 SET | REAR WINDSCREEN SEALANT | | |
| | | REVERSE SENSOR | | |

Nett Total S\$:

LABOUR :
LABOUR FEES:
PROVISION OF LABOUR TOOLS AND CONSUMABLES
TO KNOCK AND RE-ALIGN ALL DAMAGED PARTS
TO REMOVE AND CHANGE ALL DAMAGED PARTS
TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS
TO CHECK ALL ELECTRICAL WIRING
TO CHECK ALL LIGHTING UNIT
TO REMOVE AND REFIT REAR WINDSCREEN TO FACILATE REPAIR
TO REMOVE AND REFIT EXHUSAT TO FACILATE REPAIR
APPLY FIRE PROOFING CLOTH TO FACILATE REPAIR

Labour Total S\$:

B1 663.70 ✓

NV 38.00 ✓

NB 465.70 X

B1 1,053.50 ✓

NV 38.90 ✓

2,259.80

28.00 *NV* 56.00 *405h*

1st 220.00 *200h*

276.00

1,080.00 *600*

980.00 *500*

120.00 *20*

NV 180.00 *120*

NV 150.00 X

NV 120.00 X

2,630.00

E. & O.E.

Total S\$: 5,165.80



for KIAN TEONG AUTO CENTRE

Please do not hesitate to contact us at the above number if there is any other further quire.
We thank you for your kind attention. Your prompt reply is greatly appreciated.

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08

Sin Ming AutoCare Singapore 575721

Tel No. : 64556268 Fax No. : 64555166

E-Mail : info@ktauto.com.sg

Website : www.ktauto.com.sg

Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

MSIG INSURANCE (SINGAPORE) PTE LTD

4 SHENTON WAY,

#21-01 SGX CENTRE 2, SINGAPORE 068807

Attention : Motor Claim Department

Contact : 68277660 / 65942555 Fax No. : 62256371 / 62257402

Estimate

Date 200*+
Vehicle Num. 120*+
Make/Model =
Chassis/Eng# 740*00*
Accident Date
Claim No. 0*0
Reference
Policy No.

S/N Quantity Particular

1. 1 LIST ITEMS :
2. 1 REAR BUMPER *Bt*
3. 1 REAR BUMPER REINFORCEMENT *?*
4. REAR BUMPER CLIPS *Man*
5. RH REAR END PANEL *?*
6. 1 REAR BUMPER COVER *side Man*
7. 1 REAR BOOTH LID *Bt*
8. 1 REAR WINDSCREEN MOULDING *Man*
9. N REAR WINDSCREEN SEALANT *Man*
BOX REAR EXHAUST MUFFLER *?*

List TotalS\$:

1. 1 SET NETT ITEMS :
REVERSE SENSOR

Nett Total S\$:

LABOUR :

LABOUR FEES:

PROVISION OF LABOUR TOOLS AND CONSUMABLES

TO KNOCK AND RE-ALIGN ALL DAMAGED PARTS

TO REMOVE AND CHANGE ALL DAMAGED PARTS

TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS

TO CHECK ALL ELECTRICAL WIRING

TO CHECK ALL LIGHTING UNIT

TO REMOVE AND REFIT REAR WINDSCREEN TO FACILATE REPAIR

Labour Total S\$:

200*+
=
200*00*
0*0

600*+
20*+
120*+
=
740*00*
0*0

200*+
740*+
=
940*00*

CHECK

0*0

1,080*+
=
1,080*00*

Ne 2000*
220.00
220.00

1,080.00 *?*

600
980.00
120.00 *200*

180.00 *1200*
2,360.00

E. & O.E.

Total S\$: 2,608.00

for KIAN TEONG AUTO CENTRE

Please do not hesitate to contact us at the above number if there is any other further quire.
We thank you for your kind attention. Your prompt reply is greatly appreciated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display (damaged parts) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to approval from Insurance Company



KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08, Sin Ming AutoCare

Singapore 575721

Tel: 64556268 Fax: 64555166

(Joanne)

TO: AIG INSURANCE

DATE: 30/05/2018

ATTN: MOTOR CLAIM DEPT

RE: LETTER OF DEMAND

Please find below breakdown claim of the vehicle no: SGU5334K ✓

Repair cost: \$2,140.00(INCL GST)

Car Rental: \$660.00

Search Fees: \$7.45

Total amount: \$2,807.45

Your kind assistance on above matter would be appreciated



Thanks & Regards,

Wendy Siew – Mobile: 91786498

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jan 2018		29 Jan 2018 15:00 Edit Adj Rpt	S\$2,000.00 Edit Estimates	S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	DOMINO'S PIZZA SINGAPORE PTE LTD, Co. Reg. No.: 200900719D								
Main Claimant:	WU HAN YI, ID: S8133130H								
Vehicle Reg. No.:	SGU5334K	Date of Loss:	28/01/2018 12:00 - :59 [17 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 547850	Policy/Cover Note No.:	28842144VMF (Comprehensive) Coverage: 01/11/2017 - 31/10/2018						
Vehicle Reg. No. (Insured):	FBF2572Y	Policy No. (Claimant):							
		Excess:							
Repairer:	Kian Teong Auto Centre (HQ) BLK 176 SIN MING DRIVE #01-08 SIN MING AUTOCARE, 575721 Sin Ming - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 28/02/2018]								
Adj Asg. Remarks:	Please assign to Kenneth Kong								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGU5334K (547850)
[FBF2572Y]
TP
WU HAN YI
Jan 28 2018 12:00PM
[DOMINO'S PIZZA SINGAPORE PTE LTD]
Kian Teong Auto Centre

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page ☐	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/18 13:59	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page ☐	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/06/18 15:05	General View	 Load JPG	☒
2	11/06/18 15:05	General View	 Load JPG	☒
3	11/06/18 15:05	General View	 Load JPG	☒
4	11/06/18 15:05	General View	 Load JPG	☒
5	11/06/18 15:05	General View	 Load JPG	☒
6	11/06/18 15:05	General View	 Load JPG	☒
7	11/06/18 15:05	General View	 Load JPG	☒
8	11/06/18 15:05	General View	 Load JPG	☒
9	11/06/18 15:05	General View	 Load JPG	☒
10	11/06/18 15:05	General View	 Load JPG	☒
11	11/06/18 15:05	General View	 Load JPG	☒
12	11/06/18 15:05	General View	 Load JPG	☒
13	11/06/18 15:05	Reinspection Photo	 Load JPG	☒
14	11/06/18 15:05	Reinspection Photo	 Load JPG	☒
Documentation			1 per page ☐	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/01/18 14:39	PRI	 Load PDF	☐
2	29/01/18 14:39	TP GIA REPORT	 Load PDF	☐
3	29/01/18 14:44	List of 10 surveyor to TP	 Load PDF	☐
4	29/01/18 15:00	letter from TP agree SJE	 Load PDF	☐

Documents Checklist

DOCUMENTS CHECKLIST			Reset Save Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001708/RD3Q2

Date: 12/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28842144VMF

Claimant Vehicle No : SGU5334K

Insured Vehicle No : FBF2572Y

Date of Loss: 28/01/2018

Nature of Claim: TP

Claim No: 547850

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGU5334K**

Make & Model: HONDA VEZEL, 1.5 X CVT (A)

Engine No: L15B4036192

Reg. Date: 03/08/2016 (Man. Year: 2016)

Chassis No: RU11116186

Colour: Metallic Pearl White

Odometer: 36621 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,535.80	1,675.28	860.52	33.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	1,240.00	1,390.00	52.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,165.80	2,915.28	2,250.52	43.57
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	5,165.80	2,000.00	3,165.80	61.28
+ GST 7.00/7.00% (S\$)	361.61	140.00	221.61	61.28
Nett Amount (S\$)	5,527.41	2,140.00	3,387.41	61.28

INSPECTION

Date of Assignment: 29/01/2018

Date Inspected: 30/01/2018 Inspected At:

Kian Teong Auto Centre (HQ)
BLK 176 SIN MING DRIVE #01-08 SIN
MING AUTOCARE
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jun 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGU5334K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	663.70 F	*663.70 FL
2	1		*REAR BUMPER REINFORCEMENT (NPA)	Not Necessary	0.00 F	*- FL
3	1		*SET REAR BUMPER CLIPS	Necessary	38.00 F	*38.00 FL
4	1		*REAR END PANEL	Repair	465.70 F	*- FL
5	1		*RH REAR BUMPER COVER (NPA)	Not Necessary	0.00 F	*- FL
6	1		*REAR BOOTH LID	Bent	1,053.50 F	*1,053.50 FL
7	1		*REAR WINDSCREEN MOULDING (NPA)	Not Necessary	0.00 F	*- FL
8	1		*BOX REAR EXHAUST MUFFLER (NPA)	Not Necessary	0.00 F	*- FL
9	1		*VEZEL EMBLEM	Necessary	38.90 F	*38.90 FL
10	2		*REAR WINDSCREEN SEALANT	Necessary	56.00 FS	*40.00 FS
11	1		*SET REVERSE SENSOR	Scratched	220.00 FS	*200.00 FS
					Sub Total (S\$)	2,535.80 2,034.10
					- List Item Discount on L Items 0.00/20.00% (S\$)	0.00 358.82
					Total Parts (S\$)	2,535.80 1,675.28

F=Franchise part. S=SpcNett. L=ListItemDisc

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PROVISION OF LABOUR TOOLS AND CONSUMABLES TO KNOCK AND RE-ALIGN ALL DAMAGED PARTS .TO REMOVE AND CHARGE ALL DAMAGED PARTS	New	1,080.00	600.00
2	TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS	New	980.00	500.00
3	TO CHECK ALL ELECTRICAL WIRING TO CHECK ALL LIGHTING UNIT	New	120.00	20.00
4	TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR	New	180.00	120.00
5	TO REMOVE AND REFIT EXHAUST TO FACILITATE REPAIR	New	150.00	0.00
6	APPLY FIRE PROOFING CLOTH TO FACILITATE REPAIR	New	120.00	0.00
Gross Labour Cost (S\$)			2,630.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >