



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MR LEE TENG HOI  BLK 203 PETIR RD #02-657 SINGAPORE 670203  Contact No Mobile: 91194034	Cust No/Name	/MR LEE TENG HOI
	Reg No/Reg Date	SLP8243L / 20/06/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AHH006305
	Engine No	3A92UGB5802
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	PO1 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	25/01/2018/ 08:49	QUE	261 / Edwin Caina	20242			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								
RENEW & RE-ALIGN ACCIDENT PORTION AREAS:								
RENEW FRT DOOR RH & FRT FENDER RH								
REPAIR FRT BUMPER & SIDE SILL PNL RH								
E PNT98000								
RESpray FRT BUMPER , FRT FENDER RH , FRT DOOR RH , WINGMIRROR RH & SIDE SILL PNL RH								
E PNT88000								
REMOVE & REFIT RHF DOOR COMPONENT								
M SUNDRY								
RENEW RHF SPORT RIM & TRANSFER TYRE								
A 54900099								
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
A WHEELALIGNMENTBP								
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								
Sundries								
M FENDER,FR RH								
M SHIELD,FR WHEELHOUSE,RH								
M GARNISH,FR FENDER								
M PANEL ASSY,FR DOOR,RH								
M HINGE,FR DOOR,LWR RH								
M HINGE,FR DOOR,UPR RH								
M TAPE,FR DOOR SASH,RH								
M WHEEL,DISC								
M HEADLAMP ASSY,RH								
dt 1.00					458.00	00.00	458.00	
SVC 1.00					97.00	00.00	97.00	
SVC 1.00					61.00	00.00	61.00	
dt 1.00					939.00	00.00	939.00	
dt 1.00					51.00	00.00	51.00	
dt 1.00					51.00	00.00	51.00	
dt 1.00					28.00	00.00	28.00	
dt 1.00					743.00	00.00	743.00	
dt 1.00					654.00	00.00	654.00	

Estimate

Not Author  
P/B Repair  
Before paint job  
HKK Auto  
3 w/ day S.  
21/4/2018.

Confirm &amp; accepted by

LKK Auto Consultant hence notify  
the Repairer of the following:

- To resurvey before/after spray painting 7% GST on
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Nett 8,042.00  
562.94

Total Payable 8,604.94

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.