

REPAIR ESTIMATE*

VEHICLE NO. : SHC 363S

MAKE :

MODEL : HYUNDAI SONATA

DATE ~~25/1/2018~~ 14:55

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid /			\$ 1,349.50
	Boot Lid Rubber /			\$ 110.90
	Boot Lid Lock Upper /			\$ 132.10
	Boot Lid Lock Lower /			\$ 30.30
	Boot Lid Sonata Plate /			\$ 43.60
	Boot Lid Hyundai Plate /			\$ 24.20
	Boot Lid 'H' Emblem /			\$ 26.10
	Boot Lid CRDI Plate /			\$ 22.70
	Boot Lid Lamp (RH) ?			\$ 230.20
	Rear Bumper /			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip /			\$ 22.00
	Rear Bumper Side Bracket /			\$ 49.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover ?			\$ 185.80
	Rear Bumper Protector (RH) /			\$ 38.00
	Tail Lamp (RH) /			\$ 344.00
	Tail Lamp Quarter Panel (RH) /			\$ 93.80
	Rear Panel /			\$ 391.80
	Rear Panel Garnish ?			\$ 95.80
	Exhaust Pipe Insulator ?			\$ 56.10
	Exhaust Silencer ?			\$ 723.00
	Exhaust Pipe Hanger ?			\$ 56.10
	Rear Fender (RH) /			\$ 1,935.90
	Rear Fender Inner Panel (RH) /			\$ 1,255.00
	Rear Fender Inner Lining (RH) ?			\$ 74.10
	Rear Tray Lugg Side (RH) ?			\$ 37.40
	Rear Fender Mudflap (RH) /			\$ 15.50
	Rear Windscreen Moulding /			\$ 60.00
	Rear Tyre Rim (RH) ?			\$ 284.70
	Rear Wheel Hup-Cap (RH) /			\$ 145.00
	Rear Wheelbearing ING & Hub ?			\$ 384.60
	Rear Trailing Arm (RH) ?			\$ 115.00
	Rear Assist (RH) ?			\$ 115.00
	Rear Shock Absorber (RH) ?			\$ 190.60
	Rear Shock Absorber Mounting (RH) ?			\$ 55.30
	Rear Crossmember ?			\$ 1,140.40
	Stabilizer Bar ?			\$ 196.00
	Stabilizer Link ?			\$ 65.30
	Rear Upper Arm (RH) ?			\$ 321.70
	Rear Lower Arm(RH) ?			\$ 195.80
	Rear Knuckle Arm (RH) ?			\$ 550.80
	SUB TOTAL			\$ 12,362.20
	LESS 20%			\$ 2,472.44
	DISCOUNTED TOTAL			\$ 9,889.76

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid City Cab Logo & Tel No. Sticker			\$ 30.00	Nett
	Rear Bumper Reverse Sensor			\$ 135.70	Nett
	Rear Bumper Advertisement Logo			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	Nett
	Rear Fender Comfort Sticker (RH)			\$ 30.00	Nett
	Rear Windscreen Sealant			\$ 46.00	Nett
	Rear Tyre (RH)			\$ 216.00	Nett
				\$ 707.70	
	Labour Charge			1000	
	Panel Beating			\$ 1,800.00	
	Spray Painting Charge			\$ 1,200.00	1050
	Wiring Charge			\$ 50.00	20
	Tuff Kote			\$ 100.00	50
	Rear Chassis Alignment Charge			\$ 400.00	100
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	50
	Remove/Refix Rear Windscreen Glass			\$ 120.00	100
	Remove/Refix Reverse Sensor			\$ 120.00	20
	Remove/Refix Undercarriage (RR)			\$ 400.00	150?
	Remove/Refix Exhaust Pipe			\$ 150.00	50
	Rear Wheel Alignment			\$ 120.00	60
	TOTAL LABOUR			\$ 4,610.00	
	ESTIMATE TOTAL			\$ 15,207.46	
16/11/14 26/1/18 TBA Repair 4/1 After Repair To check Book value					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged parts during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					