

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 8616X

DATE 26/1/2018 15:11

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover /			\$ 562.30
	Front Bumper Bracket Top (LH) /			\$ 22.40
	Front Bumper Retainer Mounting ?			\$ 9.20
	Headlamp (LH) X			\$ 1,388.00
	Front Fender (LH) /			\$ 619.00
	Front Fender Shield (LH) X			\$ 169.80
	Front Fender Retainer X			\$ 9.20
	Front Wheel Hub Cap, LH /			\$ 150.70
	SUB TOTAL			\$ 2,930.60
	LESS 20%			\$ 586.12
	DISCOUNTED TOTAL			\$ 2,344.48
	Labour Charge			
	Panel Beating			\$ 560.00 300
	Spray Painting Charge			\$ 400.00 360
	Wiring Charge			\$ 50.00 X
	Tuff Kote			\$ 50.00 20
	Frt Wheel Alignment			\$ 80.00 X
	TOTAL LABOUR			\$ 1,140.00
	ESTIMATE TOTAL			\$ 3,484.48

Kalvin LKK
 26/1/18 1620hrs
 2 days
 PIP
 Before Part photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.