

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

26 JAN 2018

Estimate No.	: b1 45668	Page No. : 1 of 2
Date Estimated	: 26/01/2018	
Prepared By	: Chua Kee Sin	

- ESTIMATE REPAIR FOR -	- ACCOUNT - 40000
Chong Thian Sian 32 Jalan Rajah #25-03 Singapore 329141	Cash Sales - Service Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD2058H	5F00739	07/06/2016	X1 sDrive18i	0

DESCRIPTION	VALUE
Replace rear bumper and remove attachment etc include knock on accident dent	850 1,700.00
Spray painting rear bumper	934 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	230 ? 271.00
Sundries.	? 150.00
Total Labour 1:	
	3,336.00

DESCRIPTION	QTY	PRIC	VALUE
REAR LH BUMPER MOUNT	1	141.65	? 141.65
RR BUMPER CARRIER	1	445.75	? 445.75
RR BUMPER LH CORNER MOUNTING	1	141.65	? 141.65
Abrasion gua	1	2.45	? 2.45
Abrasion gua	1	2.45	? 2.45
REAR BUMPER PANEL PRIMED	1	705.80	de 705.80
REAR BUMPER MIDDLE TRIM PANEL (PDC)	1	222.35	ent 222.35
REAR BUMPER TRIM BOTTOM (LINES)	1	211.75	? 211.75
EXPANDING RIVET	26	1.35	nu 35.10
REAR LH REFLECTOR	1	35.40	? 35.40
ULTRASONIC SENSOR BLACK	4	248.70	? 994.80
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	nu 20.20
Total Parts :			2,959.35

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 45668	Page No. : 2 of 2
Date Estimated	: 26/01/2018	
Prepared By	: Chua Kee Sin	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD2058H	5F00739	07/06/2016	X1 sDrive18i	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after repair
- To display damaged part
- Parts prices are put out to
- Third party survey is on a "Without" basis
- No illegal transactions is
- Supplier is subject to approval from insurance company

Acknowledged by repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
 Date & Time 7/2/18 2:1530 Excess S\$ _____
 Surveyor's Name Tan Jiah Sign Tan Jiah
 Surveyor's Tel 97495449 Authorised Yes / No _____
 Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____
 Surveyor's E-mail tanjiah@lkkauto.com
 No. of Working Days Recommend 3 days

Labour 1	:	3,336.00
Parts	:	2,959.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	440.67
Grand Total	:	6,736.02

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **