

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0114/2018/GW
Date : 27-Jan-18

Vehicle in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Caroline Teng Su Fong
Address : 15 Seraya Lane
Singapore 437282
Telephone : (HP)98468109
Type of Claim : Third Party Claims
Policy No. : 1700088351
Vehicle No : **SKF 618 G**
Model Code : Audi A3 Sedan 1.0 TFSI
Model / Year : Dec-17
Engine No : CHZ584019
Chassis No : WAUZZZ8VXJ1024820
Mileage : 1418
Date In : 27-Jan-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Jan-18
Place of Accident : UPPER BUKIT TIMAH RD TURNING LEFT TO CHOA CHU KANG

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKF 618 G

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00	
3	To remove rear fittings, dismantle and renew rear bumper and rear lid. Transfer old fittings and align to position. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,500.00	
4	To respray rear bumper, rear lid.	\$ 1,500.00	
5	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 3,752.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 618 G.

<u>S/N</u>	<u>Parts Description</u>	<u>Damage Parts & Prices</u>	
		<u>S/NETT</u>	<u>REMARKS</u>
1	REAR BUMPER	\$ 1,697.00	
2	REAR BUMPER FIXING PARTS	\$ 166.00	
3	REAR BUMPER GUIDE SECTION-LH	\$ 14.00	
4	REAR BUMPER SPOILER	\$ 206.00	
5	REAR WHEEL HOUSING LINER - LH	\$ 32.00	
6	REAR LIGHT REFLECTOR-LH	\$ 35.00	
7	REAR BUMPER SENSOR	2 \$ 421.00	
8	REAR BUMPER SEAL - O-RING	4 \$ 14.00	
9	REAR BUMPER SIDE REINFORCEMENT	\$ 501.00	
10	REAR BUMPER SIDE SUPPORT-LH	\$ 57.00	
11	REAR LID	\$ 2,310.00	
12	REAR LID ATTACHEMENT PARTS	\$ 253.00	
13	ADHESIVE PACKING	\$ 15.00	
14	AUDI EMBLEM	\$ 108.00	
15	INSCRIPTION "A3"	\$ 83.00	
16	INSCRIPTION "TFSI"	\$ 83.00	
17	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		: \$ 6,295.00	
TOTAL LABOUR CHARGES		: \$ 3,752.00	
GRANDTOTAL		: \$ 10,047.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant