

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 2822X

MAKE :

MODEL : HYUNDAI SONATA

CHINA

DATE 26/1/2018 10:01

DOA: 25-01-18

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid —			\$ 1,349.50	
	Boot Lid Rubber —			\$ 110.90	
	Boot Lid Lock Upper X			\$ 132.10	
	Boot Lid Lock Lower X			\$ 30.30	
	Boot Lid Sonata Plate —			\$ 43.60	
	Boot Lid Hyundai Plate —			\$ 24.20	
	Boot Lid 'H' Emblem —			\$ 26.10	
	Boot Lid CRDI Plate —			\$ 22.70	
	Boot Lid Lamp (LH/RH) X		\$ 230.20	\$ 460.40	
	Licence Lamp (LH/RH) <i>LH ✓ RH ✓</i>		\$ 32.50	\$ 65.00	
	Boot Lid Trimboard X			\$ 165.40	
	Boot Lid Trimboard Clips (10pcs) ✓			\$ 10.00	
	Rear Bumper —			\$ 578.40	
	Rear Bumper Reinforcement —			\$ 483.30	
	Rear Bumper Clip —			\$ 22.00	
	Rear Bumper Sponge —			\$ 137.40	
	Rear Bumper Under Cover —			\$ 185.80	
	Rear Bumper Protector (LH/RH) X <i>LH ✓ RH ✓</i>		\$ 38.00	\$ 76.00	
	Tail Lamp (LH/RH) <i>LH ✓ RH ✓</i>		\$ 344.00	\$ 688.00	
	Rear Panel —			\$ 391.80	
	Rear Panel Garnish —			\$ 95.80	
	Spare Tyre Holder ?			\$ 27.60	
	Spare Tyre Panel X <i>LH ✓ RH ✓</i>			\$ 863.00	
	Spare Tyre Panel Cushion ?			\$ 200.30	
	SUB TOTAL			\$ 6,189.60	
	LESS 20%			\$ 1,237.92	
	DISCOUNTED TOTAL			\$ 4,951.68	
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00	Nett
	Boot Lid Advertisement Logo			\$ 100.00	Nett
	Rear No. Plate			\$ 25.00	Nett
	Rear Bumper Reverse Sensor			\$ 135.70	Nett
	Rear Bumper Advertisement Logo			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH)			\$ 200.00	Nett
	Labour Charge			\$ 540.70	
	Panel Beating			\$ 1,200.00	800
	Spray Painting Charge			\$ 800.00	720
	Wiring Charge			\$ 50.00	20
	Tuff Kote			\$ 50.00	20
	Remove/Refix Reverse Sensor			\$ 120.00	20
	TOTAL LABOUR			\$ 2,220.00	
	ESTIMATE TOTAL			\$ 7,172.38	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental cash must be surveyed and is subject to final approval from Insurance Company

Ackn. & Date:

Date:

1/26/1/18

Date:

Date:

Date:

Date:

Date:

Date:

Date:

Date:

Date:

Date:

Date:

Date:

Date:

Date:

Date:

Date:

Date:

26/1/18 15:45h

4 Dns.

LX5

After Repair p Lk

Larry Ng

Page 1 of 1