

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 5988G -

AAD1801-274

Not Authorized
11 Sep 8 1650h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 5988G - JHOW

VF1ABL15AUC280994

RENAULT

LATITUDE

25.01.2018

AIG

PART			LIST	
1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84 X
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61 X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Bu</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Dir</i> 44.99 ✓
9	1	ROCKER PANEL OUTER RH	\$	<i>N</i> 987.49 X
10	1	FENDER PANEL REAR RH	\$	<i>N</i> 3,299.13 X
11	1	WHEELARCH REAR RH	\$	<i>Sn</i> 543.47
12	1	TAILLAMP RH	\$	<i>Sn</i> 552.55
13	1	TAILLAMP PANEL RH	\$	<i>N</i> 986.70
14	1	EXHAUST REAR	\$	<i>N</i> 7,489.05
15	1	EXHAUST CAP REAR	\$	<i>Sn</i> 230.49
16	1	DOOR PANEL REAR RH	\$	<i>N</i> 2,844.66
17	1	DOOR GUIDE REAR RH	\$	<i>Sn</i> 176.82
18	1	DOOR HINGE UPPER RH	\$	<i>N</i> 274.50
19	1	DOOR HINGE LOWER RH	\$	<i>N</i> 300.55
20	1	DOOR CHECK REAR RH	\$	<i>Sn</i> 203.06
21	1	DOOR FINISHER REAR RH	\$	<i>Sn</i> 423.10
22	1	DOOR WHEATHESTRIIP REAR RH	\$	<i>Sn</i> 410.66
23	1	DOOR SEAL REAR RH	\$	<i>Sn</i> 162.02
24	1	DOOR WAIST SEAL OUTER REAR RH	\$	<i>Sn</i> 334.69
25	1	DOOR MOULDING REAR RH	\$	<i>Sn</i> 176.82

TOTAL	\$	21,792.06
10%	\$	2,179.21
	\$	19,612.86

Specical Nett

1	1SET	PARKING AID	\$	<i>Sn</i> 700.00 X
2	1SET	REAR BUMPER CLIP	\$	<i>N</i> 66.00 ✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 5988G -**AAD1801-274**

3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00	—
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	} X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>na</i>	20.00	
6	1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	
7	1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	
8	1	EXHAUST MOUNTING REAR	\$	<i>sn</i>	17.82	
9	1	TAILLAMP CLIP RH	\$	<i>na</i>	5.00	} X
10	1SET	WHEELARCH CLIP RR RH	\$	<i>na</i>	66.00	
11	2	REAR WINDSCREEN SELANT	\$	<i>na</i>	80.00	
12	1	WINDSCREEN MOULDING	\$	<i>na</i>	100.00	
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	} X
14	1	CAP HUB RH RR	\$	<i>cm</i>	35.00	
15	1	RIM RH RR	\$	<i>sn</i>	385.00	X
16	1	TYRE RH RR	\$	<i>sn</i>	330.00	X
17	1	DOOR STICKER "Trans-cab"	\$	<i>na</i>	80.00	X
18	1	DOOR STICKER "Classic"	\$	<i>na</i>	30.00	X
19	1	DOOR STICKER "6555-3333"	\$	<i>na</i>	80.00	X

TOTAL	\$	2,225.82
TOTAL PARTS	\$	21,838.68

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>4401</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	<i>3001</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	X
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	X
Towing Fees	\$	<i>na</i> 120.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	<i>601</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-274

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 5988G -

To check steering geometry and computer wheel alignment \$ 220.00 *601*

To transfer of door fittings, attachment and perform water seepage test. \$ *~* 170.00 *x*

To transfer of tire, rim and on wheel balancing. \$ *~* 170.00 *x*

TOTAL	\$	7,710.00
Over All Total	\$	29,548.68

(PARTS BY PARTS)**Repair Days**~~10~~ Days*2 1/2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: