

Not Notwithstanding
 11 Sep 87
 Resurvey After Paint
 3 days



ESTIMATE TO REPAIR

VEHICLE NO. : GBC 4971 G
 MAKE : SSANGYONG
 MODEL : ACTYON SPORTS D/CAB 2.0 6AT 2WD
 YEAR : 2012
 CHASSIS NO : KPADA1ETSCP139738

SURVEYOR NAME :
 DATE OF SURVEY : 31 JAN 2018
 TIME OF SURVEY :

DATE : 29-Jan-18
 DATE OF ACCIDENT : 22-Jan-18
 THIRD PARTY REF : SLG 5492 B / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper			\$ 650.00	
1 pc	N/S Tail Lamp			\$ 380.00	
1 pc	N/S Rear Body Panel			\$ 1,100.00	
				\$ 2,130.00	
	Less 10%			\$ 213.00	
				\$ 1,917.00	
	To putty & spray painting.			\$ 500.00	
	To remove rear panel inner plate			\$ 350.00	
	Labour Charges.			\$ 800.00	
TG-RA/-					\$ 3,567.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel: 65-64520893 Fax: 65-64589127 Website : www.LTM.sg
 Co Reg No 199307277D GST Reg No M2-0019086-0

This document must not be reproduced in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd