

INSURANCE

INS. CASE OWNER:

Stacey

CC 4 ASM AXA1800 1732, T. 16/01/18

LKK:
IDAC

Surveyor:

Thompson

DOI:

ASSIGNMENT/

8/7/18

Date / Time:

21/01/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKK 6404R

Name of Insured:

H. Sze OMW

Insured Tel No.:

HP: 98716871

Excess Sec II :SS

D.O.A: 21/01/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L- YES / NO)

Claim No.:

58M007R4 / 27635

Policy No.:

444264671

Make / Model:

RM01

Place of Accident:

ML04 DE INSIDE LP W.5

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SKK 82250



INSRS:
WSP:
Tel:
Liability:
RMKS:

performance



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time		STAGE	DATE / PIC
7/01/18	SKK 82250 - P	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OE: 01/02/18 > 54	
		After call ltr to OE:	
3/1/18 @ 10:30pm	(ALLO) OI NO RESPONSE	Documentation Check List:	Handler Typist
01/02/18 10:23hrs	21/01/18 H. Sze OMW 98716871 & 444264671 de 11/01/18 - 31m	Notification ltr (if non-pickup)	
		After call ltr to OE:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

RECEIVED 16 OCT 2018

PRELIMINARY ADVICE	Date/Time: 9/3/18	Sent By: LSP	
FINALIZATION	Date/Time: 16/4/18	Confirm with: CAROLINE	Confirm by: MTM
Repair Cost:	P17 SS9,295.25	(6 days) Reduction:	46 %
FINAL SETTLEMENT	Date/Time: 09/05/18	Confirm with: CAROLINE	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	27
Repair Cost:	SS9,945.92	01 RMK ENDS TP.	
Loss of Rental (LOR):	SS -	(days)	
Loss of Use (LOU):	SS 350.00	(330 x 7 days)	
Loss of Income (LOI):	SS -	(5 x days)	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>		[Tick only one]	
GIA/LTA Search	SS 2.00		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/Independent)	
Legal Cost	SS -		
Total:	SS10,291.92	Global Sum SS:	
FINAL PAYMENT	Date/Time: 09/10/18	Confirm with: CAROLINE	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS 10,291.92	Name 1:	PERFORMANCE MOTOR LIMITED
Payee 2: (Strike if N.A.)	SS -	Name 2:	
Payee 3: (Strike if N.A.)	SS -	Name 3:	

COPY SENT
16/10/18

ASSIGNMENT

The UIC / Chassis frame / Body Structure affected due to collision

Lump Sum / L.B. (US)

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18001732/eb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 29-01-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKK 6404R	Veh. Inspected	SKX 8325D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	29/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/01/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401553W GST Reg. No M2-0020081-X

115, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438185
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

26 JAN 2018

Estimate No. : b1 45647
Date Estimated : 25/01/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Ng Yeng Seng (Huang Yongxin)
417 Serangoon Central
#06-466

Singapore 550417

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKX8325D	P836971	29/12/2015	216d G TOURER	0

DESCRIPTION

Replace rear tail end panel, rear boot lid, rear bumper and remove attachment etc include knock on accident dent

2550 4,250.00
2,295.00

Spray painting rear boot lid, rear bumper, tail end panel and floor panel

1730 3,197.00
2,159.10

To replace rear windscreen glass

487 574.00
438.30

To supply and install rear windscreen solar film.

531.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 271.00
261.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00
135.00

To carry out body cavity preservation.
(For cut panel).

451 531.00
90.00

Sundries. *NU*

? 150.00
80.00

Total Labour 1: 9,681.00

DESCRIPTION

BOOTLID
LH TRUNK LID HINGE
RH TRUNK LID HINGE
INTERIOR TAIL TRIM
RR BUMPER LH SIDE GUIDE
RR BUMPER RH SIDE GUIDE
REAR BUMPER CARRIER
SUPPORT
RR BUMPER LH INNER SIDE GUIDE
RR BUMPER RH INNER SIDE GUIDE
REAR BUMPER TRIM STRIP (CHROM)

QTY	PRIC
1	1,146.30
1	74.05
1	74.05
1	279.10
1	58.55
1	58.55
1	413.45
1	57.85
1	64.30
1	64.30
1	105.65

VALUE
b1 1,146.30
Ry 74.05
Rx 74.05
m 279.10
m 58.55
m 58.55
b1 413.45
d 57.85
m 64.30
m 64.30
m 105.65

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63448773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45647
Date Estimated : 25/01/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKX8325D	P836971	29/12/2015	216d G TOURER	0

DESCRIPTION

LEFT PROTECT
RIGHT PROTECT
REAR BUMPER PANEL PRIMED (LINES PDC
SET MOUNTS PDC SENSOR REAR
REAR BUMPER TOWING FLAP EYE PRIMED
LETTERING 216 D
GROMMET
BADGE (BMW)
STRIKER BOOT LID
Stop buffer
BOOT LID/TAILGATE PUSH BOTTON ICAM
LOCK TRUNK LID
ACTUATION UNIT
LH MOUNTING TAILGATE SUPPORT BOTTOM
RH MOUNTING TAILGATE SUPPORT BOTTOM
SPINDLE DRIVE
BOOTLID SEALING
BOOTLID SEALING
DECOUPING RING PDC TORQUE CONVERTER
ULTRASONIC SENSOR MINERALWEISS(WA96
BLIND RIVET AVIBVLB
SCREW (SF PLUS M5X15)
(DG/SL) BODY ADHESIVE K5B (195ML)
(DG) BODYWORK ADHESIVE K5A (50ML)
(DG) CLEANER R1 (100ML)
PUNCH RIVET N4

QTY PRIC

1	2.05
1	2.05
1	942.75
1	62.50
1	30.30
1	61.05
2	0.75
1	69.50
1	54.40
2	13.05
1	46.05
1	189.10
1	572.30
1	25.25
1	25.25
2	333.90
1	89.40
1	89.40
1	89.40
4	5.05
43	0.55
11	0.55
1	281.55
1	118.35
1	23.85
23	0.55

VALUE

2.05
2.05
942.75
62.50
30.30
61.05
1.50
69.50
54.40
26.10
46.05
189.10
572.30
25.25
25.25
667.80
89.40
89.40
20.20
1,475.20
23.65
6.05
281.55
118.35
23.85
12.65

Total Parts : 7,314.40

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
 Date/Time 21/1/18 @ 2pm Excess \$0
 Surveyor's Name Tanyan Sign _____
 Surveyor's Tel 97495719 Authorized Yes / No
 Authorized Date _____

RESURVEY PARTS PHOTO BY SURVEYOR (Yes/No) PMA Yes/No

Surveyor's E-mail tanyan@lkkauto.com
 No. of Working Days Recommend 6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Labour: 1	:	9,681.00
Parts	:	7,314.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,189.68
Grand Total	:	18,185.08

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Cin. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45647
Date Estimated : 25/01/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Ng Yeng Seng (Huang Yongxin)
11 West Coast Walk
#07-24 The Park Condo

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 127161

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SKX8325D	P836971	29/12/2015	216d G TOURER	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# W/SCREEN RUBBER BUFFER *	1.60	10.00	3.00	15.52
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	2.00	3.00	255.21
# (DG/SL) GLASS PRIMER 30ML (VP206) *	27.85	1.00	3.00	27.01

Total Labour :
Total Parts : 297.74
Total Labour & Parts : 297.74



FINAL REPORT

Estimate No. : b1 45647
Date Estimated : 25/01/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Ng Yeng Seng (Huang Yongxin)
11 West Coast Walk
#07-24 The Park Condo

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 127161

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKX8325D	P836971	29/12/2015	216d G TOURER	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, boot lid include making good the tail end panel and knocking out dents caused by the accident	2550.00	10.00	2,295.00	
* To spray paint boot lid and rear bumper and tail end panel	2399.00	10.00	2,159.10	
To remove and install rear windscreen glass include conducting water leak tests	487.00	10.00	438.30	
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00	10.00	207.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	10.00	135.00	
* To carry out body cavity preservation. (Per panel)	100.00	10.00	90.00	
Sundries.	80.00	0.00	80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,174.95	1.00	3.00	1,139.70
REAR BUMPER CARRIER	423.80	1.00	3.00	411.09
SUPPORT	59.25	1.00	3.00	57.47
RR BUMPER LH INNER SIDE GUIDE	65.90	1.00	3.00	63.92
RR BUMPER RH INNER SIDE GUIDE	65.90	1.00	3.00	63.92
REAR BUMPER TRIM STRIP (CHROM)	105.65	1.00	3.00	102.48
REAR BUMPER PANEL PRIMED (LINES PDC	966.25	1.00	3.00	937.26
GROMMET	0.75	2.00	3.00	1.45
BADGE (BMW)	69.49	1.00	3.00	67.41
# W/SCREEN RUBBER BUFFER *	1.60	10.00	3.00	15.52
DECOUPLING RING PDC TORQUE CONVERTER	5.05	2.00	3.00	9.80
ULTRASONIC SENSOR MINERALWEISS(WA96 *	368.80	1.00	3.00	357.74
ULTRASONIC SENSOR MINERALWEISS(WA96	368.80	1.00	3.00	357.74
(DG) CLEANER R1 (100ML)	23.85	1.00	3.00	23.13
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	2.00	3.00	255.21



FINAL REPORT

# (DG/SL) GLASS PRIMER 30ML (VP206) *	27.85	1.00	3.00	27.01
---------------------------------------	-------	------	------	-------

SUPPLEMENTARY ITEMS

Total Labour :	5,404.40
Total Parts :	3,890.85
Total Labour & Parts :	9,295.25
Deduction for Excess :	0.00
Total Repair Costs less Excess:	9,295.25
GST @7%:	650.67
Grand Total :	9,945.92

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Friday, 2 February 2018 10:56 AM
To: 'PBSP'
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: REQ FOR DIRECT SETTLEMENT- SKX8325D AND SKK6404R ON 23/01/2018 ***LKK
REF:CC4/ASM18001732/eb3

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Friday, 2 February 2018 10:46 AM
To: Shu Pei (LKKAUTO) <shupeil@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: Re: REQ FOR DIRECT SETTLEMENT- SKX8325D AND SKK6404R ON 23/01/2018 ***LKK
REF:CC4/ASM18001732/eb3

Dear Asher,

Please let us have your reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Wednesday, 31 January 2018 10:40 AM
To: PBSP
Cc: 甯珺 @ CS A Team
Subject: RE: REQ FOR DIRECT SETTLEMENT- SKX8325D AND SKK6404R ON 23/01/2018 ***LKK
REF:CC4/ASM18001732/eb3

Dear Caroline,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Dear Asher,

For your information and necessary action please.

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]
Sent: Wednesday, 31 January 2018 10:29 AM
To: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: Fw: REQ FOR DIRECT SETTLEMENT- SKX8325D AND SKK6404R ON 23/01/2018

Dear Motor Claims,

Please let us have your reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Friday, 26 January 2018 9:50 AM
To: motor.survey@axa.com.sg
Subject: REQ FOR DIRECT SETTLEMENT- SKX8325D AND SKK6404R ON 23/01/2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

SNG



MANDATE REQUEST FOR S8M007R4

Type

🔔 Question

Message

Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$9,945.92 (w/GST) Loss of Use: \$350.00 (7days x \$50) GIA Search: \$2.00 Total: \$10,297.92 Immediate Advice with Mandate for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (13/08/2018)

Reply



Re:MANDATE REQUEST FOR S8M007R4

Type

🔗 Question

Message

PLS PROCEED

Reply

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S7818772G**
Name: **GOH SU YIN, MELISSA**

Birth Date: **30 Jun 1978**
Issue Date: **10 Jun 2009**



0017502048

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7818772G**



Name: **GOH SU YIN, MELISSA**

吴素贤
Race: **CHINESE**

Date of birth: **30-06-1978** Sex: **F**

Country of birth: **SINGAPORE**

S7818772G

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Vehicle Description	PASS DATE
Class 3	Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg	08 Jan 1999

SP 428A



Licence No: S7818772G

4415702



NRIC No: **S7818772G**



Date of issue: **10-06-2009**

11 WEST COAST WALK #07-24
SINGAPORE 127181

NRIC No: **S7818772G** Date: **08/08/2017**



Aviva Ltd., 4 Shenton Way, #01-01 SGA Centre 2, Singapore 068807. Tel: (65) 6827 9999 www.aviva.com.sg

CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION
(REPUBLIC OF SINGAPORE) OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

CERTIFICATE NUMBER. 10708852

1) VEHICLE REGISTRATION NO.

SKX8325D

2) NAME OF INSURED

FAMILY NAME
GIVEN NAME

NG
YENG SENG

3) EFFECTIVE DATE OF COMMENCEMENT OF INSURANCE FOR THE PURPOSE OF THE ACT

29-Dec-2017 00:00hours

4) DATE OF EXPIRY OF INSURANCE

28-Dec-2018 23:59hours

5) PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE

Any driver aged 30 or over

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by any reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been canceled at the time of accident or loss.

Please refer to the policy document for full terms and conditions.

6) LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or reward, tuition or driving tests, racing, pace-making, reliability trials, speed-testing or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

NAMED DRIVER

7) FINANCE COMPANY

DBS BANK LTD

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia), or any amendment, act or acts passed in substitution thereof.

Issued in Singapore: 06-Dec-2017 at 10:22hours

Aviva Ltd.

IMPORTANT NOTE:

- If you want to cancel your policy at any time, you will need to return the certificate to us.
- You MUST report all accidents to Us within 24 hours of the occurrence regardless of whether You intend to claim on Your own policy or not, or whether Your car is damaged or not. Should You fail to do so, Your No Claims Discount could be affected and Your claim may be prejudiced.


Nishit Majmudar
Chief Executive Officer

In case of vehicle breakdown, accident or windscreen damage, please call 6333 2222 (24 hours) immediately.

ORIGINAL

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7718734J



Name

NG YENG SENG
(HUANG YONGXIN)

黄永新

Race

CHINESE

Date of birth

12-07-1977

Sex

M

Country of birth

SINGAPORE



4087633



NRIC No. S7718734J



Date of issue

20-08-2007

11 WEST COAST WALK #07-24
SINGAPORE 127161

NRIC No: S7718734J

Date: 11/02/2017



(A)

AXA Insurance Pte Ltd
8 Shenton Way
#27-01
Singapore 068811
Attention: Motor Claims

"Without Prejudice"

Your Ref:

Our Ref:

Date:

Subject:

30 July 2018

ACCIDENT INVOLVING VEHICLES SKX8325D & SKK6404R ON 23.01.2018

Dear Sirs,

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	:	S\$	9945.92
Loss of use	:	S\$	350.00 (S\$ 50.00 x 7 days)
GIA search fee	:	S\$	2.00
Total	:	S\$	10297.92

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & GIA search slip
3. Copy of Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@simedarby.com.sg.

Yours sincerely

Teng Wai Khan
Customer Service Manager, Body & Paint

Performance Motors
Limited
1920-Cali-BMW
(1800-2255-269)
www.pml.com.sg

303 Alexandra Road
Sims Darby
Performance Centre
Singapore 152941
Tel Sales 6319 0100
Tel AfterSales
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sims Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel AfterSales
6319 0527
Fax 6479 6824

280
Kemping Arang Rd
East Coast Centre
Singapore 436180
Tel AfterSales
6319 0888
Fax 6344 1332

Registered office:
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Cs. Reg. No.
197401559W



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

05 FEBRUARY 2018

HO SZE ONN
BLK 21 SERANGOON AVE 3
#03-08
SINGAPORE 556124

Dear Sir/Madam,

OUR REF : CC4/ASM18001732/eb3
YOUR REF : SKK 6404R
ACCIDENT INVOLVING SKK 6404R AND SKX 8325D ALONG NICOLL DR OUTSIDE
CARPARK NO 5 ON 23.01.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from PERFORMANCE MOTORS LTD, acting on behalf of the owner of SKX 8325D against your motor insurance policy.

Based on the accident report, accident scenario, it was reported that your vehicle had rear-ended the Third Party vehicle SKX 8325D. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Siti Jaafar
Case Handler
DID: 6256 3561
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

Performance Motors Limited

A member of the Sime Darby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SKX 832SD & SKX 6404R ON 23.1.18.

I, Ng Yeng Seng owner of Vehicle Registration No. SKX 832SD hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:



Name: Ng Yeng Seng (Date)

NRIC No.: S77187347

In the presence of:

Name: **PERFORMANCE MOTORS LIMITED** (Date)

NRIC No.:
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941
TEL: 63190100 (Sales)
63190111 (Aftersales)



redefining / insurance

CLAIM REF : S8M007R4
INSURED : HO SZE ONN

DISCHARGE VOUCHER

We/I [NG YENG SENG, NRIC NO. 57718734J] hereby agree to accept the sum of dollars [TEN THOUSAND TWO HUNDRED NINETY SEVEN AND CENTS NINETY TWO ONLY.] [S\$10,297.92] paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. [SKK 6404R] as a result of an accident along [NICOLE DRIVE AT CHANGI] on [23/01/2018] of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. [SKX 8325D].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. [SKK 6404R] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [SKK 6404R].

Dated this 08 day of OCT 2018

Claimant's Signature : 

NRIC no./ Company Stamp : S7718734J

Occupation/ Business : SALES

Address : 11 WEST COAST WALK #07-24

Telephone No. : 9686 7836

Witness's Name : PERFORMANCE MOTORS LIMITED

Witness's Signature : 

Witness's NRIC No. : 303 Alexandra Road
Sime Darby Performance Centre
Singapore 150044
TEL: 63190100 (Sales)
63190111 (After-sales)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax 64747770280, Kampung Arang Road
East Coast Centre
Singapore 438188
Tel. 63190888 (AfterSales)
Fax. 63449773115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1249744

Date IN : 08/03/2018

Cust. Svc. Advisor: Chua Kee Sin

Page No. : 1 of 2

Invoice Number : 1966047 / WSB

Invoice Date : 17/05/2018

Payment Terms : 30 Days From Invoice

Invoice By : Toh Jing Xuan

- CUSTOMER INFORMATION -

Mr Ng Yeng Seng (Huang Yongxin)
11 West Coast Walk
#07-24 The Park Condo

Singapore 127161

- INVOICE TO - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811REGN. NO.
SKX8325DCHASSIS NO.
P836971REGN. DATE
29/12/2015MODEL
216D G TOURERMILEAGE
52557

- - - - LABOUR 1 - - - -

To replace rear bumper and attachments, bootlid including
make good the tail end panel and knock out dented area
caused by the accident.

To respray bootlid, rear bumper and tail end panel.

To remove and install rear windscreen glass including
conduct water leak tests.To remove and install boot compartment carpet and garnish
to facilitate repairs.To check electrical wiring systems and lightings at the
rear section for proper function.

To carry out body cavity preservation.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 23.01.2018. 3RD PARTY CAR : SKK6404R.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO ON
08.03.2018 AT 2PM. AUTHORISED REPAIR BY MS ASHER SNG
FROM LKK AUTO ON 02.02.2018 VIA EMAIL.PROPOSE LOSS OF USE = \$50x7. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

GIA SEARCH FEE = \$2.00.

Retail

Price

DISC%

NETT

2,550.00

10.00

2,295.00

2,399.00

10.00

2,159.10

487.00

10.00

438.30

230.00

10.00

207.00

150.00

10.00

135.00

100.00

10.00

90.00

80.00

0.00

80.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

Total Labour 1:

5,404.40

- - - - PARTS - - - -

BOOTLID

REAR BUMPER PANEL PRIMED (LINES PDC

REAR BUMPER TRIM STRIP (CHROM)

GROMMET

BADGE (BMW)

DECOUPING RING PDC TORQUE CONVERTER

ULTRASONIC SENSOR MINERALWEISS(WA96

REAR BUMPER CARRIER

SUPPORT

Qty

Retail

Price

DISC%

NETT

1

1,174.95

3.00

1,139.70

1

966.25

3.00

937.26

1

105.65

3.00

102.48

2

0.75

3.00

1.45

1

69.50

3.00

67.41

2

5.05

3.00

9.80

1

368.80

3.00

357.74

1

423.80

3.00

411.09

1

59.25

3.00

57.47

101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770200, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax: 63449773119, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)**SERVICE TAX INVOICE**Repair Order No. : **B1 1249744**Date IN : **08/03/2018**Cust. Svc. Advisor: **Chua Kee Sin**Page No. : **2 of 2**Invoice Number : **1966047 / WSB**Invoice Date : **17/05/2018**Payment Terms : **30 Days From Invoice**Invoice By : **Toh Jing Xuan**

RR BUMPER LH INNER SIDE GUIDE	1	65.90	3.00	63.92
RR BUMPER RH INNER SIDE GUIDE	1	65.90	3.00	63.92
ULTRASONIC SENSOR MINERALWEISS(WA96	1	368.80	3.00	357.74
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	3.00	255.21
(DG) CLEANER R1 (100ML)	1	23.85	3.00	23.13
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	3.00	27.01
W/SCREEN RUBBER BUFFER	10	1.60	3.00	15.52

Total Parts : **3,890.85**

Labour Charges : **5,324.40**
 Parts Charges : **3,890.85**
 Lubricant/Misc : **80.00**

Total Labour & Parts Charges : **S\$ 9,295.25**
 Less Insurance Excess : **S\$ 0.00**
 Invoice Total Amount Exclude GST : **S\$ 9,295.25**
 GST @ 7% : **S\$ 650.67**
 Invoice Total Amount Include GST : **S\$ 9,945.92**

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 9,945.92**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-013946

Date of Request: 25/01/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 25/01/2018

Enquiry By Vivi

TP Vehicle No. SKK6404R

Accident Date 23/01/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKK6404R	AXA Insurance Pte Ltd	14/08/2017-13/08/2018	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-013946

Date of Request: 25/01/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 25/01/2018

Enquiry By Vivi

TP Vehicle No. SKK6404R

Accident Date 23/01/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKK 6404R (Insd veh)	Model:	B.M.W. 216D
	SKX 8325D (TP veh)		
Date of Accident:	23/01/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	18,503.66
Final Repair Cost	:	\$	9,945.92
Loss of Use	:	\$	350.00
Rental (if any)	:	\$	
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	10,297.92

Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____100____(%)	Assessed Liability (*): _____(%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown		
1)	PERFORMANCE MOTORS LIMITED	\$ 10,297.92

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

14/11/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18001732/T1eb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 14-11-2018



ATTN: STACEY NG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKK 6404R	Veh. Inspected	SKX 8325D
Policy No.	GA252646/1	Coverage (\$)	0.00
Claim No.	S8M007R4	Excess (\$)	0.00
Assign From		Assign Date	29/01/2018

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 216D	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WBA2E32000P836971	Colour	WHITE
Odometer	52557	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	GOODYEAR	6 mm
L/H Front Tyre	225/50 R17	GOODYEAR	6 mm
R/H Rear Tyre	225/50 R17	GOODYEAR	6 mm
L/H Rear Tyre	225/50 R17	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	23/01/2018	Inspection Date	08/03/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 8325D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	150.00	80.00
1	BOOTLID (SN) (CONSISTENT)	BENT	1,146.30	1,139.70
1	LH TRUNK LID HINGE (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	74.05	-
1	RH TRUNK LID HINGE (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	74.05	-
1	INTERIOR TAIL TRIM (SN) (CONSISTENT)	NOT NECESSARY	279.10	-
1	RR BUMPER LH SIDE GUIDE (SN) (CONSISTENT)	NOT NECESSARY	58.55	-
1	RR BUMPER RH SIDE GUIDE (SN) (CONSISTENT)	NOT NECESSARY	58.55	-
1	REAR BUMPER CARRIER (SN) (CONSISTENT)	BENT	413.45	411.09
1	SUPPORT (SN) (CONSISTENT)	DEFORMED	57.85	57.47
1	RR BUMPER LH INNER SIDE GUIDE (SN) (CONSISTENT)	NECESSARY	64.30	63.92
1	RR BUMPER RH INNER SIDE GUIDE (SN) (CONSISTENT)	NECESSARY	64.30	63.92
1	REAR BUMPER TRIM STRIP (CHROM) (SN) (CONSISTENT)	MISSING	105.65	102.48
1	LEFT PROTECT (SN) (CONSISTENT)	NOT NECESSARY	2.05	-
1	RIGHT PROTEC (SN) (CONSISTENT)	NOT NECESSARY	2.05	-
1	REAR BUMPER PANEL PRIMED (LINES PDC) (SN) (CONSISTENT)	DEFORMED	942.75	937.26
1	SET MOUNT PDC SENSOR REAR (SN) (CONSISTENT)	NOT NECESSARY	62.50	-
1	REAR BUMPER TOWING FLAP EYE PRIMED (SN) (CONSISTENT)	NOT NECESSARY	30.30	-
1	LETTERING 216 D (SN) (CONSISTENT)	NOT NECESSARY	61.05	-
2	GROMMET (SN) (CONSISTENT)	NECESSARY	1.50	1.45
1	BADGE (BMW) (SN) (CONSISTENT)	NECESSARY	69.50	67.41
1	STRIKER BOOT LID (SN) (CONSISTENT)	NOT NECESSARY	54.40	-
2	STOP BUFFER (SN) (CONSISTENT)	NOT NECESSARY	26.10	-
1	BOOT LID /TAILGATE PUSH BOTTON ICAM (SN) (CONSISTENT)	NOT NECESSARY	46.05	-
1	LOCK TRUNK LID (SN) (CONSISTENT)	NOT NECESSARY	189.10	-
1	ACTUATION UNIT (SN) (CONSISTENT)	NOT NECESSARY	572.30	-
1	LH MOUNTING TAILGATE SUPPORT BOTTOM (SN) (CONSISTENT)	NOT NECESSARY	25.25	-

Report Ref No. CC4/ASM18001732/T1eb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RH MOUNTING TAILGATE SUPPORT BOTTOM (SN) (CONSISTENT)	NOT NECESSARY	25.25	-
2	SPINDLE DRIVE (SN) (CONSISTENT)	NOT NECESSARY	667.80	-
1	BOOTLID SEALING (SN) (CONSISTENT)	NOT NECESSARY	89.40	-
1	BOOTLID SEALING (SN) (CONSISTENT)	NOT NECESSARY	89.40	-
4	DECOUPING RING PDC TORQUE CONVERTER (SN) (CONSISTENT)	NECESSARY (2 PCS ONLY)	20.20	9.80
4	ULTRASONIC SENSOR MINERALWEISS (WA96) (SN) (CONSISTENT)	NOT WORKING (2 PCS ONLY)	1,475.20	715.48
43	BLIND RIVET AVIBVLB (SN) (CONSISTENT)	NOT NECESSARY	23.65	-
11	SCREW (SF PLUS M5X15) (SN) (CONSISTENT)	NOT NECESSARY	6.05	-
1	(DG/SL) BODY ADHESIVE K5B (195ML) (SN) (CONSISTENT)	NOT NECESSARY	281.55	-
1	(DG) BODYWORK ADHESIVE K5A (50ML) (SN) (CONSISTENT)	NOT NECESSARY	118.35	-
1	(DG)CLEANER R1(100ML) (SN) (CONSISTENT)	NECESSARY	23.85	23.13
23	PUNCH RIVET N4 (SN) (CONSISTENT)	NOT NECESSARY	12.65	-
10	W/SCREEN RUBBER BUFFER (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	15.52	15.52
2	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	255.21	255.21
1	(DG/SL) GLASS PRIMER 30ML (VP206) (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	27.01	27.01
			7,762.14	3,970.85
LABOUR				
REPLACE REAR TAIL END PANEL , REAR BOOT LID , REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT INCLUSIVE OF THE REPAIR OF RH TRUNK LID HINGE.			4,250.00	2,295.00
SPRAY PAINTING REAR BOOT LID , REAR BUMPER , TAIL END PANEL AND FLOOR PANEL .			3,197.00	2,159.10
TO REPLACE REAR WINDSCREEN GLASS .			574.00	438.30
TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM .		NOT NECESSARY	531.00	-
TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.			271.00	207.00

Report Ref No. CC4/ASM18001732/T1eb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION .		177.00	135.00
	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL).		531.00	90.00
			9,531.00	5,324.40
GRAND TOTAL			17,293.14	9,295.25
RECOMMENDED COST OF REPAIRS				9,295.25

Report Ref No. CC4/ASM18001732/T1eb3q2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.

Service Request Details

Claim

SIAM00784

Reference

CCA/ASM18001732/711eb3d2

Loss Date

23 January 2018

Request Date

26 January 2018

Due Date

Vendor Name

LKX AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

9K0832SD

Make

TPVO BMW

Model

216D GRAN TOURER LED NAV 7 SEATER

Service Address

Primary Contact/Insured

HO SZE ONN

21 SERANGOON AVENUE 3, 556134, Singapore

98316821

SZE ONN.HO@LIVE.COM

Claim Handler

NG Stacy

6568804351

stacey.ng@axa.com.sg

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Additional Instructions

Document Type

Document SubType

Upload Documents

NAME

TYPE

SUB-TYPE

AUTHOR

DATE UPLOADED

Accident Statement

Reports & Statement

Merklin















LKXInvoice1 (5).pdf

Invoice

Surveyor/ Assessor expense

LKX AUTO CONSULTANTS PTE LTD (TP)

14 November 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 payment_breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 November 2018
 LOO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 November 2018
 LKKInspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 November 2018
 LKKAdjustment1a CL.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 November 2018
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	14 November 2018
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	PGA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	14 November 2018
 WORKSHOP INVOICE.pdf	Invoice	Repairs	LKK AUTO CONSULTANTS PTE LTD (TP)	14 November 2018
 LETTER TO OL.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	14 November 2018
 GIA SEARCH.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	13 August 2018
 Immediate Advice with Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	13 August 2018
 LKK Survey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2018
 LKK Resurvey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2018
 TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	9 March 2018
 Preliminary Advice.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	9 March 2018

