

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)clearance
7/13/2018
Sunny & Sep?
8/3/2018
4/226/2/2018
Sunny & Repu
Moring


GST REG. NO : M2 - 0020081 - X

E S T I M A T E

26 JAN 2018

Estimate No.	: b1 45647	Page No. : 1 of 2
Date Estimated	: 25/01/2018	
Prepared By	: Chua Kee Sin	

- ESTIMATE REPAIR FOR - Ng Yeng Seng (Huang Yongxin) 417 Serangoon Central #06-466 Singapore 550417	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKX8325D	P836971	29/12/2015	216d G TOURER	0

DESCRIPTION	VALUE
Replace rear tail end panel, rear boot lid, rear bumper and remove attachment etc include knock on accident dent	2550 4,250.00
Spray painting rear boot lid, rear bumper, tail end panel and floor panel	1730 3,197.00
To replace rear windscreen glass	487 574.00
To supply and install rear windscreen solar film.	? 531.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	230 271.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To carry out body cavity preservation. (For cut panel).	451? 531.00
Sundries.	? 150.00
Total Labour 1:	9,681.00

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID	1	1,146.30	bt 1,146.30
LH TRUNK LID HINGE	1	74.05	RY 74.05
RH TRUNK LID HINGE	1	74.05	Rx 74.05
INTERIOR TAIL TRIM	1	279.10	x 279.10
RR BUMPER LH SIDE GUIDE	1	58.55	? 58.55
RR BUMPER RH SIDE GUIDE	1	58.55	? 58.55
REAR BUMPER CARRIER	1	413.45	? 413.45
SUPPORT	1	57.85	? 57.85
RR BUMPER LH INNER SIDE GUIDE	1	64.30	? 64.30
RR BUMPER RH INNER SIDE GUIDE	1	64.30	? 64.30
REAR BUMPER TRIM STRIP (CHROM)	1	105.65	misv 105.65

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : **b1 45647**
Date Estimated : **25/01/2018**
Prepared By : **Chua Kee Sin**

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKX8325D	P836971	29/12/2015	216d G TOURER	0

DESCRIPTION	QTY	PRIC	VALUE
LEFT PROTECT	1	2.05	? 2.05
RIGHT PROTEC	1	2.05	? 2.05
REAR BUMPER PANEL PRIMED (LINES PDC	1	942.75	del? 942.75
SET MOUNTS PDC SENSOR REAR	1	62.50	? 62.50
REAR BUMPER TOWING FLAP EYE PRIMED	1	30.30	de? 30.30
LETTERING 216 D	1	61.05	neu? 61.05
GROMMET	2	0.75	neu 1.50
BADGE (BMW)	1	69.50	neu 69.50
STRIKER BOOT LID	1	54.40	? 54.40
Stop buffer	2	13.05	? 26.10
BOOT LID/TAILGATE PUSH BOTTON ICAM	1	46.05	X 46.05
LOCK TRUNK LID	1	189.10	? 189.10
ACTUATION UNIT	1	572.30	? 572.30
LH MOUNTING TAILGATE SUPPORT BOTTOM	1	25.25	? 25.25
RH MOUNTING TAILGATE SUPPORT BOTTOM	1	25.25	? 25.25
SPINDLE DRIVE	2	333.90	? 667.80
BOOTLID SEALING	1	89.40	? 89.40
BOOTLID SEALING	1	89.40	? 89.40
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	neu 20.20
ULTRASONIC SENSOR MINERALWEISS(WA96	2 / 4	368.80	1 neu ✓ 1,475.20
BLIND RIVET AVIBVLB	43	0.55	neu 23.65
SCREW (SF PLUS M5X15)	11	0.55	neu 6.05
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	281.55
(DG) BODYWORK ADHESIVE K5A (50ML)	1	118.35	neu 118.35
(DG) CLEANER R1 (100ML)	1	23.85	neu 23.85
PUNCH RIVET N4	23	0.55	12.65

Total Parts : 7,314.40

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 213/18 @ 2pm Claim No. _____

Date & Time 21/1/18 @ 2pm Excess S\$ _____

Surveyor's Name Tan Jiah Sign Tan Jiah

Surveyor's Tel 97495449 Authorised Yes / No _____

Authorised Date 21/1/18 Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No Yes P.M. Yes / No _____

Surveyor's E-mail tanjiah@lkkauto.com

No. of Working Days Recommend 6 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Labour 1	:	9,681.00
Parts	:	7,314.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,189.68
Grand Total	:	18,185.08

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **