

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0605/2018
DATE : 26-JAN-2018

EQ INSURANCE COMPANY LTD

22 GEMMILL LANE

S(069257)

TEL : 62239433

FAX : 62243903

OWNER'S NAME : WU RUIXIN
ADDRESS : APT BLK 127 BISHAN STREET 12
#07-141
S(570127)
TELEPHONE NO : 93854709

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MOMVP000003255-00-000
VEHICLE NO : SKQ8050H
MODEL CODE : SJGBKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20J864093
CHASSIS NO : JF1SJGK85EG035365
MILEAGE : 1 KM
DATE IN : 26/01/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 25/01/2018

Print Date : 27/01/2018

Print Time : 14:29:53

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKQ8050H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM EQ INS LOCATION:MIDDLE RD&NICOLL HIGHWAY JUNCTION DATE:25/01/2018 TIME:1630H		
3	ZZ/002	REPLACE/REPAIR RR LH FENDER,RR BUMPER, RR PANEL	1680.00	
4	ZZ/003	RESPRAY RR LH FENDER,RR BUMPER,RR PANEL	1260.00	
5	ZZ/004	TRANSFER/BALANCE TYRE/RIM	50.00	
6	ZZ/005	TRANSFER DOOR(PER SIDE)MECHANISM	200.00	
7	ZZ/006	REMOVE&REFIX CARPET,SEATS TO FACILITATE REPAIRS RR BOOT GARNISH&TRIM TO FACILITATE REPAIR	550.00	
8	ZZ/007	REMOVE&INSTALL(PER SIDE)QUARTER GLASS RR LH	180.00	
9	ZZ/008	TO CONDUCT(FRONT/REAR)LIGHTING TEST	50.00	
10	ZZ/009	TO SUPPLY&INSTALL(PER SIDE)TINTED FILM	145.00	
11	ZZ/10	SUNDRIES	100.00	
TOTAL LABOUR CHARGES			4215.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKQ8050H

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
1	DISC WHEEL AL 18 18A	28111SG020	750.00			
2	PNL SD OUT QTR RPLH	51439SG0119P	864.00			
3	SKIRT COMPL R	52401SG0109P	288.00			
4	BUMPER FACE R	57704SG012	540.00			
5	REAR BUMPER SIDE BRACKET RHS	57707SG080	14.40			
6	REAR BUMPER SIDE BRACKET LHS	57707SG090	14.40			
7	BEAM COMPL R EU	57711SG0219P	288.00			
8	REAR BUMPER TOW COVER	57731SG010NN	12.60			
9	MUD GUARD R LH	59122SG070	57.60			
10	PNL COMPL DR R LH	60409SG0119P	684.00			
11	LATCH&ACT AY DR RRH	61035SG010	234.00			
12	HANDLE OUT DR	61160FJ000V2	36.00			
13	FRAME AY HDL OUT RLH	62142SG010	39.60			
14	WSTR DR R LH	63512SG011	144.00			
15	WSTR BODY SD FLG R	63572SG001	72.00			
16	REAR BUMPER REFLECTOR RHS	84281SC000	20.40			
17	REAR BUMPER REFLECTOR LHS	84281SC010	20.40			
18	LENS & BODY LAMP REAR LH	84912SG011	388.80			
19	TAPE DR SASH R F LH	90422SG070	18.00			
20	TAPE DR SASH R M LH	90422SG090	10.80			
21	TAPE DR SASH R R LH	90422SG110	14.40			
22	GARNISH AY RG, B	91111SG000	144.00			
23	PROTR R GARNISH	SUPP 91713SG000	21.60			
24	PROTECTOR LWR SD	SUPP 91713SG010	5.40			
25	ORNAMENT R	93033SG001	79.20			

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKQ8050H

		DAMAGED PARTS & PRICES			
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
SUB TOTAL		4761.60	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		952.32	0.00	0.00	0.00
GRAND TOTAL		3809.28	0.00	0.00	0.00
OVERALL TOTAL		3809.28			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKQ8050H

TOTAL LABOUR CHARGES 4215.00
TOTAL SPARE PARTS CHARGES 3809.28

GRAND TOTAL 8024.28 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.