

1-2-18/16:08


2-2-18/11:08

SMRT Accident Vehicle Repair Estimates

30-1-18 / 11:08

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4679E
Ref. No : TAX/01/18/2145
Reg. Date : 19/09/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : TAN PENG KNG
Type of Accident : SIDE SWIPE
Date / Time of Accident : 24/01/2018 03:50:00 PM
Accident Reported Date / Time : 24/01/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094268
Special Instruction to ARC, if any :



SFY9082B - AXA 46
BEFORE PAINT PHOTO, AFTER REPAIR PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP:90036121
LUMPSUM REPAIR

Prepared Date : 24/01/2018 04:57:02 PM

381 433

387 361

↓ 1/4 1/2 3/4 → 2格多

Recording Camera

☒ ☐

Radio Antenna

☒ ☐

1st witness

Date 30-1-18

2nd witness

Date

LEE SHENG AUTO PTE LTD

Vehicle Return Date:

2/2/18

Vehicle Return Time:

11:15

SMRT staff sign:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U305750372

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 676.00	300.00
Total Spray Painting Charges	: 936.00	500.00
Total Material Charges	: 644.22	644.22
Other Charges	: 705.00	235.00
TOTAL	: 2,961.22	1,679.22
Lum Sum Total	: 2,950.00	1,700.00
No. of Repair Days	: 5.00	3.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 24/01/2018 06:29:07 PM	30/01/2018 11:08:10 AM

M

LKK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 24/01/2018 06:29:07 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1802-0100

Invoice No :

Quotation Date : 5/2

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 1/24/2018 6:32:32 PM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	676.00 ✓	300.00 / ✓
Total Labour	676.00	300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR RH	378.00 ✓	200.00 / ✓
TO RESPRAY REAR FENDER RH	378.00 ✓	200.00 / ✓
TO RESPRAY ROCKER PANEL MOULDING	180.00 ✓	100.00 / ✓
Total Spray Painting & Panel Beating	936.00	500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30.00 / ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO TRANSFER DOOR MECHANISM	120.00	60.00 / ✓
TO REPLACE SUNDRY PARTS	100.00	20.00 / ✓
TO WASH AND VACUUM	60.00	0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	125.00 / ✓
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00
Total Other Costs	705.00	235.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67003-47080		6505486	DOOR RR/RH ✓	1	954.50	25.00	715.87 ✓ DT	Replace	Replace	No ✓ DT
			PIXEL STICKER ✓	1	60.00	0.00	60.00 ✓ NE	Replace	Replace	No ✓ NE
61604-47090			FENDER RR/RH R	1	766.80	100.00	0.00 X R	Replace	Repair	No R
			STICKER DECAL SMRT ✓	1	7.80	0.00	7.80 ✓ NE	Replace	Replace	No ✓ NE
	COMMO N		STICKER DECAL 6555 8888 ✓	1	21.60	0.00	21.60 ✓ NE	Replace	Replace	No ✓ NE
62710-47130			QUARTER GLASS RR/RH X	0	846.50	25.00	0.00 X nn	Replace	Not given	No X
	COMMO N		SEALANT W/SCREEN X	0	37.00	0.00	0.00 X nn	Replace	Not given	No X
75851-47900			MOULDING BODY, RH R	1	673.60	100.00	0.00 X R	Replace	Repair	No R
TOTAL MATERIALS								805.28	805.27	
TOTAL MATERIALS(Discounted)								644.22	644.22	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

805.27 /
 - 20%
 644.22 /
 + 300.00 /
 + 735.00 /

 1679.22 /
 4/8 \$1700/- /

Substian
 8/2/2018