

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
 #04/#05 IOB BUILDING
 SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA/AMK

Claim Type: Third Party

Accident Date: 28/01/2018

TP Veh Reg No: SHD6501R

Estimate No: ES1890094/AMK

Date: 29 Jan 2018

Policy No: DMPCSN3053931701

Veh Reg No: SKG2995Z

Make/Model: HONDA JAZZ 1.3L AT

Chassis No: JHMGE68509S206209

Engine No: L13Z11006212

Reg. Date: 24/11/2008

Estimate Repair Cost to Vehicle No :SKG2995Z

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	474.50	1 PC	474.50	
2 REAR BUMPER CLIP	3.70	5 PC	18.50	
3 REAR TAILGATE	771.50	1 PC	771.50	
4 TAILGATE EMBLEM 'JAZZ'	26.50	1 PC	26.50	
5 TAILGATE WINDSCREEN GLASS MOULDING	85.10	1 PC	85.10	
			1,376.10	
		Less 20%	275.22	1,100.88
Special Net				
6 REVERSE SENSOR	200.00	1 SET	200.00	
7 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	
			240.00	240.00
Labour				
8 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	
9 REMOVE & REFIX REAR BUMPER, TAILGATE & ATTACHMENTS, TAILLAMPS ; KNOCKING & REPAIR REAR END PANEL & REALIGN THE SAME	500.00	1 LA	500.00	
10 PUTTY & RESPRAY REAR BUMPER, TAILGATE, REAR END PANEL & ALL AFFECTED AREAS	600.00	1 LA	600.00	
11 RUSTPROOFING	60.00	1 LA	60.00	
			1,280.00	1,280.00
			Total	S\$ 2,620.88
			Add GST @ 7%	183.46
			Total Amount Payable	S\$ 2,804.34

VEHICLE LYING AT:

NO.10 ANG MO KIO INDUSTRIAL PARK 2A

#01-04 AMK AUTOPOINT

SINGAPORE 568047

TEL : 64812001

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation For Cheng Hoe Motor Pte Ltd
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

AUTHORISED SIGNATURE

DORLYN LI