

MSIG OD



Service Order Confirmation

SERVICE ORDER NO: 18IP0258

CUSTOMER NO.: CV035208

CUSTOMER NAME: TAN LIAN MIIN MARGARET

TELEPHONE NO.:

ADDRESS: 23 FLORA ROAD #03-08 ESTELLA GARDENS

Singapore

VEH No.: SLG4485D

Order Date: 01/26/18

Reg Date: 09/29/16

KM: 29,573


VIN NO.: WWWZZZ16ZGM024127

ENGINE NO:

SA: Tang Shu Shi

MODEL: JETTA TSI (DSG) HIGHLINE HIDC MODEL NO.: 1634G7

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P SUNDRIES AIR CON GAS	48	TU	1.25		60 ?
2	B&P MECH ELECT WIRING & MECH COMPONENT CHECK NETT	1	TU	200		200 ✓
3	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	360		360 ✓
4	B&P AIRCON VACUUM & REGAS AIRCON-NETT	1	TU	238		238 ✓
5	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
6	B&P MACP LABOUR LABOUR	8	UNIT	475		3800 1900
7	B&P MACP PAINT SPRAY PAINT	5	UNIT	500		2500 2000
8	B&P NUMBER PLATE B&P NUMBER PLATE -NETT	1	ST	80		80 Bt -
Item						
9	5C6823031E FRONT BONNET	1	PCS	1,020.84	28	735.00 Acc -
10	1K8823186F 9B9 LATCH	1	PCS	111.33	28	80.16 Bt -
11	5C8823509D BONNET LOCK	1	PCS	158.59	28	114.18 ?
12	5C6823301A HINGE LH	1	PCS	135.40	28	97.49 Bt -
13	5C6823302A HINGE RH	1	PCS	135.40	28	97.49 Bt -
14	5C6823708 BONNET SEAL RH	1	PCS	26.56	28	19.12 Acc -
15	5C6807217Q GRU FRT BUMPER	1	PCS	852.00	28	613.44 R
16	5C6807183A FRT LHS BUMPER BRACKET	1	PCS	32.26	28	23.23 ?
17	5C6807184A FRT RHS BUMPER BRACKET	1	PCS	31.11	28	22.40 ?
18	5C6805706J BUMPER CENTRE BRACKET	1	PCS	100.89	28	72.64 ?
19	5C6807248H BUMPER FOAM LHS	1	PCS	103.80	28	74.74 ?
20	5C6807248G BUMPER FOAM RHS	1	PCS	103.80	28	74.74 ?
21	5C6807109C FRT REINFORCEMENT	1	PCS	573.69	28	413.06 ?
22	5C6919493A SENSOR BRACKET	1	PCS	53.52	28	38.53 ?
23	5C6919494A SENSOR BRACKET	1	PCS	53.52	28	38.53 ?
24	D 180KU2A1 2KADHESIVE	1	PCS	103.66	28	74.64 Acc -
25	D 822150A1 BONDAGENT	1	PCS	74.16	28	53.40 Acc -
26	5C6853651AJZLL FRT RADIATOR GRILLE	1	PCS	350.46	28	252.33 CRA -
27	5C8941751B H/LAMP LH	1	PCS	5,098.50	28	3,670.92 ?
28	5C8941752B H/LAMP RH	1	PCS	5,098.50	28	3,670.92 CRA -



Service Order Confirmation

SERVICE ORDER NO: 18IP0258

CUSTOMER NO.: CV035208

CUSTOMER NAME: TAN LIAN MIIN MARGARET

TELEPHONE NO.:

ADDRESS: 23 FLORA ROAD #03-08 ESTELLA GARDENS
Singapore

VEH No.: SLG4485D

Order Date: 01/26/18

Reg Date: 09/29/16

KM: 29,573

VIN NO.: WVVZZZ16ZGM024127

ENGINE NO:

SA: Tang Shu Shi

MODEL: JETTA TSI (DSG) HIGHLINE H1DCMODEL NO.: 1634G7

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	5C6805588Q LOCK CARRIER	1	PCS	784.03	28	564.50
30	5C6805567 SUPPORT LOCK CARRIER	1	PCS	85.48	28	61.55
31	5C6805931 H/LAMP TOP PANEL LH	1	PCS	37.78	28	27.20
32	5C6805932 H/LAMP TOP PANEL RH	1	PCS	37.78	28	27.20
33	5C0820411K A/C CONDENSER	1	PCS	680.58	28	490.02
34	1K0121253AA RADIATOR INNER	1	PCS	909.46	28	654.81
35	1K0121251BN RADIATOR OUTER	1	PCS	909.46	28	654.81
36	5C6121283G AIR GUIDE LH	1	PCS	24.12	28	17.37
37	5C6121284G AIR GUIDE RH	1	PCS	24.12	28	17.37
38	G 013040M2 COOLANT ADD 1.5 Ltr Ready Mix	2	PCS	27.00	28	38.88
39	5C6955453S WIPER TANK	1	PCS	181.20	28	130.46
40	431955465A GASKET	1	PCS	5.40	28	3.89
41	443955465 GASKET	1	PCS	1.60	28	1.15
42	G 052184A2 WINDSHIELD CLEANER 1 Litre Btl	1	PCS	22.50	28	16.20
43	5C6821106A FENDER RH	1	PCS	691.66	28	498.00
44	5C6821136 RHS FENDER BRACKET	1	PCS	45.27	28	32.59

Remarks : MSIG (IN-HOUSE) OD CLAIM

DOA: 26/01/2018

SURVEY BY:

EXCESS: \$

Service Order Confirmation

SERVICE ORDER NO: 18IP0258

CUSTOMER NO.: CV035208

CUSTOMER NAME: TAN LIAN MIIN MARGARET

TELEPHONE NO.:

ADDRESS: 23 FLORA ROAD #03-08 ESTELLA GARDENS

Singapore

VEH No.: SLG4485D

Order Date: 01/26/18

Reg Date: 09/29/16

KM: 29,573

VIN NO.: WWWZZZ16ZGM024127

ENGINE NO:

SA: Tang Shu Shi

MODEL: JETTA TSI (DSG) HIGHLINE HIDC MODEL NO.: 1634G7

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
-----	-------------	-----	-----	------------	--------	--------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

RASUL
Hp 90010068
8 days
30/01/18 @ 1645
EXCESS: 500
REVERT
Resurvey by part

TOTAL 20,710.95

GST AMOUNT 1,449.77

TOTAL AMOUNT 22,160.72



Authorized Signature

Certified Goods/Service received:

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT