

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD, #17-00
TOWER BLOCK, MND COMPLEX 069110

Attention : Motor Claim Department

Estimate : ES201811

Date : 22/01/2018
Vehicle Num. : SLM 4548A (LCR)
Make/Model : TOYOTA PRIUS HYBRID
Chassis/Eng# :
Accident Date : 21/01/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	REAR BUMPER ✓ Deform	-	423.90
3.	1	REAR LOWER BUMPER ✓ Pun	✓	552.30
4.	1	REAR BUMPER REINFORCEMENT ?	?	318.80
5.	1	TAILGATE OUTER GARNISH R	✓	881.70
6.	1	TAILGATE ✓ BT	✓	922.50
List Total S\$:				3,099.20
25.00% Discount S\$:				774.80
				2,324.40

1.	1SET	SPECIAL NETT ITEMS :		
2.	1SET	REAR BUMPER CLIP ✓ NEC	-	30.00
3.	1	TAILGATE OUTER GARNISH CLIPS ✓ NEC	-	30.00
4.	1	SEALANT	-	160.00 50
Special Nett Total S\$:				220.00

LABOUR :			
WIRINGS CHECK AND RECTIFY WHERE NECESSARY		180.00	30
REMOVE & REFIT REAR WINDSCREEN GLASS		240.00	120
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES		180.00	60
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS		1,500.00	600
PUTTY AND SPRAY PAINT ALL AFFECTED AREAS		1,200.00	600
Labour Total S\$:		3,300.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

for WORLD AUTO PTE LTD

Signature: _____
Date: _____

Sebastian.
29/1/18.

- Part by part repair.

E. & O.E. Total S\$: 5,844.40

- Question mark Item Photo

- Photo Before Paint

90036121

sebastianyang@lkkauto.com.