



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mah Yingjie	Cust No/Name LCV03281/Mr Mah Yingjie
30 Dover Rise	Reg No/Reg Date SKR3688X / 29/10/201
#08-02 Dover Parkview	Date In/Mileage / 0
Singapore 138687	Chassis No KNAFW411MA5252349
Contact No 66333188	Engine No G4FCAH204548
	Make/Model KIA/CERATO 1.6 A SX (2010)
	Colour/Trim LC / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV03281	CRDVCH	27/01/2018/ 13:35		465 / Tay Jian Ye	22335

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 TO RENEW FRT LH FENDER AND FRT LH SIDE MIRROR REPAIR FRT LH DOOR AND FRT BUMPER				1100 2200.00
E PNT98000 PAINT WORK SPRAY FRT BUMPER AND FRT LH FENDER, FRT LH DOOR , FRT LH SIDE MIRROR				1050 2100.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30 50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 200.00
M SUNDRY TO APPLY ANTI COROSSION ON AFFECTED PORTION				80 150.00
M SUNDRY SUNDRIES				20 550.00
M MIRROR ASSY-OUTSIDE RR VIEW,LH	1.00	500.00	00.00	500.00
M PANEL-FENDER,LH	1.00	464.00	00.00	464.00

SURVEYOR NAME: Tan Jie 97495745  
 SURVEYOR SIGNATURE: [Signature]  
 DATE: 6/2/18 @ 12:15 WP  
 REMARKS: Resurvey before paint  
SURC (Holland)  
4 days.

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Confirm & accepted by  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_

Authorized signatory and company stamp

Nett 6,214.00  
 7% GST on 6214.00 434.98  
**Total Payable 6,648.98**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.