

CASE OWNER:

Chen wale

CC 4 / LCR180001748

R1 js3/v

LKK:

IDAC:

Surveyor:

RASUL

DOI:

30/01/18

Date / Time:

29/01/18

Registered in Merimen:

29/01/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SLK 9777D

Name of Insured : LCR

Insured Tel No. : HP:

Excess Sec II :SS

D.O.A. : 21/01/18

Is driver the owner?

( YES ☒ NO )

Nature of Accident :

If NO, Driver Name / Age : SIVAPATHAN SUNDARLINGAM

Driver Tel No. : 9010 6659

(VA ☒ YES / NO )

Claim No. : 0744808571SG

Policy No. : 0999995011

Make / Model : TOYOTA AXIO

Place of Accident : PIE (ALJUNIED WEST FLYING)

OI GIA REPORT ☒ YES / NO ; TP GIA REPORT ☒ YES / NO

Insured Liability : % Final ? Yes / No

FBM 5706Y

INSRS:  
WSP: Southern motor  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

21/01/18 (jog)

CCTV -

8-2-18

02/02/18 (typist)

FBM 5706Y - CC2/EGZ18001428/K/ps3  
1 - NSA/EGZ18001242/14  
SLK 9777D - NSA/EGZ18001242/14DOP 21/01/18  
DOP 21/01/18  
DOP 21/01/18

OI VIDEO - W/IN LANE

AIG MANDATE TO REJECT.



RECEIVED 08 FEB 2018

STAGE DATE / PIC

Non-Reporting ltr (1st):	} NA
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	} NA NOT AT FAULT
After call ltr to OI:	

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>	
After call ltr to OI:	<input checked="" type="checkbox"/>	
Authorisation To Act:	<input checked="" type="checkbox"/>	
Release Voucher:	<input checked="" type="checkbox"/>	
Final Repair Bill:	<input checked="" type="checkbox"/>	
Car Rental Invoice:	<input checked="" type="checkbox"/>	
Towing Invoice:	<input checked="" type="checkbox"/>	
LTA / GIA:	<input checked="" type="checkbox"/>	
Medical Bill:	<input checked="" type="checkbox"/>	
PIR:	<input checked="" type="checkbox"/>	
Mandate/Reject Instruction:	<input checked="" type="checkbox"/>	
LOD:	<input checked="" type="checkbox"/>	
Payment Breakdown Form:		
Post-Repair Photos:		
Others REJECTION EMAIL:	<input checked="" type="checkbox"/>	

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with:

Repair Cost: \$\$ ( days) Reduction: % Email ☐ Call ☐FINAL SETTLEMENT Date/Time: Confirm with: Email ☐ Call ☐

Final Liability: % 0 (Agreed / Assessed) BOLA S/N No. : NIL CCTV

Repair Cost: \$\$ X OI W/IN LANE

Loss of Rental (LOR): \$\$ X ( days)

Loss of Use (LOU): \$\$ X (\$ x days)

Loss of Income (LOI): \$\$ X (\$ x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search: \$\$ X

Medical: \$\$ X

Disbursement: \$\$ X (e.g. Tow/ Independent)

Legal Cost: \$\$ X

Total: \$\$ Global Sum \$:

FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐

Payee 1: \$\$ X Name 1:

Payee 2: (Strike if N.A.) \$\$ X Name 2: X

Payee 3: (Strike if N.A.) \$\$ X Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT 02/02/18

- REJECTED \$320/-

Form

LCP

Ref: 8001748/R1JS3

5214N

30/11/18

FBM 57064

2017 DK

REPAIRS

0121 NS THREE CORES DIA 10MM

FBM 57064

Southern Motor

Blk 1006, Blk Merch Lane 2 #01-10

REPAIR

REPAIR

REPAIR

REPAIR


Excess

Diagrams

REPAIR

Policy Condition

Remarks: The vehicle has commenced its repair at the time of inspection.



REPAIR

REPAIR Room Consistent? Yes or No

REPAIR Room Consistent? Yes or No

REPAIR 4 days Fee Yes or No

REPAIR 4 days Fee Yes or No

REPAIR 24 HRS up

Date Repair Completed

Vehicle IN OUT

REPAIR Time After Inspection

P/P \$3,183.20

R(607.50/.16%)

REPAIR Fee

☐

Prel. Report

☐

Final Report

Days Of Repair

Resurvey No. of No

Survey Fee

Survey Fee

Survey Fee

Survey Fee

Survey Fee

Survey Fee

Survey Fee

Survey Fee

Add Fee

☐

REPAIR Fee

REPAIR Fee

REPAIR Fee

REPAIR Fee

REPAIR Fee

REPAIR Fee



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/LCR18001748/R1js3

78 SHENTON WAY #08-16  
CHARTIS BUILDINGS SINGAPORE 079120

Date : 29-01-2018



Code : LCR

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 9787D	Veh. Inspected	FBM 5706Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	29/01/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	21/01/2018	Inspection Date	30/01/2018
Survey held at	SOUTHERN MOTOR BLOCK 1006 BUKIT MERAH LANE 2 #01-10 SINGAPORE 159762		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



南方摩哆  
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10  
Singapore 159762 Tel:62730369 Fax:62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 29<sup>th</sup> January 2018

Motor Vehicle Department

119 1st Pacific Insurance Aft 4th

78 Thornton Way 207-16

61 c. Building

Singapore 078120

Dear Mrs

Re: Cont of repair to Honda CB400X - 78MS706Y

1 pc of	Windscreen	windscreen		21000	XSL
"	Front signal	Front signal		9000	CR
"	Top engine guard	Top engine guard		30000	SL
"	Lower engine guard	Lower " "		30000	SL
"	Front mudguard	Front mudguard		25000	CR
"	Front fairing	Front fairing		24000	CR
"	Centre fairing	Centre fairing		25000	SL
"	Exhaust pipe	Exhaust pipe		25000	SL
"	Front footrest	Front footrest		6500	SL
"	Rear footrest	Rear "		4500	SL
"	Fuel tank plate	RH	Fuel Tank plate RH	19500	at
"	Brake lever		Brake lever	4500	SL
"	Handle bar		Handle bar	15000	PH
"	Mirror		Mirror	15000	SL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Receiver**  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Yours faithfully,  
SOUTHERN MOTOR

RASUE  
4p 90010068  
4 days  
P/P  
30/01/18 @ 1250  
Reg before repair

Natt  
Frankfurt  
Jack fork  
GIVI Rose  
Lambour

~~3000~~  
~~1500~~ 60  
~~1500~~ 150 sec  
~~3000~~ 200  
 780-70

Tel 64192000  
Fax 64152727

## Joy Irene (LKKAUTO)

---

**From:** Tee, Chee-Wah <Chee-Wah.Tee@aig.com>  
**Sent:** Thursday, 8 February 2018 9:35 AM  
**To:** Joy Irene (LKKAUTO)  
**Cc:** Vivian Lau (LKKAUTO)  
**Subject:** FW: TP / 0744808571SG---FBM5706Y VS SLK9787D (OI) DOA 21/01/2018 \*\*\* LKK REF - CC4/LCR18001748/js3

Dear Joy,

Thanks for your email.

Based on the video footage, we are of the view that OI is not liable for this accident.

Kindly reject TPPD claim.

Thank you.

Regards,

Tee Chee Wah  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120  
Tel +64191089 | Fax +68357416  
[Chee-Wah.Tee@aig.com](mailto:Chee-Wah.Tee@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

### IMPORTANT NOTICE:

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** Joy Irene (LKKAUTO) [mailto:JoyIrene@lkkauto.com]  
**Sent:** Wednesday, February 07, 2018 8:53 AM  
**To:** Tee, Chee-Wah  
**Cc:** Vivian Lau (LKKAUTO)  
**Subject:** TP / 0744808571SG---FBM5706Y VS SLK9787D (OI) DOA 21/01/2018 \*\*\* LKK REF - CC4/LCR18001748/js3

Dear Mr. Tee,

We refer the subject.

Basing on the video, OI was travelling within lane.

In view of this, we are of the opinion that OI report is probable and OI should not be blamed for the accident.

Kindly let us have your view and opinion whether or not liability be denied.

Thank you.

Best Regards,  
Joy Irene | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## Joy Irene (LKKAUTO)

---

**From:** Joy Irene (LKKAUTO)  
**Sent:** Thursday, 8 February 2018 11:27 AM  
**To:** 'Southern Motor'  
**Cc:** CS A Team; Admin A  
**Subject:** FBM5706Y VS SLK9787D (OI) DOA 21/01/2018 \*\*\* LKK REF - CC4/LCR18001748/js3

WITHOUT PREJUDICE

Dear Sirs,

We refer to our e-mail below.

We regret to inform you that we are unable to look into your client's claim.

The video that was provided to your office on 30.01.2018 showed our insured was travelling within lane.

Should you have newly discovered evidence to prove our client's fault, please send us a copy for our review and for our principal's consideration.

Thank you.

Best Regards,  
Joy Irene | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

**From:** Joy Irene (LKKAUTO)  
**Sent:** Tuesday, 30 January 2018 4:49 PM  
**To:** 'Southern Motor' <[soumotor@hotmail.com](mailto:soumotor@hotmail.com)>  
**Cc:** Vivian Lau (LKKAUTO) <[vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** RE: Pre repair inspection request - FBM5706Y VS SLK9787D (OI) DOA 21/01/2018 \*\*\* LKK REF - CC4/LCR18001748/js3

WITHOUT PREJUDICE

Dear Sirs,

We attach a copy of the video from our insured's car for your viewing.

Our insured was travelling within lane.

Best Regards,  
Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd  
DID: 6749-5792 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

**From:** Southern Motor [<mailto:soumotor@hotmail.com>]  
**Sent:** Tuesday, 30 January 2018 2:41 PM  
**To:** Joy Irene (LKKAuto) <[JoyIrene@lkkauto.com](mailto:JoyIrene@lkkauto.com)>  
**Subject:** Re: Pre repair inspection request - FBM5706Y VS SLK9787D (OI) DOA 21/01/2018 \*\*\* LKK REF - CC4/LCR18001748/js3

Dear Madam,

We shall be much obliged if you would let us know whether the above motorcycle No FBM5706Y is authorized for direct settlement.

Thank you.

Yours Faithfully,  
Southern Motor

---

**From:** Shirley Hiew (LKK Auto) <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)>  
**Sent:** Monday, January 29, 2018 7:03 PM  
**To:** Southern Motor; assignments  
**Cc:** Admin A; Joy Irene (LKKAuto); Vivian Lau (LKKAuto); Hsiao Tong (LKKAuto)  
**Subject:** Pre repair inspection request - FBM5706Y VS SLK9787D (OI) DOA 21/01/2018 \*\*\* LKK REF - CC4/LCR18001748/js3

Dear Sir/Madam,  
We refer to the above matter.  
Please be informed that we are currently pending for our insured's GIA report.

Kindly note that for liability, claim negotiation and settlement, please contact Joy at 6749 5792.  
Our respective case handler will look into the matter and revert to you in due course.

Meanwhile, please arrange appointment for survey.

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108





### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Jan 2018 <a href="#">Edit Reg</a>		29 Jan 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,183.20</b> <a href="#">Edit Estimates</a>	<b>S\$3,183.20</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	LCRD Pte Ltd, Co. Reg. No.: NA		
Main Claimant:	ZHANG JUNWEI, ID: G6885214N		
Vehicle Reg. No.:	FBM5706Y	Date of Loss:	21/01/2018 14:00 - :59
Claim Type:	TP / 0744808571SG	Policy/Cover Note No.:	0999995011 (Comprehensive)
Vehicle Reg. No. (Insured):	SLK9787D	Policy No. (Claimant):	DMMPHQ17-000944
		Excess:	
Repairer:	Southern Motor (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10, 159762 Bukit Merah - Tel: 62730369		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tee, Chee-Wah] Chee-Wah.Tee@aig.com		
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 07/02/2018]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBM5706Y (07448085715G)  
[SLK9787D]  
TP  
ZHANG JUNWEI  
Jan 21 2018 2:00PM  
[LCRD Pte Ltd]  
Southern Motor

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<a href="#">Upload Video</a>	<a href="#">Upload Audio</a>	View <span style="border: 1px solid black; padding: 0 5px;">View in Browser</span>
----------------------------------	--	-------------------------------	------------------------------------	------------------------------	------------------------------	--

<b>Video</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	30/01/18 14:21	Video - Accident		Load MP4	

<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	30/01/18 11:26	Accident Statement <small>From: SC - Reg. No: SLK9787D, Claimant: LCRF PTE LTD</small>		Load HTML	

<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/02/18 11:43	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
2	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
3	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
4	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
5	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
6	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
7	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
8	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
9	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
10	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
11	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
12	08/02/18 11:43	General View Right		Load JPG	<input checked="" type="checkbox"/>
13	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
14	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
15	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
16	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
17	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
18	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
19	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
20	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
21	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
22	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
23	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
24	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
25	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
26	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
27	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>
28	08/02/18 11:43	General View		Load JPG	<input checked="" type="checkbox"/>

29	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	08/02/18 11:43	General View	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1	Thumbnail	Print
1	29/01/18 17:35	EMAIL FROM WORKSHOP DD 29.01.2018	1	Load PDF	
2	29/01/18 17:35	ACKNOWLEDGEMENT EMAIL TO AIG DD 29.01.2018	1	Load PDF	
3	29/01/18 17:35	TP ESTIMATE + NOTIFICATION FROM WORKSHOP + TP GIA REPORT	1	Load PDF	
4	02/02/18 13:12	TP ESTIMATE- MARKED	1	Load PDF	
5	08/02/18 11:40	REJECTION LETTER	1	Load PDF	
6	08/02/18 11:40	MANDATE TO REJECT	1	Load PDF	

## Documents Checklist

Reset	Save	Print
-------	------	-------

**DOCUMENTS CHECKLIST**

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18001748/R1JS3Q2

Date: 14/02/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995011  
 Claimant Vehicle No: FBM5706Y Insured Vehicle No: SLK9787D  
 Date of Loss: 21/01/2018 Nature of Claim: TP Claim No: 0744808571SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **FBM5706Y**  
 Make & Model: HONDA CB400X, 399cc Engine No: NC47E5200047  
 Reg. Date: 14/12/2017 (Man. Year: 2017) Chassis No: JH2NC4793HK200046  
 Colour: Grey Odometer: 3182 km  
 Engine Capacity: 399 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 120/70Z R17 Rear Tyre Size: 160/60Z R17  
 Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,375.70	2,893.20	482.50	14.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	415.00	290.00	125.00	30.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,790.70</b>	<b>3,183.20</b>	<b>607.50</b>	<b>16.03</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>265.35</b>	<b>222.82</b>	<b>42.53</b>	<b>16.03</b>
<b>Nett Amount (S\$)</b>	<b>4,056.05</b>	<b>3,406.02</b>	<b>650.03</b>	<b>16.03</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

## INSPECTION

Date of Assignment: 29/01/2018  
 Date Inspected: 30/01/2018 Inspected At: Southern Motor (HQ)  
 BLK 1006 BUKIT MERAH LANE 2, #01-10  
 Singapore 159762  
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: Joy Irene Bascao

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WINDSCREEN	Serviceable	210.00 FL	*- FL
2	1		*FRONT SIGNAL	Cracked	90.00 FL	*90.00 FL
3	1		*TOP ENGINE GUARD	Scratched	350.00 FL	*350.00 FL
4	1		*LOWER ENGINE GUARD	Scratched	300.00 FL	*300.00 FL
5	1		*FRONT MUDGUARD	Cracked	250.00 FL	*250.00 FL
6	1		*FRONT FAIRING	Cracked	240.00 FL	*240.00 FL
7	1		*CENTRE FAIRING	Scratched	250.00 FL	*250.00 FL
8	1		*EXHAUST PIPE	Scratched	850.00 FL	*850.00 FL
9	1		*FRONT FOOTREST	Scratched	65.00 FL	*65.00 FL
10	1		*REAR FOOTREST	Scratched	45.00 FL	*45.00 FL
11	1		*FUEL TANK PLATE RH	Cut	195.00 FL	*195.00 FL
12	1		*BRAKE LEVER	Scratched	48.00 FL	*48.00 FL
13	1		*HANDLE BAR	Bent	150.00 FL	*150.00 FL
14	1		*MIRROR	Scratched	180.00 FL	*180.00 FL
15	1		*HANDLE BALANCER	Scratched	35.00 FL	*35.00 FL
16	1		*FORK FAIRING BRACKET	Serviceable	215.00 FL	*- FL
17	1		*GIVI BOX	Scratched	250.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,723.00</b>	<b>3,198.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>347.30</b>	<b>304.80</b>
<b>Total Parts (\$\$)</b>	<b>3,375.70</b>	<b>2,893.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT	New	30.00	30.00
2	LABOUR	New	300.00	200.00
3	JACK FORK	New	85.00	60.00
Gross Labour Cost (S\$)			<b>415.00</b>	<b>290.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >