



南方摩哆
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel: 62730369 Fax: 62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 29th January 2018

Motor Claims Department

Attn: Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16

Attn: Building

Singapore 078120

Dear Sirs

Re: Cost of repair to Honda CB400X - 7BM5706Y

1 pc of Windscreen	100.00 X
" Front signal	90.00 CRA -
" Top engine guard	350.00 SCR -
" Lower engine guard	300.00 SCR -
" Front mudguard	250.00 CRA -
" Front fairing	240.00 CRA -
" Centre fairing	250.00 SCR -
" Exhaust pipe	250.00 SCR -
" Front footrest	65.00 SCR -
" Rear footrest	45.00 SCR -
" Fuel tank plate RH	195.00 AT -
" Brake lever	45.00 SCR -
" Handle bar	150.00 PH -
" Mirror	150.00 SCR -
" Handle balancer	35.00 SCR -
" Front fairing bracket	215.00 X
	<u>3473.00</u>

Less 10%

3125.70

Nett

Transport
Jack fork
Givi box
Labour

3000 /
1500 60

2500 150 SCR -

3000 200

3780.70

Yours faithfully,
SOUTHERN MOTOR

Tel 64193000
Fax 64153717