

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: QBE Insurance International Ltd

Policy No: Third Party

Date: 26.01.2018

Accident Date : 18.01.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Nissan Latio" Reg. No. SJN4527D Claiming Against Your Insured Reg. No. SKG5225T		
1pc	Rear Bumper	564.00	N
12pcs	Rear Bumper Clips	2.60	N
2pcs	Rear Bumper Brackets	96.70	N
1pc	Rear Bumper Auto Boot Sensor Receiver		N
1pc	Rear Bumper Sponge		N
1pc	Boot Emblem		N
1pc	Boot Badge Latio		N
			1,195.10
	Less 10%		119.51
			1,075.59
1pc	Rear Bumper Reverse Sensor	220.00	SN
1pc	Rear Bumper Reverse Camera	200.00	SN
	To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring Etc	80.00	
	Labour Charge - Panel Beating, Replacement Of Boot, End Panel and Parts Replacement	300.00	
	To Respray Affected Areas	400.00	
			3,025.59
		Total :	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorised
LIS Repw
After panel beating
LKK Auto Consultants
26/1/2018
4w days

4/5 \$1500
4w days