

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: QBE Insurance International Ltd

Policy No: Third Party

Date: 26.01.2018

Accident Date : 18.01.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Nissan Latio" Reg. No. SJN4527D Claiming Against Your Insured Reg. No. SKG5225T			
1pc	Rear Bumper <i>Rm</i>	564.00	564.00 N X
12pcs	Rear Bumper Clips <i>SV</i>	2.60 140	31.20 N X
2pcs	Rear Bumper Brackets <i>RJH</i>	96.70	X 193.40 N X
1pc	Rear Bumper Auto Boot Sensor Receiver <i>HN</i>		X 215.00 N X
1pc	Rear Bumper Sponge <i>SV</i>	41.00	41.00 N X
1pc	Boot Emblem <i>HN</i>		68.50 N X
1pc	Boot Badge Latio <i>HN</i>		82.00 N X
			1,195.10
	Less 10%		119.51
			1,075.59
1pc	Rear Bumper Reverse Sensor <i>HN</i>	220	280.00 SN X
1pc	Rear Bumper Reverse Camera <i>HN</i>	350	350.00 SN X
	To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring Etc	80	120.00 HN
	Labour Charge - Panel Beating, Replacement Of Boot, End Panel and Parts Replacement	300	500.00 2001-
	To Respray Affected Areas	400	700.00 2001-
		Total :	3,025.59

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorised
W/S Repw
After paint
LKK Auto
22/1/2018
4 days

4/5 \$1500
4w days
P/Part
\$4001-
2 days
12/2/18