

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

### **SMRT Accident Vehicle Repair Estimates**

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHB5336T

Ref. No

TAX/01/18/2147

Reg. Date

11/09/2012

Vehicle Type

TAXI

Make

CHEVROLET EPICA 2.0 VCDI

Model

EPICA-2.0

Name of Driver

TENG MOSES

Type of Accident

HEAD TO REAR

Date / Time of Accident

25/01/2018 09:57:00 AM

Accident Reported Date / Time :

25/01/2018 12:00:00 AM

Surveyor is Required?

Yes

Survey by

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued?:

Accident Repair Job Card No :

000024094284

Special Instruction to ARC, if any :

SJX1668Y - AXA

Prepared Date : 25/01/2018 12:11:23 PM

Carre @ SHIRTH 6555 8888

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

10:16

Sebastian.
30/1/18.
- Lung Sun Repair.
- Quertion Mark Item Photo
- Photo After Paint.

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: KL1LA69RJBB134326 Mileage :

Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates** 

Quotation from ARC Adjusted by Surveyor, if applicable

0

Total Labout Charges : 676.00 0.00

Total Spray Painting Charges : 936.00 0.00

 Total Material Charges
 : 3,327.38
 3,395.28

 Other Charges
 : 500.00
 0.00

 TOTAL
 : 5,439.38
 0.00

 Lum Sum Total
 : 5,450.00
 0.00

No. of Repair Days : 5.00 0.00
Prepared / Adjusted By : 5.00

Arc / Surveyor Sing Off Date : 25/01/2018 03:53:25 PM 01/01/1900 12:00:00 AM

repared / Adjusted Date

Remarks :

repared Date : 25/01/2018 03:53:25 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : Prepared Date :

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
TO REPAIR REAR PORTION	676.00	0.00 3 00 .			
Total Labour	676.00	0.00			

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
TO REPSRAY REAR BUMPER	378.00	0.00 200			
TO RESPRAY BUMPER BEAM	180.00	0.00 ?			
TO RESPRAY REAR BOOT LID	378.00	0.00 200			
Total Spray Painting & Panel Beating	936.00	0.00			

# Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
TO CHECK WIRING AND SYSTEM FUNCTION	80.00				
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	0.00			
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 ×			
TO REPLACE SUNDRY PARTS	100.00	0.00 30			
TO WASH AND VACUUM	60.00	0.00 ×			
Total Other Costs	500.00	0.00			

'AX/01/18/2147 Page:

3

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace /	No
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace	No
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace 7	No
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace 7	No
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace 1	No
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace 7	No
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace p	No
96851765	REAR	6504566	LAMP BACK UP LH	1	151.00	10.00	135.90	Replace	Replace/CR	No
96851763	REAR	6504563	LAMP RR COMBINATION LH	1	415.00	10.00	373.50	Replace	Replace 7	No
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace	No NEC
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace	No NEC
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace /	No NEC
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80		Replace	No NEC
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No NEC
	TOTAL MATERIALS						4,244.10 4,244.10			
	TOTAL MATERIALS(Discounted)							3,327.38	3,395.28	

# Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

AX/01/18/2147