



AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120
Our Client,
SIMON WOO YEE THYE

5 Days.
Lump sum repair.
After repair photos.
Guo Qiang - 82880282

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Repair Estimate

Third party survey is on a "Without Prejudice" basis

CarCrafters Singapore Pte Ltd

48 Toh Guan Road East, Singapore 608686
Tel: 6267 9916 Fax: 6267 9313

Signature: Date: 1/2/2018
Date: Vehicle Num: SLP1771A
Make/Model: AUDI A6-2.0 (A)
Chassis No: WAUZZZ4G9CN086986

www.carcrafters.sg

Guo Qiang@hkauto.com

05/2/18

S/N	PARTS	QTY	PRICE	TOTAL
1	REAR BUMPER / Cut	1	\$ 1,584.00	\$ 1,584.00
2	REAR FENDER RH Repair x	1	\$ 1,900.00	\$ 1,900.00
3	RIM / Cut	1	\$ 980.00	\$ 980.00
4	TYRE X	1	\$ 320.00	\$ 320.00
5	REAR ABS SPEED SENSOR RH X	1	\$ 170.00	\$ 170.00
6	REAR BUMPER GUIDE PIECE RH /	1	\$ 38.00	\$ 38.00
7	LOWER SPOILER X NN	1	\$ 190.00	\$ 190.00
8	REAR WHEELHOUSING LINER RH ?	1	\$ 190.00	\$ 190.00
9	TAILLIGHT INNER RH X	1	\$ 910.00	\$ 910.00
10	TAILLIGHT OUTER RH X	1	\$ 910.00	\$ 910.00
11	REAR SENSOR X	2	\$ 160.00	\$ 320.00
12	SUBFRAME X	1	\$ 2,970.00	\$ 2,970.00
13	REAR TRAILING ARIM RH X	1	\$ 820.00	\$ 820.00
14	TRACK CONTROL ARM UPPER RH ?	1	\$ 540.00	\$ 540.00
15	TIE ROD RH ?	1	\$ 110.00	\$ 110.00
16	WHEELBEARING HOUSING RH ?	1	\$ 970.00	\$ 970.00
17	REAR SHOCK ABSORBER RH X NN	1 set	\$ 715.00	\$ 715.00
TOTAL AMOUNT				\$ 13,637.00
LABOUR				
1	To remove/ replace/ refit of rear portion of realigned rear bumper, rear fender RH & other area.			\$ 800.00
2	To remove & replace of rim & tyre.			\$ 100.00
3	To remove/replace/refit of rear undercarriage RH.			\$ 400.00
4	To send for wheel alignment & balancing. - Alignment report if undercarriage effect			\$ 100.00
5	To putty & respray rear bumper, rear fender RH & other affected accident area.			\$ 800.00
6	To check accident affected wiring system & recover.			\$ 50.00
7	To recode & decode engine management system & fault code clearing after repair works.			\$ 100.00
TOTAL				\$ 15,987.00
GST 7%				\$ 1,119.09
GRAND TOTAL				\$ 17,106.09

400

30.

?

670

400

30

X NN