

## SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKC2182Z/1801024

29<sup>th</sup> January 2018

The Manager  
Motor Claim Department  
AIG Asia Pacific Insurance Pte Ltd  
CHARTIS Building  
78 Shenton Way #07-16  
Singapore 079120

Date of Accident : 26<sup>th</sup> January 2018  
Location : Alexandra Road Towards West Coast Highway  
Third Party Claim Vehicle No : SLE 7771 T  
Repair Cost For Vehicle No : SKC 2182 Z (Volkswagen Jetta 1.4 TSI)

### Estimate Supply of Parts & Labours

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Front bumper fascia	1	1,140.00	\$ 1,140.00
2	Front bumper clips	1set	25.00	\$ 25.00
3	Front bumper retainer LH	1	44.15	\$ 44.15
4	Headlamp LH	1	634.40	\$ 634.40
5	Headlamp bracket LH	1set	59.95	\$ 59.95
6	Front bumper reinforcement beam	1	606.05	\$ 606.05
7	Front bumper fog lamp LH	1	204.65	\$ 204.65
8	Front bumper fog lamp cover LH	1	87.00	\$ 87.00
				<u>\$ 2,801.20</u>

<u>Labour Charges :-</u>	<u>Amounts</u>
Cut out, renew, knocking & welding front bumper fascia, remove & install all damage parts & re-align body.	\$ 780.00
Spray painting on damage parts	\$ 800.00
Check all lighting after repairs	\$ 65.00
Labour Charge	<u>\$ 1,645.00</u>
Total Amount	<u>\$ 4,446.20</u>

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.