Au Wan Hoo @ Albert Au Wan Ho Block 9 #14-457 Jalan Rumah Tinggi, Singapore 150009 Tel (65) 6235 8097 HP (65) 8450 6622 E-mail albertau28@hotmail.com

6 February 2018

LKK Auto Consultants Pte Ltd 51 Ubi Ave 1, #01-25 Paya Ubi Industrial Park Singapore 408933 Your ref: CC3/AIG18001764/es3

Dear Mr Asher Sng

AIG Insurance Policy No: 2100348419-04 - Motor Vehicle: SKK6042B

My car was involved in an accident which happened in the B2 Car Park of Terminal 3 Changi Airport.

On 26 January at about 2.50pm, when I was slowly reversing my car into a parking lot, a car BMW bearing registration plate SCL7873C bumped into my car from the back.

My car was then in the middle of the main driveway backing towards a parking lot, the said BMW from a subsidiary driveway crossed the white line without stopping and bumped into the back my car.

The person driving the BMW is Jeffrey Tay (not sure of spelling). His hand phone number is 97297744.

After visually checking my Camry and the BMW, I had not found any damage. Therefore, I didn't think making a claim or sending my Camry for checking was necessary.

I was surprised to receive your letter yesterday, letter dated 31 January. IT WAS CLEAR TO ME THE BMW SCL7873C WAS IN THE WRONG in not stopping at the white line, and not looking before going across the line onto the main driveway. Under the circumstances, Mr Jeffrey Tay was fully responsible for the accident.

Enclosed are some photos showing the location, and the position of the two cars after the accident,

Regards,

Au Wan Hoo @ Albert Au Wan Ho

CC: Claims Manager

AIG Asia Pacific Insurance PL Motor Claims Department

74 Shenton Way, #07-16 AIG Building

Singapore 079120



CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Au Wan Hoo @ Albert Au Wan Ho : 07 Aug 2017 To 08 Aug 2018

Vehicle No. Policy No.

: SKK60428 : 2100348419-04

Period of Insurance Engine No.

: 1AZE273570

Endorsement No.

Chassis No.

: MR053BK5104014743

Issued Date

: 31 Jul 2017

ABOUT THE COVER

Make/Model

: TOYOTA NEW CAMRY 2.0

Engine Capacity/Tonnage: 1,998.00 CC

Sum Insured : Market Value Off Peak Car : No

First Year of Registration : 2013

Insuring with COE/PARF : Yes

Driver Restriction : NA Person or Classes of Persons Entitled to Drive*:

a) The Policytocker b) Any over parties who is driving on the Policytocker's process with his/her permission. This Policy will incommitty me Policytocker or any authorized draver only if treatms meets the specified age consistent.

You have to pay on addressed own of \$2,000 as "Young and/or incorporationed Dever Excess" ("YOR") if You are or Your Authorised Dever (named or uncorrect) to under the age of 23 addresses have 8 years' diving experience.

Age Condition

: All Age Condition

Limitation as to use' :

Use only for social, acrossic and pleasure graposes and for the Policyholder's humanss. This Policy does not obver use for him or tenant, draming before, draming less, racing, page-making, reliablely that or appendicular and pleasure graposes and goods other than semples in commercial policy for the policyholder's humanss.

Loss of Use (16 days) 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Add (Cop. 188) and Section 95 of the Read Transport Act, 1987 (Malaysia), are not to 60 included under these headings

Section 1 Fire - S0 Own Damage - \$2000 Theft - \$0 Flood Cover - \$0

Windspreen: \$100

Named Driver and Excess (www.expecutio)

Au Wan Hoo @ Albert Au Won Ho - \$2000 (Own Demage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Central AIG Authorised Repairers (For claims: related repairs)
Any accessor repairs to the Vehicle must be certed out by one of our Authorised Repairers. Within the Biss. 3 years of the first registration of the Vehicle must be certed out by one of our Authorised Repairers. Within the Biss. 3 years of the Vehicle must be the Service of the Service of the Vehicle must be certed out by one of our Authorised Repairers or service out to the Biss Agent's another access of the Biss. 3 years of the Vehicle must be serviced out to the Biss Agent and access of the Biss Agent and Authorised Repairers, please cented our Polyton access rememberly hother at 465 5336 5200. Alternatively, You may refer to AIG widely with a grown agreement and access and the Biss Agent and Authorised Repairers.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS SANK LTD

Whe haveby certify that the policy to which this Certificate of insurance values is liqued in accordance with the policies of the Motor Values (Three Party Risks and Compensation) Act (Cap. 1991, Part IV of your Royal Transport Act. 1907 (Malayris) and Sales Values (Three Party Risks) and Sales Values (Three Party Risks) Rules. 1909 (Malayris)

0030210000


AIG ASIA PACIFIC INSURANCE PL 78 SHENTON WAY 207-18 AIG BUILDING

SINGAPORE 079120

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AlG Asla Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

78 Chamber Aug 827 15 ACC 25, dug 5079170] 1 4.5 5415 2800] 2 405 6415 2482 (www.c.100 1.00



REPUBLIC OF SINGAPORE IDENTITY CARD NO. SQ047392H



14234

AU WAN HOO @ALBERT AU WAN HO



收运录 CHENESE
CONSTRUCT
29-09-19-29
Gayory IR-INI
MORG KONG

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)

PASS DATE

Closs 3 Melor Cars and Meter Tractors the weight of Melor Cars and Meter Tractors the weight of Melograms

№5₩ S0047392H

893500.0 (34 at state 0+ 28-05-1993

APT BLK 9 JALAN RUMAH TRIGGI #14-457 SINGAPORE 160000 50047392H 01,027

01,02/2014



Accident Photo



BMW did not stop at the white line. The white line was clearly shown in another photo.

This is a can which passed by after the accident. It has no relevance to the accident.

Accident Photo

Photo taken on 27 January 2018 one day after the accident

- A indicates the position of the Camry SICK60428
 B indicates the position of the BMW SCL7873C
 C indicates the lot Camry was backing into
 D indicates the white line BMW crossed without stopping



Accident Photo

