

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 01 February 2018

Third Party Insurer: AIG

Vehicle No: EG8383X

Third Party Veh No: SLP1706P

Model: JAGUAR XJ - 3.0 DIESEL

Date of Accident: 28/01/2018

Chassis: SAJAC2223BNV14146

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	FRONT DOOR LH	<i>Del/warp</i>	\$3,850.00 ✓
1	FRONT DOOR WEATHERSTRIP LH	<i>rm</i>	\$253.00 <i>508m</i>
1	FRONT DOOR MECHANISM LOCK LH	<i>n</i>	\$520.00 X
1	FRONT DOOR LOWER RUBBER SEAL LH		\$215.00 ?
1	FRONT DOOR SIDE RUBBER SEAL VERTICAL LH		\$189.00 ?
10	FRONT DOOR INNER TRIM BOARD CLIP LH	\$8.90	\$89.00 ?
1	REAR DOOR LH	<i>R</i>	\$3,990.00 ✓
1	REAR DOOR WEATHERSTRIP LH	<i>rm</i>	\$336.00 <i>508m</i>
1	REAR DOOR LOWER RUBBER SEAL LH		\$215.00 ?
1	REAR DOOR SIDE RUBBER SEAL VERTICAL LH		\$189.00 ?
10	REAR DOOR INNER TRIM BOARD CLIP LH	\$8.90	\$89.00 ?
1	REAR FENDER LH	<i>R</i>	\$3,790.00 X
1	REAR FENDER INNER SHIELD LH	<i>rm</i>	\$536.00 X
12	REAR FENDER INNER SHIELD CLIP LH	\$8.90	\$106.80 X
1	ROCKER SIDE SKIRTING LH	<i>rm</i>	\$1,840.00 ✓
14	ROCKER SIDE SKIRTING CLIP LH	\$7.50	\$105.00 ✓
3	ROCKER SIDE SKIRTING RETAINER LH	\$119.00	\$357.00 ?
1	REAR BUMPER	<i>R</i>	\$3,942.00 X
18	REAR BUMPER CLIP	\$8.90	\$160.20 X
1	REAR BUMPER SIDE BRACKET LH	<i>R</i>	\$255.00 X
1	REAR 19" SPORT RIM LH	<i>Del</i>	\$2,690.00 ✓
SUB TOTAL			\$23,717.00
Less 10%			-\$2,371.70
PARTS TOTAL			\$21,345.30

*Not authorized
L1Pup 8?*

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR LH 275/40 ZR 19 (105Y) TYRE		<i>rm</i> \$540.00 X
LKK Auto Consultants hence notify the Repairer of the following:			
• To resurvey before/after spray painting			
• To display damaged part(s) during resurvey			
• Parts prices are subject to confirmation			
• Third party survey is on a "Without Prejudice" basis			
• No illegal modification(s) is allowed			
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
Acknowledged by Repairer			
Signature:			
Date:			

6 days

6 days

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 01 February 2018

Third Party Insurer: AIG

Vehicle No: EG8383X

Third Party Veh No: SLP1706P

Model: JAGUAR XJ ~ 3.0 DIESEL

Date of Accident: 28/01/2018

Chassis: SAJAC2223BNV14146

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$2,100.00	1000
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$1,800.00	1250
TO TUFF KOTE / ANTI-RUST	\$90.00	nn X
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	\$350.00	?
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$80.00	nn X
TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED WHEEL ALIGNMENT	\$60.00	✓
TO DISMANTLE & REINSTALL FRONT LH DOOR INNER COMPONENT MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION	\$350.00	1200
TO DISMANTLE & REINSTALL REAR LH DOOR INNER COMPONENT MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION	\$350.00	1200
TO CHECK WIRING WITH TEST	\$120.00	400
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH ALL THE ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$280.00	nn X
TO REMOVE AND REINSTALL REAR LH FENDER QUARTER GLASS PERFORM AND WATER LEAK TEST	\$100.00	nn X

LABOUR TOTAL \$5,680.00

WINSON

TOTAL \$27,565.30