

INS. CASE OWNER:

Sunderi

CC 4 / III1800

1775

K uaz

LKK:
IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

20-01-18

Date / Time:

29/01/18

Registered in Merimen:

30/01/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHO 66832

Name of Insured:

CPL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

29-01-18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Ang Tien Hwat

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

M41 8010876

Policy No.:

M410001X

Make / Model:

M-BENZ B220

Place of Accident:

TPE 7 EXT OF CTE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SFX 70835



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hui Yang



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

2/2
114SFX 70835 / HUI / (P17013382) / S2 ; DOA: 29/01/18
SHO 66832 - X

OI car ended to TP.

RECEIVED 04 JUN 2018

RECEIVED 25 JUN 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOI:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

20/06/18

Confirm with

bel

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost:

SS

3103.00

Loss of Rental (LOR):

SS

535.00

(

5

days)

x 100 + GST

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

7.49

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

3645.49

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

3645.49

Name 1:

HUI YANG MOTOR PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

30/01/2018

SFX 7083S

08 05

Estimated Cost

01 TRS TRS CO RES/EM/INV M

To: Hui Yang Motor

SFX 7083S

Hui Yang Motor

Blk 176 Sin Ming Drive #04-02

Phone No

Phone No

Phone No


Phone No

Phone No

Phone No

Policy Condition

Remarks: The van had commenced its repair at the time of inspection.



Ball or Metal Value

040 Accident Report Consistent? Yes or No

041 FR Rep Consistent? Yes or No

042 Rep Consistent? Yes or No

043 Rep Consistent? Yes or No

044 Rep Consistent? Yes or No

045 Rep Consistent? Yes or No

046 Rep Consistent? Yes or No

047 Rep Consistent? Yes or No

31/1 File pass to Catherine

US - 29001- (Red: \$ 3100.95 / 52%)

Vehicle

Make/Model/Year/Color/Type/Engine/Transmission

Make/Model/Year/Color/Type/Engine/Transmission

Make

Toyota

1598

Model

M. Gou

Year

214220

Engine

Color

MR0538EC107

Gen. Code/Body/Panel/Door/Window

Steering/Brake/Jammed/Leaked/Burnt/Other

Brake/Brake/Jammed/Leaked/Burnt/Other

Mod. Nbr. S/N. VIN. STC. etc.

Tyre Size

185/70R14

BS/DUN/BXNOVA BY BS WZA MID OHTSU/PR SUM

TOYO/YOKO

1-1/14

Front

Rear

Left

Right

Survey Notes

Des of Damages: FR, REAR, LHS, RHS, U/C, Roof/Top

The U/C, Chassis/frame, Body Structure affected due to collision

Copy This Report

Final Report

Final Report

Days Of Repair

Resurvey No. of This

Copy To

Personnel

Copy To

Personnel

Add Web

File No

File No

File No

File No

File No

Report Form

Report Form

Report Form



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18001775/Kua3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 30-01-2018	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh. SHD 6683Z	Veh. Inspected	SFX 7083S
	Policy No.	Coverage (\$)	0.00
	Claim No.	Excess (\$)	0.00
	Assign From	Assign Date	30/01/2018
2. Vehicle Particulars & Condition			
	Make & Model	c.c	0
	Engine No. HIDDEN	Year of Reg.	
	Chassis No.	Colour	
	Odometer -	Steering	
	Brakes	Modification	
	General		
3. Conditions of Tyres			
	Size	Make	Balance
	R/H Front Tyre		mm
	L/H Front Tyre		mm
	R/H Rear Tyre		mm
	L/H Rear Tyre		mm
4. Description of Damages			
5. General Information			
	Accident Date 29/01/2018	Inspection Date	30/01/2018
	Survey held at HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

辉 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

29/01/2018

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA ALITS - SFX7083S

1pc	rear boot cover
1pc	rear boot cover "TOYOTA" logo
1pc	rear boot cover "COROLLA" emblem
1pc	rear boot cover "ALTIS" emblem
1pc	rear boot cover outer garnish
2pcs	rear boot cover reflector @\$172.45
2pcs	rear boot cover hinge @\$132.10
1pc	rear boot cover inner lock
1pc	rear boot cover inner rubber
2pcs	rear taillamp @\$281.90 <i>n/s Bux</i>
2pcs	rear taillamp lower panel @\$80.75
4 8pcs	rear taillamp lower panel clip @\$12.90
1pc	rear taillamp LH panel
1pc	rear bumper
2pcs	rear bumper side retainer @\$132.10
1pc	rear end panel
1pc	rear end panel inner garnish

less 25%

1set rear reverse sensor

wiring
tuffkote
spray painting
labour charges
Total

Bur	\$	781.10	✓
ru	\$	43.10	—
ru	\$	43.90	—
ru	\$	41.10	—
ru	\$	281.10	X
ru	\$	344.90	X
ru	\$	264.20	X
ru	\$	161.60	—
66.125N Nulvix	\$	132.25	50% <i>n</i>
clsm	\$	563.80	X
NISAu	\$	161.50	LT
ru	\$	103.20	LT
ru	\$	80.70	X
Bur	\$	374.45	—
n/s Dir	\$	264.20	LT
Ry	\$	781.90	—
net	\$	191.60	—
	\$	4,614.60	
	\$	1,153.65	
	\$	3,460.95	

Shan s.nett \$ 280.00 *200%*n**

\$	80.00	<i>20%</i>
\$	80.00	<i>60%</i>
\$	1,000.00	<i>700%</i>
\$	1,100.00	<i>600%</i>
\$	6,000.95	



LKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledges to Receiver

Signature:

Date:

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

29/01/2018

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA ALITS - SFX7083S

1pc	rear boot cover
1pc	rear boot cover "TOYOTA" logo
1pc	rear boot cover "COROLLA" emblem
1pc	rear boot cover "ALTIS" emblem
1pc	rear boot cover outer garnish
2pcs	rear boot cover reflector @\$172.45
2pcs	rear boot cover hinge @\$132.10
1pc	rear boot cover inner lock
1pc	rear boot cover inner rubber
2pcs	rear taillamp @\$281.90 <i>NIS ?</i>
2pcs	rear taillamp lower panel @\$80.75
4 8 pcs	rear taillamp lower panel clip @\$12.90
1pc	rear taillamp LH panel
1pc	rear bumper
2pcs	rear bumper side retainer @\$132.10
1pc	rear end panel
1pc	rear end panel inner garnish

less 25%

1set rear reverse sensor

wiring
tuffkote
spray painting
labour charges
Total

<i>Bu</i>	\$ 781.10	✓
<i>na</i>	\$ 43.10	—
<i>na</i>	\$ 43.90	—
<i>na</i>	\$ 41.10	—
<i>in</i>	\$ 281.10	X
<i>in</i>	\$ 344.90	X
<i>na</i>	\$ 264.20	X
<i>na</i>	\$ 161.60	—
<i>na</i>	\$ 132.25	<i>50%</i>
<i>clsm</i>	\$ 563.80	
<i>NIS Bu</i>	\$ 161.50	<i>LT</i>
<i>na</i>	\$ 103.20	<i>LT</i>
<i>na</i>	\$ 80.70	X
<i>Bu</i>	\$ 374.45	✓
<i>NIS Di</i>	\$ 264.20	<i>LT</i>
<i>na</i>	\$ 781.90	✓
<i>na</i>	\$ 191.60	✓
	\$ 4,614.60	
	\$ 1,153.65	
	\$ 3,460.95	

Shon s.nett \$ 280.00 *200%*

wiring	\$ 80.00	<i>20%</i>
tuffkote	\$ 80.00	<i>60%</i>
spray painting	\$ 1,000.00	<i>700%</i>
labour charges	\$ 1,100.00	<i>600%</i>
Total	\$ 6,000.95	



LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 29 January 2018 5:14 PM
To: Hui Yang Motor; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Sundari Nagarajan - III
Subject: RE: TP Claim for SFX7083S against SHD6683Z
Attachments: SKM_C28718012913100.pdf

5.42pm @ 29/01/2018
person @ Sandra
vehicle In
amndge on 30/01/2018

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SFX7083S and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]
Sent: 29 January, 2018 2:53 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: TP Claim for SFX7083S against SHD6683Z
Importance: High

Hi,

Our choice of surveyor will be LKK Auto Consultants Pte Ltd.

Thank you & Regards,
Sandra

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, January 29, 2018 1:49 PM
To: Hui Yang Motor
Subject: RE: TP Claim for SFX7083S against SHD6683Z

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]

Sent: 29 January, 2018 1:08 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: TP Claim for SFX7083S against SHD6683Z

Importance: High

Hi,

Please refer to the attached doc.

Thank you & Regards,
Sandra

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this

message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

輝陽 汽車有限公司

HUI YANG MOTOR PTE LTD

Contact Add : SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

To:	India International Insurance Pte Ltd	From:	Hui Yang Motor Pte Ltd
Fax:	64514658	Pages:	7 Page (Including this page)
Phone:	64515752 (Bel)	Date:	January 29, 2018
Re:	3 rd Party Claim for SFX7083S against SHD6683Z	Time :	1.00 PM

Hi,

Accident involving SFX7083S & SHD6683Z along TPE towards CTE on 29/01/2018

Please refer to attached and help to arrange surveyor on 30/01/2018 (Tuesday).

Vehicle SFX7083S already in our workshop.

** Kindly acknowledge receipt of this email.*

Thank you

Regards
Bel Chew
Hp: 90473466

Print Received Message

This mail is associated with :

***SFX7083S (MCT18010876)**

[SHD6683Z]

TP

HYMS CAR LEASING PTE LTD

Jan 29 2018 6:00AM

[COMFORT TRANSPORTATION PTE LTD]

Hui Yang Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 08/06/2018 09:22 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$3645.49) - SFX7083S - Claim Handler: Sundari Nagarajan

Approved: 3645.49.

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

Date: 06/02/2018

India International Insurance Pte Ltd

Motor Claims Department

64 Cecil Street

#04-00 IOB Building

Singapore 049711

**RE: ACCIDENT INVOLVING SFX7083S & SHD6683Z ON 29-01-2018
ALONG TPE TWDS CTE**

SETTLEMENT OF OUR CLAIM FOR SFX7083S

Lump sum repair cost as recommended by surveyor (TP0286)	\$ 3,103.00
5 days Loss of Rental @ \$107.00 per day	\$ 535.00
LTA Insurance Enquiry	\$ 7.49
Total	<u>\$ 3,645.49</u>

**The above claim applies only to vehicle damage and expressly exclude all personal injuries and other consequential loss.*

Please let us have your reply soonest possible, thank you.

Best Regards,

Marco Neo

HUI YANG MOTOR PTE LTD

DID: 64515752

Fax: 64514658

email: hui_yang_motor@hotmail.com

AUTHORIZATION LETTER

TO WHOM IT MAY CONCERN

I/We, H/YMS Car Leasing Pte Ltd hereby declare and agree to use the address of **Hui Yang Motor Pte Ltd**, that is at Blk 176 Sin Ming Drive, #04-02 Sin Ming Autocare Singapore 575721 in all my/our correspondences with any party in connection with my/our claim arising from an accident involving my/our motor vehicle registration number SFX 7083S and other vehicles registration number SHD 6632 along TPE TWDS CTE on 29-1-2018

I/We, further grant authority to Messrs **Hui Yang Motor Pte Ltd** or any of their representatives to open all my/our letters and to negotiate my/our claim on my/our behalf.

I/We wish to inform you that you could issue the cheque payment in favour of my/our repairer Messrs **Hui Yang Motor Pte Ltd**.



.....
Signature of registered owner and/or Company's stamp

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18010876
Claimant Ref: SFX7083S

We/I, Hui Yang Motor Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 3,103.00 (repair cost); S\$ 535.00 (loss of ~~use~~/rental); S\$ 7.49 (search fee); vehicle no. SFX7083S that was damaged pursuant to the accident which occurred on 29/01/2018 (date) at TPE TOWARDS CTE (location) involving vehicle no. SHD6683Z (insured vehicle). This is pursuant to the inspection conducted on 30/01/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner HYMS CAR LEASOMG PTE LTD ("the third party claimant") of vehicle no. SFX7083S to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SFX7083S (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 3,645.49 to Hui Yang Motor Pte Ltd.

Dated this 20 day of June 2018

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

Hui Yang Motor Pte Ltd

NRIC:

201629438M

Address:

176 Sin Ming Drive
#04-02, S(515PI)

Nationality:

Occupation:

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

LKK Auto Consultants Pte Ltd

NRIC:

199607198R

Address:

Blk 51, Paya Ubi Industrial Park,
Ubi Avenue 1, #02-25 | S(408933)

Nationality:

Occupation:

HUI YANG MOTOR PTE LTD

Bill To:

India International Insurance Pte Ltd
Motor Claims Department
64 Cecil Street
#04-00 IOB Building
Singapore 049711

TAX INVOICE

TP Claim Invoice No: TP0286
Bill Date: 06/02/2018

	Description	Amount
	Date of Accident : 29/01/2018 Owner : HYMS CAR LEASING PTE LTD Vehicle No : <u>SFX7083S</u> Make & Model : <u>TOYOTA ALITS</u>	
	<u>Lump Sum repair cost as recommended by surveyor</u>	\$ 2,900.00
	Sub-Total :	\$ 2,900.00
	Add 7% GST :	\$ 203.00
	Total Amount SGD :	\$ 3,103.00

Reg No.:201629438M

GST No:201629438M

HUI YANG MOTOR PTE LTD



Authorised Signature

Hui Yang Motor Pte Ltd

Sin Ming Autocare Blk 176 Sin Ming Drive

#04-02 Singapore 575721

Email: hui_yang_motor@hotmail.com

H/P: 98625891 Office: 64515752 Fax : 64514658

RENT RECEIPT

No.: RC18-08

Date: 6/2/2018

收到
Received from Hui Yang Motor Pte Ltd

支付大銀
the sum of Dollars Five hundred and thirty-five only

为租金
being the rent of SJL 5080B (100X 5 days) + 7% GST R15: 13490

日期从
due for the period from 29/1/18 至 3/2/18

预先支付
payable in advance.

\$ 535.00

Cash / Cheque No:

Important: No subletting of the above premise or any part thereof, or assigning the tenancy of the premise is allowed without the written consent of the landlord.

Signature of Landlord




HYMS CAR LEASING PTE LTD

Blk 176 Sin Ming Drive #04-02 Sin Ming AutoCare Singapore 575721

Hp: 8333 6725 Fax 6451 4658

RENTAL TERMS AND CONDITIONS

No.: 13490

NAME <u>Hui Yang Motor Pte Ltd</u>			REG. NO. <u>SJC 8080</u>	CAR MAKE <u>HONDA CIVIC 1.6</u>																																																
ADDRESS <u>Blk 176 Sin Ming Drive #04-02</u>			KM OUT	DATE & TIME OUT <u>29/11/2018 5:45pm</u>																																																
<u>Sin Ming AutoCare Singapore 575721</u>			KM IN	DATE & TIME IN <u>3/2/2018 11am</u>																																																
TEL <u>HP 97568413</u>			KM DRIVEN	TIME USED																																																
NAMED DRIVER <u>Mui Weng Chang</u>																																																				
DRIVING LICENCE NO. <u>S14194862</u>	DATE OF EXPIRY	PLACE OF ISSUE	HOURS	@\$																																																
PASSPORT NO.	DATE OF ISSUE	PLACE OF ISSUE	<u>5</u> DAYS	@\$ <u>100</u>																																																
ADD NAMED DRIVER			WEEKS	@\$																																																
DRIVING LICENCE NO.	DATE OF EXPIRY	PLACE OF ISSUE	MONTHS	@\$																																																
PASSPORT NO.	DATE OF ISSUE	PLACE OF ISSUE	BY INITIALING, RENTER AGREES TO PAY ADD FEE FOR COLLISION DAMAGES WAIVER (C.D.W.)																																																	
REMARKS  <p>THIS VEHICLE IS USE WITHIN SINGAPORE ONLY OUR INSURANCE DOES NOT COVER IN MALAYSIA</p>			SUB-TOTAL	\$ <u>500</u>																																																
			<u>7%</u> GST	\$ <u>35</u>																																																
			TOTAL RENTAL	\$ <u>535</u>																																																
			DELIVERY FEE																																																	
			COLLECTION FEE																																																	
<table border="1"> <thead> <tr> <th>Vehicle Number</th> <th>Date From</th> <th>Date To</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td></td> <td>Replacement</td> </tr> <tr> <td></td> <td></td> <td></td> <td>Replacement</td> </tr> <tr> <td>1st Party Excess</td> <td><u>\$1500/130</u></td> <td></td> <td></td> </tr> <tr> <td>3rd Party Excess</td> <td><u>\$1500/130</u></td> <td></td> <td></td> </tr> </tbody> </table>			Vehicle Number	Date From	Date To	Remarks				Replacement				Replacement	1st Party Excess	<u>\$1500/130</u>			3rd Party Excess	<u>\$1500/130</u>			<table border="1"> <thead> <tr> <th>PER DAY \$</th> <th>PER WEEK \$</th> <th>PER MONTH \$</th> </tr> </thead> <tbody> <tr> <td colspan="3">BY INITIALING, RENTER AGREES TO PAY ADD FEE FOR PERSONAL ACCIDENT INSURANCE (P.A.I.)</td> </tr> <tr> <td colspan="3"> <table border="1"> <thead> <tr> <th>PER DAY \$</th> <th>PER WEEK \$</th> <th>PER MONTH \$</th> </tr> </thead> <tbody> <tr> <td colspan="3">PREPAYMENT</td> </tr> <tr> <td colspan="3">CHECK</td> </tr> <tr> <td colspan="3">CASH</td> </tr> <tr> <td colspan="3">RECEIPT NO.</td> </tr> <tr> <td colspan="3">AMOUNT DUE/ REFUND</td> </tr> </tbody> </table> </td> </tr> </tbody> </table>			PER DAY \$	PER WEEK \$	PER MONTH \$	BY INITIALING, RENTER AGREES TO PAY ADD FEE FOR PERSONAL ACCIDENT INSURANCE (P.A.I.)			<table border="1"> <thead> <tr> <th>PER DAY \$</th> <th>PER WEEK \$</th> <th>PER MONTH \$</th> </tr> </thead> <tbody> <tr> <td colspan="3">PREPAYMENT</td> </tr> <tr> <td colspan="3">CHECK</td> </tr> <tr> <td colspan="3">CASH</td> </tr> <tr> <td colspan="3">RECEIPT NO.</td> </tr> <tr> <td colspan="3">AMOUNT DUE/ REFUND</td> </tr> </tbody> </table>			PER DAY \$	PER WEEK \$	PER MONTH \$	PREPAYMENT			CHECK			CASH			RECEIPT NO.			AMOUNT DUE/ REFUND		
Vehicle Number	Date From	Date To	Remarks																																																	
			Replacement																																																	
			Replacement																																																	
1st Party Excess	<u>\$1500/130</u>																																																			
3rd Party Excess	<u>\$1500/130</u>																																																			
PER DAY \$	PER WEEK \$	PER MONTH \$																																																		
BY INITIALING, RENTER AGREES TO PAY ADD FEE FOR PERSONAL ACCIDENT INSURANCE (P.A.I.)																																																				
<table border="1"> <thead> <tr> <th>PER DAY \$</th> <th>PER WEEK \$</th> <th>PER MONTH \$</th> </tr> </thead> <tbody> <tr> <td colspan="3">PREPAYMENT</td> </tr> <tr> <td colspan="3">CHECK</td> </tr> <tr> <td colspan="3">CASH</td> </tr> <tr> <td colspan="3">RECEIPT NO.</td> </tr> <tr> <td colspan="3">AMOUNT DUE/ REFUND</td> </tr> </tbody> </table>			PER DAY \$	PER WEEK \$	PER MONTH \$	PREPAYMENT			CHECK			CASH			RECEIPT NO.			AMOUNT DUE/ REFUND																																		
PER DAY \$	PER WEEK \$	PER MONTH \$																																																		
PREPAYMENT																																																				
CHECK																																																				
CASH																																																				
RECEIPT NO.																																																				
AMOUNT DUE/ REFUND																																																				
FORM OF PAYMENT IN ADVANCE <input type="checkbox"/> CASH <input type="checkbox"/> BILL <input type="checkbox"/> CHARGE CLUB <input type="checkbox"/> CHEQUE NO. <input type="checkbox"/>																																																				
I HAVE READ THE TERMS AND CONDITIONS ON BOTH SIDES OF THIS RENTAL AGREEMENT AND AGREE THEREOF. I UNDERTAKE NOT TO USE OR LET OTHERS USE THE VEHICLE TO CARRYOUT ANY ILLEGAL OR CRIMINAL ACTS INCLUDING CARRYING OF DUTY UNPAID GOODS ESPECIALLY CIGARETTES.																																																				
SIGNED BY THE PARTIES HERETO ON THE _____ DAY OF _____																																																				
																																																				
OWNER			RENTER'S/DRIVER'S SIGNATURE																																																	

HYMS CAR LEASING PTE LTD

BLK 176 SIN MING DRIVE
#04-02 AUTOCARE
SINGAPORE 575721
HP : 8333 6725 FAX : 6451 4658
REG NO : 201320561K
GST REGISTER NO: 201320561K

TAX INVOICE

BILL TO: HUIYANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE
SINGAPORE 575721

TAX INVOICE NO : LT022018-018
DATE : 06/02/2018
REFERENCE NO : SFX7083S

NO.	DESCRIPTION	AMOUNT
	AGREEMENT NO : 13490 HIRER'S NAME : MUI WENG KHANG REGISTRATION NO : SJC5080B MAKE : HONDA CIVIC DURATION : 29/01/18 - 03/02/18 PER DAY \$100X 5 DAYS	\$500.00
	SUB TOTAL	\$500.00
	7% GST	\$35.00
	TOTAL AMOUNT	\$535.00

Payment:

- A. For Cheque Payment, Please Crossed And Issue to "HYMS CAR LEASING PTE LTD".
Please Indicate Vehicle Number On The Back Of The Cheque And Mail The Cheque To:
HYMS CAR LEASING PTE LTD
Blk 176 Sin Ming Drive
#04-02 Sin Ming AutoCare
Singapore 575721
- B. For Internet Banking Transfer, Please Indicate Vehicle Number And Transfer To:
Bank OCBC Current Account 531-756864-001



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 29 Jan 2018 / 11:16:45

Receipt Date/Time : 29 Jan 2018 / 11:16:45

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180129-000542

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SHD6683Z

As at 29 Jan 2018/06:50:00

Insurance Co: INDIA INT'L INS PTE LTD

1 Insurance Enquiry - SHD6683Z

Enquiry Fee

20180129110342388458

7.00 0.49 7.49

Sub-Total 7.00 0.49 7.49

Total Before Rounding 7.00 0.49 7.49

Rounding Difference 0.04

Total Amount Payable 7.45

Paid By

xxxxxxxxxxxx7046

Credit Card:

Visa/MasterCard

7.45

Total 7.45

Cash Change 0.00

Tendered Amount 7.45

Excess Refundable Amount 0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Jan 2018 Edit Reg		29 Jan 2018 00:00 Edit Adj Rpt	S\$2,900.00 Edit Estimates	S\$2,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	HYMS CAR LEASING PTE LTD , Co. Reg. No.: 201320561K								
Vehicle Reg. No.:	SFX7083S	Date of Loss:	29/01/2018 06:00 - :59 [149 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18010876	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHD6683Z	Policy No. (Claimant):	5082577969-01						
		Excess:							
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 08/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (08/06/2018): Alert - Adj Mandate Approved (S\$3645.49) - SFX7083S - Claim Handler: Sundari Nag... III_SG (02/02/2018): Alert - Adj Mandate Approved (S\$0.00) - SFX7083S - Claim Handler: Sundari Nagara... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFX7083S (MCT18010876)**
[SHD6683Z]
TP
HYMS CAR LEASING PTE LTD
Jan 29 2018 6:00AM
[COMFORT TRANSPORTATION PTE LTD]
Hui Yang Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
2	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
3	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
4	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
5	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
6	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
7	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
8	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
9	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
10	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
11	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
12	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
13	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
14	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
15	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
16	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
17	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
18	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
19	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
20	07/06/18 17:37	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/01/18 09:52	ACKNOWLEDGEMENT EMAIL TO III DD 29.01.2018.pdf	Load PDF	
2	30/01/18 09:52	NOTIFICATION FROM WORKSHOP + TP ESTIMATE + TP GIA REPORT	Load PDF	
3	02/02/18 10:05	TP ESTIMATE - MARKED	Load PDF	
4	04/06/18 15:07	WORKSHOP INVOICE	Load PDF	
5	04/06/18 15:07	RENTAL RECEIPT	Load PDF	
6	04/06/18 15:07	LTA SEARCH	Load PDF	
7	04/06/18 15:07	LOD	Load PDF	
8	26/06/18 14:57	DISCHARGE VOUCHER	Load PDF	
9	26/06/18 14:57	AUTHORISATION TO ACT FORM	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	31/01/18 08:44	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note:

Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18001775/KUA3Q2

Date: 26/06/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SFX7083S Insured Vehicle No: SHD6683Z
 Date of Loss: 29/01/2018 Nature of Claim: TP Claim No: MCT18010876

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFX7083S
 Make & Model: TOYOTA COROLLA, 1.6 (M) Engine No: 3ZZ4496370
 Reg. Date: 18/08/2005 (Man. Year: 2005) Chassis No: MR053ZEC107095084
 Colour: Metallic Gold Odometer: 214220 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14
 Front Left Side: HIFLY 6 mm Rear Left Side: HIFLY 5 mm
 Front Right Side: HIFLY 6 mm Rear Right Side: HIFLY 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,740.95	2,278.52	1,462.43	39.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,380.00	880.00	38.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,000.95	3,658.52	2,342.43	39.03
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	6,000.95	2,900.00	3,100.95	51.67
+ GST 7.00/7.00% (S\$)	420.07	203.00	217.07	51.67
Nett Amount (S\$)	6,421.02	3,103.00	3,318.02	51.67
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,645.49		

INSPECTION

Date of Assignment: 29/01/2018
 Date Inspected: 30/01/2018 Inspected At: Hui Yang Motor Pte Ltd (HQ)
 176 Sin Ming Drive #04-02, Sin Ming

AutoCare
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jun 2018)
Parts:	143	TOYOTA COROLLA 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFX7083S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT COVER	Buckled	781.10 FL	*781.10 FL
2	1	*REAR BOOT COVER TOYOTA LOGO	Necessary	43.10 FL	*43.10 FL
3	1	*REAR BOOT COVER COROLLA EMBLEM	Necessary	43.90 FL	*43.90 FL
4	1	*REAR BOOT COVER ALTIS EMBLEM	Necessary	41.10 FL	*41.10 FL
5	1	*REAR BOOT COVER OUTER GARNISH	Serviceable	281.10 FL	*- FL
6	2	*REAR BOOT COVER REFLECTOR	Serviceable	344.90 FL	*- FL
7	2	*REAR BOOT COVER HINGE	Repair	264.20 FL	*- FL
8	1	*REAR BOOT COVER INNER LOCK	Dented	161.60 FL	*161.60 FL
9	1	*REAR BOOT COVER INNER RUBBER (50%)	Dented / Distorted	99.19 FS	*66.12 FS
10	2	*REAR TAILLAMP	Serviceable	563.80 FL	*- FL
11	1	*REAR TAILLAMP LOWER PANEL	N/S Buckled	161.50 FL	*80.75 FL
12	8	*REAR TAILLAMP LOWER PANEL CLIP	Necessary (4 PCS ONLY)	103.20 FL	*51.60 FL
13	1	*REAR TAILLAMP LH PANEL	Repair	80.70 FL	*- FL
14	1	*REAR BUMPER	Buckled	374.45 FL	*374.45 FL
15	1	*REAR BUMPER SIDE RETAINER	N/S Distorted	264.20 FL	*132.10 FL
16	1	*REAR END PANEL	Bent	781.90 FL	*781.90 FL
17	1	*REAR END PANEL INNER GARNISH	Dented	191.60 FL	*191.60 FL
18	1	*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,861.54	2,949.32
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,120.59	670.80
Total Parts (\$\$)	3,740.95	2,278.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRING	New	80.00	20.00
2	TUFFKOTE	New	80.00	60.00
3	SPRAY PAINTING	New	1,000.00	700.00
4	LABOUR CHARGES	New	1,100.00	600.00
Gross Labour Cost (S\$)			2,260.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >