

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

30/01/18
(Tuesday)

29/01/2018

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA ALITS - SFX7083S

1pc	rear boot cover
1pc	rear boot cover "TOYOTA" logo
1pc	rear boot cover "COROLLA" emblem
1pc	rear boot cover "ALTIS" emblem
1pc	rear boot cover outer garnish
2pcs	rear boot cover reflector @\$172.45
2pcs	rear boot cover hinge @\$132.10
1pc	rear boot cover inner lock
1pc	rear boot cover inner rubber
2pcs	rear taillamp @\$281.90 <i>NIS ?</i>
2pcs	rear taillamp lower panel @\$80.75
4 8 pcs	rear taillamp lower panel clip @\$12.90
1pc	rear taillamp LH panel
1pc	rear bumper
2pcs	rear bumper side retainer @\$132.10
1pc	rear end panel
1pc	rear end panel inner garnish

less 25%

1set rear reverse sensor

wiring
tuffkote
spray painting
labour charges
Total

Bu	\$	781.10	✓
re	\$	43.10	✓
re	\$	43.90	✓
re	\$	41.10	✓
re	\$	281.10	X
re	\$	344.90	X
re	\$	264.20	X
re	\$	161.60	✓
Nulkit	\$	132.25	50%a
clssn	\$	563.80	
NIS Bu	\$	161.50	LT
re	\$	103.20	✓
re	\$	80.70	X
Bu	\$	374.45	✓
NIS Dir	\$	264.20	✓
re	\$	781.90	✓
re	\$	191.60	✓
		\$ 4,614.60	
		\$ 1,153.65	
		\$ 3,460.95	

Shan s.nett \$ 280.00 *200%a*

	\$	80.00	20%
	\$	80.00	60%
	\$	1,000.00	700%
	\$	1,100.00	600%
		\$ 6,000.95	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: