

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Pre-assign / CCU / FTE

Registered in Merimen:



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :S\$

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

5

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:


1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

7320.

COPY SENT





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18001776/ea3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 30-01-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLU 1283R	Veh. Inspected	SLP 581M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	30/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/01/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401539W GST Reg. No. HQ-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Tampong Arang Road
East Coast Centre
Singapore 438190
Tel. 63190888 (AfterSales)
Fax. 63448773

318, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796401 (AfterSales)
64796404 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

30 JAN 2018

Estimate No. : b1 45693
Date Estimated : 29/01/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Zhang Cui Ping
310 Canberra Road
#10-133

Singapore 750310

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP581M	V725902	25/05/2017	116d	0

DESCRIPTION

To replace on front bumper & attachments including knock out dent area cause by accident

VALUE
850 2,550.00

Painting on front bumper assembly

434 1,038.00

To check electrical wiring systems at the front section for proper function

150. 177.00

To replace left headlight including program and conduct tests for proper function.

114 480 531.00

Sundries.

? 80.00

Total Labour 1: 4,376.00

DESCRIPTION

FRT BUMPER TOP MOUNT
LH CLOSED GRID (BASIS)
IMPACT ABSORBER TOP
GRILLE MIDDLE BOTTOM
GRILLE MIDDLE BOTTOM
FRT BUMPER LH INSERT
FRT BUMPER RH INSERT
FRT BUMPER PANEL PRIMED
SET PDC HOLDER FRONT
FRT BUMPER LOWER MOUNT
LH HEADLIGHT LED TECHNOLOGY

QTY	PRIC	VALUE
1	352.90	? 352.90
1	93.20	ent 93.20
1	41.40	? 41.40
1	115.50	? 115.50
1	115.50	? 115.50
1	31.35	? 31.35
1	31.35	? 31.35
1	767.00	de 767.00
1	22.55	? 22.55
1	124.90	? 124.90
1	2,208.40	? 2,208.40

Total Parts : 3,904.05

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401539W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190211 (AfterSales)
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190886 (AfterSales)
Fax: 62449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190028 (AfterSales)
63190033/239 (Motorrad)
64796431 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45693
Date Estimated : 29/01/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP581M	V725902	25/05/2017	116d	0

0

Client ID / 3rd Party / Uninsured / Direct Salesperson

Page No. _____ City No. _____

Date & Time 5/2/18

Examiner's Name Tanji

Examiner's ID 97495749

Approved By WP

Signature Tanji

Signature e.khanto

Signature 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	4,376.00
Parts	:	3,904.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	579.60
Grand Total	:	8,859.65

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Asher Sng (LKKAUTO)

From: Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>
Sent: Wednesday, 7 February 2018 11:43 AM
To: Asher Sng (LKKAUTO)
Cc: Vic (LKKAUTO)
Subject: RE: Your ref: 3021355098SG, ACCIDENT INVOLVING SLU 1283R (OI) & SLP 581M (TP) ON 28/01/2018

Hi Asher,

please proceed with rejection

thanks,

Saliha Syed Yusoff
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1917 | Fax +(65) 68357416

saliha.syed-yusoff@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Asher Sng (LKKAUTO) [mailto:AsherSng@lkkauto.com]
Sent: Tuesday, February 06, 2018 11:00 AM
To: Syed-Yusoff, Saliha
Cc: Vic (LKKAUTO)
Subject: Your ref: 3021355098SG, ACCIDENT INVOLVING SLU 1283R (OI) & SLP 581M (TP) ON 28/01/2018

Your ref: 3021355098SG
Our Ref: CC3/AIG18001776/ea3

Hi Saliha,

ACCIDENT INVOLVING SLU 1283R (OI) & SLP 581M (TP) ON 28/01/2018

We refer to the above matter.

TP reported that he was making a right turn at the control junction with a green light collided with OI that switch on hazard light and slowdown from opposite direction.

OI reported that he switch on his hazard light to alert other road user while traveling across the junction, TP from opposite direction make a right turn and collided into his vehicle .

Enclosed a copy of the third party video for your perusal.

The video clearly show that third party was making a right turn at the control junction without green arrow and did not give way to insured even after notice insured approaching the junction with an alert by switching on his hazard light and head light.

We are of the opinion that liability is not in third party's favour.

In view of the above, we are intending to reject TP claim.

Kindly let us have your advice / instruction if any.

Thank You.

Best Regards.

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Friday, 9 February 2018 2:19 PM
To: 'PBSP'; Mei Kwan (LKKAuto)
Cc: Admin A; Vic (LKKAuto); assignments
Subject: RE: REQ FOR DIRECT SETTLEMENT- SLP581M AND SLU1283R ON 28/01/2018 *** LKK REF: CC3/AIG18001776/ea3
Attachments: SLP 581M.MP4; OI SKETCH PLAN.pdf

Without Prejudice

Hi Caroline,

We refer to the above matter.

We attached here with a copy of our insured's accident statement for your easy reference.

Our principal has reiterated that the accident was caused due to the entire negligence of your client making a right turn at the control junction without green arrow and did not give way to our insured even after notice insured approaching the junction with an alert by switching on his hazard light and head light.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Friday, 9 February 2018 11:16 AM
To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: Re: REQ FOR DIRECT SETTLEMENT- SLP581M AND SLU1283R ON 28/01/2018 *** LKK REF: CC3/AIG18001776/ea3

Dear Asher,

Pleas let us have your up date for this case.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Sent: Monday, 5 February 2018 2:12:40 PM
To: PBSP; Mei Kwan (LKKAUTO)
Cc: 甯珺 @; Vic (LKKAUTO); assignments
Subject: RE: REQ FOR DIRECT SETTLEMENT- SLP581M AND SLU1283R ON 28/01/2018 *** LKK REF: CC3/AIG18001776/ea3

Without Prejudice

Hi Caroline,

We are still pending approval from our principal on the liability.

Shall revert to you upon approval.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]
Sent: Monday, 5 February 2018 2:01 PM
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: Re: REQ FOR DIRECT SETTLEMENT- SLP581M AND SLU1283R ON 28/01/2018 *** LKK REF: CC3/AIG18001776/ea3

Dear Asher

We have arranged for survey this morning at 10am.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Sent: Monday, 5 February 2018 1:54:46 PM
To: PBSP; Mei Kwan (LKKAUTO)
Cc: 甯珺 @; Vic (LKKAUTO); assignments
Subject: RE: REQ FOR DIRECT SETTLEMENT- SLP581M AND SLU1283R ON 28/01/2018 *** LKK REF: CC3/AIG18001776/ea3

Without Prejudice

Hi Caroline,

We refer to our tele-conversation.

Please kindly arrange your client to arrange for survey.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]
Sent: Monday, 5 February 2018 12:43 PM
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: Re: REQ FOR DIRECT SETTLEMENT- SLP581M AND SLU1283R ON 28/01/2018 *** LKK REF: CC3/AIG18001776/ea3

Dear Asher,

Have you seen the video link below?

Please advise for this.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Friday, 2 February 2018 1:28:45 PM
To: Asher Sng (LKKAUTO); Mei Kwan (LKKAUTO)
Cc: 甯珺 @; Vic (LKKAUTO); assignments
Subject: Re: REQ FOR DIRECT SETTLEMENT- SLP581M AND SLU1283R ON 28/01/2018 *** LKK REF: CC3/AIG18001776/ea3

Dear Asher

Please refer to video link below.

https://www.dropbox.com/s/jv5d10gy1ojx2uk/EVT_20180128_165358_2.avi?dl=0

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Sent: Friday, 2 February 2018 11:00:38 AM
To: PBSP; Mei Kwan (LKKAUTO)
Cc: 甯珺 @; Vic (LKKAUTO); assignments
Subject: RE: REQ FOR DIRECT SETTLEMENT- SLP581M AND SLU1283R ON 28/01/2018 *** LKK REF: CC3/AIG18001776/ea3

Without Prejudice

Hi Caroline,

We refer to the above matter.

Please be informed that liability is unclear for this matter. Our insured driver reported that your client make a right turn at the control junction and collided into our insured vehicle. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of video footage/witness statement/scene photos(if any) in order for us to look into the matter.

We shall revert upon hearing from you.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]

Sent: Friday, 2 February 2018 10:39 AM

To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <yicalpeh@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: Re: REQ FOR DIRECT SETTLEMENT- SLP581M AND SLU1283R ON 28/01/2018 *** LKK REF: CC3/AIG18001776/ea3

Dear Asher,

Please let us have your reply on liability.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

From: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>

Sent: Tuesday, 30 January 2018 10:04 AM

To: PBSP

Cc: 甯珺 @; Asher Sng (LKKAUTO); Vic (LKKAUTO); assignments

Subject: RE: REQ FOR DIRECT SETTLEMENT- SLP581M AND SLU1283R ON 28/01/2018 *** LKK REF: CC3/AIG18001776/ea3

Dear Caroline,

Thank you for your email.

Please be informed that we are currently **pending for our insured's report.**

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

Meanwhile, please arrange appointment for survey.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]

Sent: Tuesday, 30 January, 2018 9:48 AM

To: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Subject: REQ FOR DIRECT SETTLEMENT- SLP581M AND SLU1283R ON 28/01/2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

You are returning to a previous page. This page may be outdated.
Please click 'Refresh' to refresh the page.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Pending for Survey Report
Main	30 Jan 2018 Edit Reg		05 Feb 2018 00:00 Edit Adj Rpt	S\$2,794.20 Edit Estimates	S\$2,794.20 View Rpt		Cancel Case

Main	Reference	Claim Details	Documents	Show All
[Created by adjuster]				

CLAIM SUBFOLDER DETAILS			
Insured:	ONG CHIN HOWE, ID: S76391311		
Main Claimant:	ZHANG CUI PING, ID: S2616392G		
Vehicle Reg. No.:	SLP581M	Date of Loss:	28/01/2018 16:00 - :59
Claim Type:	TP / 3021355098SG	Policy/Cover Note No.:	1700074535
Vehicle Reg. No. (Insured):	SLU1283R	Policy No. (Claimant):	C0071979
Excess:			
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 08/02/2018]		
		View All	Compose Case Mail

ASSOCIATED MAIL RECEIVED			
There are no mail for this case.			

ALL ASSOCIATED TASKS						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By
No results.						

Claim Documents

*SLP581M (3021355098SG)
[SLU1283R]
TP
ZHANG CUI PING
Jan 28 2018 4:00PM
[ONG CHIN HOWE]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser v	
Video			1 per page v	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	07/02/18 11:41	Video - Accident from claimants veh	Load AVI	
Assessment Reports			1 per page v	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	31/01/18 14:33	Accident Statement <small>From: SC - Reg. No: SLU1283R, Claimant: ONG CHIN HOWE</small>	Load HTM	
Photos/Images			3 per page v	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
2	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
3	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
4	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
5	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
6	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
7	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
8	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
9	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
10	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
11	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
12	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
13	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
14	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
15	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
16	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
17	09/02/18 14:28	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
18	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
19	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
20	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
21	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
22	09/02/18 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page v	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/01/18 10:02	TP ESTIMATE	Load TIF	
2	30/01/18 10:02	TP GIA REPORT	Load PDF	
3	07/02/18 13:37	TP ESTIMATE - MARKED	Load PDF	
4	09/02/18 14:19	APPROVAL TO REJECT TP CLAIM	Load PDF	

5 | 09/02/18 14:19 | EMAIL WSP TO REJECT TP CLAIM

1 | Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18001776/T1EA3Q2

Date: 13/02/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700074535
 Claimant Vehicle No: SLP581M Insured Vehicle No: SLU1283R
 Date of Loss: 28/01/2018 Nature of Claim: TP Claim No: 3021355098SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP581M
 Make & Model: BMW 116D, 1.5 (A) Engine No: 37029866B37D15A
 Reg. Date: 25/05/2017 (Man. Year: 2017) Chassis No: WBA1V72090V725902
 Colour: Black Odometer: 30869 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,984.05	860.20	3,123.85	78.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,296.00	1,934.00	2,362.00	54.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,280.05	2,794.20	5,485.85	66.25
+ GST 7.00/7.00% (S\$)	579.60	195.59	384.01	66.25
Nett Amount (S\$)	8,859.65	2,989.79	5,869.86	66.25
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 05/02/2018
 Date Inspected: 05/02/2018 Inspected At: Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	*Check	80.00 FS	*- FS
2	1		*FRT BUMPER TOP MOUNT	*Check	352.90 FS	*- FS
3	1		*LH CLOSED GRID (BASIS)	Cut	93.20 FS	*93.20 FS
4	1		*IMPACT ABSORBER TOP	*Check	41.40 FS	*- FS
5	1		*GRILLE MIDDLE BOTTOM	*Check	115.50 FS	*- FS
6	1		*GRILLE MIDDLE BOTTOM	*Check	115.50 FS	*- FS
7	1		*FRT BUMPER LH INSERT	*Check	31.35 FS	*- FS
8	1		*FRT BUMPER RH INSERT	*Check	31.35 FS	*- FS
9	1		*FRT BUMPER PANEL PRIMED	Deformed	767.00 FS	*767.00 FS
10	1		*SET PDC HOLDER FRONT	*Check	22.55 FS	*- FS
11	1		*FRT BUMPER LOWER MOUNT	*Check	124.90 FS	*- FS
12	1		*LH HEADLIGHT LED TECHNOLOGY	*Check	2,208.40 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **3,984.05** **860.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE ON FRONT BUMPER & ATTACHMENTS INCLUDING KNOCK OUT DENT AREA CAUSE BY ACCIDENT	New	2,550.00	850.00
2	PAINTING ON FRONT BUMPER ASSEMBLY	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REPLACE LEFT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION	New	531.00	0.00
Gross Labour Cost (S\$)			4,296.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >