

Surrender

Tangjin

REF:

III

18571 Year 3 - ①

ASSIGNMENT

From: _____ Date: 02022018

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 6882L
at Workshop m/s Motorway Car Care
of 10914 Lower Delta Rd

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Tony

(Policy Condition)

3pm

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLW 6882L Yr Regn: 20/6 Dec.

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Samsung Tivoli 1.6 c.c. 1597.

Colour: Bronze A/C: Insured / Std / NI / NA

Sp. Reading: 27387 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KPT 3031 USG Plot 437.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S Rim / STD A/Rim or

Tyre Size: F: 205 / 60R16
R: 205 / 60R16

BS / DUN / EXNOVA / GY / FS LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexon.

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____

D.O.I. 2/2/12 @ 345pm

Survey held at Motorway Car Care

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Insp (\$☐ Weekend (\$