

meditation.

REF: CS3 / AXA17006196 / Gdls

Special Instruction:

45: ~~\$~~ 3000.00

From (Person): Chen Xinyou of AXA Date/Time: 26/12/2018
Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: PFA Automotive
Workshop: Twin car Automotive

OD/TP Re-inspection / Evaluation

To inspect Vehicle No: WNC 9233 Insured: SNC 5832Y

at Workshop m/s: Twin car Automotive Tel: 69420051

of 2 Kaki Bukit Ave 2 #01-17

Policy No: P1680520 Claim No: 00427047

Sum Insured: _____ Excess: _____


Make of Veh: _____ D.O.A. 24032017
(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 15/1/18 Confirmed with 2 Final Fig 2, 2 days (Red S 2 / 2 %; Original 8 days)

Date/Time: 15/7/18 Submit Final Fig 3300, 5 days (Red \$ 4700, 59%; Original 8 days)

Date/Time	Action/Instruction
	WNC 9233 - @3 / AXA 1700486 / Gh3mz SIC 5832Y - CC4 / AXA 17016519 / Klyg3
	DIA: 24032017 DIA: 23082017
	 13/2/2017

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 22 FEB 2010

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add

Transport

Photos

Others

Total

1) Date/Time 22/2/18 File Pass to TMH

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CS3/AXA17006196/Gqb-1	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 30-01-2018	
		Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 5832Y	Veh. Inspected	WNC 9233
Policy No.	P1680520	Coverage (\$)	0.00
Claim No.	C0427047	Excess (\$)	0.00
Assign From	MERIMEN (CHEN XINYOU)	Assign Date	26/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	24/03/2017	Inspection Date	30/01/2018
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(Pending for Payment)

Reinspection PRI PRI UPLOADED

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Mar 2017		29 Mar 2017 13:13		05 May 2017 17:23 S\$0.00 (S\$107.00)		Pending for Payment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Main Claimant:	CHIA JIUNN MING, Co. Reg. No.: -		
Vehicle Reg. No.:	WNC9233	Date of Loss:	24/03/2017 00:00 - :59
Claim Type:	TP / C0427047	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHC5832Y	Policy No. (Claimant):	
	Excess:	S\$5,000.00	
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Chen Xinyou - 6880 4269]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 07/04/2017]		
Driver/Custodian (Insured):	TAN KEE HUAT JOHNNY (49 / Male), NRIC: S1799825J, Tel: +6598581885		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

- AXA_SG (26/01/2018): Re: PRS FOR WNC 9233
- AXA_SG (26/01/2018): Reinspection - C0427047/P1680520

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Friday, 26 January, 2018 8:00 AM
To: sur@lkkauto.com; assignments@lkkauto.com
Subject: Reinspection - C0427047/P1680520

This mail is associated with :
***WNC9233 (C0427047)**
[SHC5832Y]
TP
CHIA JIUNN MING
Mar 24 2017 12:00AM
[TRANS-CAB SERVICES PTE LTD]
Twincar Automotive Pte Ltd

Dear Adjuster,

Please conduct reinspection. Details has been shared under documents.

Regards,
Chen Xinyou

[This mail is sent from a mailer account - do not reply to this email address]

Sent by : Chen Xinyou (AXA Insurance Pte Ltd)

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

Unique Entity Number: 200721148H

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI D'O MUMANDY
SEGA PARAM
ONG BOCK KEE
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YINGXIAN SELWYN

✓Head Office:
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Branch:
490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490
Branch:
133 New Bridge Road
#10-03 Chinatown Point
Singapore 059413

AXA INSURANCE PTE LTD

16 JAN 2018

HEAD OFFICE: CSU
TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)

E-MAIL: annatan@visionlawllc.com

BRANCH

TEL : (65) 63580703
TEL : (65) 65330868

BRANCH

TEL : (65) 65342811 (Hunting)
TEL : (65) 65330868

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to HEAD OFFICE for it is

Our Ref : AKN-atv-Ins-T140-105009-17
Your Ref : SHC 5832 Y

Date: 15 January 2018

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attn: Motor Claims Department

TRANS-CAB SERVICES PTE LTD

2 Ang Mo Kio Street 63
Singapore 569111

WITHOUT PREJUDICE
BY HAND

CERTIFICATE OF POSTING
[For your information only]

Dear Sir,

CLAIMANT : CHIA JUINN MING

ACCIDENT INVOLVING WNC 9233 & SHB 7982 P & SHC 5832 Y ON 24-MAR-2017 AT JUNCTION OF BUKIT TIMAH ROAD AND WHITLEY ROAD AT ABOUT 2255HOURS

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on **24-MAR-2017 AT JUNCTION OF BUKIT TIMAH ROAD AND WHITLEY ROAD AT ABOUT 2255HOURS** involving our client's vehicle registration number **WNC 9233** and vehicle registration number **SHC 5832 Y** driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

01.	Cost of Repair	\$ 8,560.00
02.	Loss of Use for 8 days at \$180.00 per day	\$ 1,440.00
03.	Additional 2 loss of use for pre repair	\$ 360.00
04.	Survey report fees	\$ 683.00
05.	GIA & LTA search / report fees	\$ 67.35
06.	Cost Contribution (at this stage)	\$ 2,675.00
07.	Disbursements (at this stage)	\$ 50.00
TOTAL		\$13,835.35

.../2 to be continued next page

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

11333333

VISION LAW LLC

Advocates & Solicitors

Page 2

Our Ref : AKN-atv-Ins-T140-105009-17
Your Ref : SHC 5832 Y

Date: 15 January 2018

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Department

TRANS-CAB SERVICES PTE LTD

2 Ang Mo Kio Street 63

Singapore 569111

We enclose a copy of each of the following documents for your consideration:-

- (a) Police report lodged by driver of WNC 9233 ;
 - (b) LTANet Search;
 - (c) Certificate of Insurance;
 - (d) Registration Card;
 - (e) Final Repair Bill;
 - (f) Surveyor's report & invoice; and
 - (g) **83 b/w photographs** depicting the damages to motor vehicle WNC 9233.
- (P.S:- Original photographs will be sent to insurance co. only)

The demand herein is in respect of our client's claim for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully



(HEAD OFFICE)

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

Enquire Vehicle & Owner Information (Vehicle No. SHB7982P As At 24 Mar 2017 / 22:55:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: T140-105009-17

Current Owner Details

Owner ID Type: Company

Owner ID: 200303878K

Owner Name: TRANS-CAB SERVICES PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 2

Registered Street Name: ANG MO KIO STREET 63

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 569111

Current Vehicle Details

Vehicle No.: SHB7982P

Make Description/Model: CHEVROLET / EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO

Insurance Company Name: AXA INSURANCE PTE LTD

Enquire Vehicle & Owner Information (Vehicle No. SHC5832Y As At 24 Mar 2017 / 22:55:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: T140-105009-17

Current Owner Details

Owner ID Type: Company
Owner ID: 200303878K
Owner Name: TRANS-CAB SERVICES PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 2
Registered Street Name: ANG MO KIO STREET 63
Registered Unit No.: -
Registered Building Name: -
Registered Postal Code: 569111

Current Vehicle Details

Vehicle No.: SHC5832Y
Make Description/Model: RENAULT / LATITUDE 2.0L DCI AUTO D/AB 4DR
Insurance Company Name: AXA INSURANCE PTE LTD

Thank you



Ng Ching Boon Eric has successfully logged out.

Your last login date and time was 12 Jan 2018, 17:06:18.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(S\$)</u>	<u>Log Date/Time</u>
1	Vehicle	SHC5832Y	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	12 Jan 2018 / 17:07:04
2	Vehicle	SI-B7982P	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	12 Jan 2018 / 17:06:40

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHIA JIUNN MING
BLOCK B #03-12 PERMASVILLE JALAN PERMAS 3
BANDAR BARU PERMAS JAYA 81750 MASAI JOHOR
JOHOR
MALAYSIA 81750

Contact : 0107011373 93959643, 0187671481

TAX INVOICE

Date : 16/11/2017
Date in : 28/03/2017
Vehicle Num. : WNC9233
Make/Model : TOYOTA INNOVA 2.0 G (A)-2005
Chassis/Eng# : PN111NV4008601083/1TR-6093017
Accident Date : 24/03/2017
Claim No : CLM13655
Reference : MAR-35/2017
Policy No. : JVD2018634 (08/06/2017)

LUMP SUM REPAIR BILL
AS PER SURVEYOR REPORT
REF : 0434-17-TCA DATED 30/10/2017
BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$
8,000.00

E. & O.E.	Sub S\$:	8,000.00
Add GST (7 %) S\$:		560.00
Total Amount S\$:		8,560.00



for TWINCAR AUTOMOTIVE PTE LTD

The Insured / Pemegang Polisi CHIA JIUNN MING BLOCK C1#08-01 TAMAN LARKIN IDAMAN JALAN IDAMAN UTAMA 80350 JOHOR BAHRU			Policy No. / No. Polisi JVD2018634 01-01		
Occupation / Pekerjaan OTHERS			Account No. / No. Akaun 741700-00		
I.C. No. / No. Kad Pengenalan 771108055915			Type of Cover / Jenis Perlindungan COMPREHENSIVE		
Hire Purchase Owner / Pemilik Sewa Beli AEON CREDIT SERVICE (M) BERHAD			Period of Insurance / Tempoh Insurans From / Dari 00:00:01 AM 09-06-2016 To / Hingga 08-06-2017		
Bus. Regn. No / No Pendaftaran Perniagaan -		Premium / Premium All Rider / Semua Penunggang Maximum Cumulative Loading / Tambahan Berganda Maksima 15.00%		RM 1,405.10 0.00 210.77 1,615.87	
NCD / Diskaun Tanpa Tuntutan 0.00%		Wef / Berkuatkuasa dari 09-06-2016		0.00 1,615.87	
Make & Type of Body / Binaan & Jenis Badan TOYOTA INNOVA / MPV			Gross Premium / Premium Kasar Service Tax / Cukai Perkhidmatan 0%		1,615.87 0.00
Registration No. / No. Pendaftaran WNC9233	Excess / Lebihan 0.00	Regn. Card No. / No. Kad Pendaftaran A2952751	GST / GST 6% SR Stamp Duty / Duti Setem		96.95 10.00
Carrying or Seating Capacity Incl. Driver / Muatan Tempat Duduk Termasuk Pemandu 8	Tonnage / C.C./ Watt Tan / Keupayaan Enjin 1998.00 CC Year of Manufacture / Tahun Diperbuat 2005	Estimate of Value Incl. Accessories and Spare Parts / Nilai Anggaran termasuk aksesori dan alat-alat ganti 42,000.00	Act / Akta RM 158.36		
Engine/Motor No. / No. Enjin/Motor 1TR-6093017	Chassis No. / No. Cas/s PN111NV4008601083		Trailer / Treler -		
Only The Extensions, Endorsement And / Or Warranties Indicated Below Apply To This Policy. / Hanya Lanjutan, Endorsemen dan / atau Warranti sepertimana yang dinyatakan di bawah ini boleh diguna pakai dalam polisi ini. 2, 2(f), 30, 100, 106, 15, 113					
Total Due / Jumlah Berbayar			RM 1,722.82		

Subject to IMPORTANT NOTICE: Your duty as the Owner of the vehicle as attached.

Total Due (OTC) / Jumlah Berbayar Di Kaunter RM 1,722.80

Authorised Driver / Pemandu yang Diberi Kuasa:

THE POLICYHOLDER, WU HUI MEI

Geographical Area : Malaysia , Republic of Singapore and Negara Brunei Darussalam. / Kawasan Geografi : Malaysia, Republik Singapura dan Negara Brunei Darussalam.

Limitations as to Use / Authorised Driver : As described in the Certificate of Insurance. / Had Penggunaan / Pemandu Yang Diberi Kuasa : Seperti yang tercatat dalam Sijil Insurans.

Replacing Cover Note No./

Gantian No. Nota

Perlindungan

Renewal of Policy No./

Pembaharuan No. Polisi

Date of Proposal or

Declaration /

Terikh Cadangan atau

Pengisytiharan

08-06-2016

Issued By / Dikeluarkan Oleh :

MOK SHEAU PYNG

LOT 2554


JALAN RAYA SALENG

Tel : 075987788

Fax : 0075987788

for / untuk

AmGeneral Insurance Berhad



Date of Issue / Time 08-06-2016 06:04:50 PM

Terikh Dikeluarkan / Waktu

Authorised Signature / Tandatangan Yang Diberi Kuasa

Note: / Nota: No refund of premium for any cancellation of policy if premium is charged on minimum premium / Tidak bayaran balik premium bagi sebarang pembatalan polisi sekiranya premium yang dikenakan adalah premium minima.
08JVT1PN770650-1

AmGeneral Insurance Berhad (44191-P)

A member of the AmBank group

Menara Kumia, No. 8, Jalan PJS 8/8, 46160 Petaling Jaya, P.O. Box 8607, 46792 Petaling Jaya, Selangor Darul Ehsan, Malaysia
Tel +603-7875 3333 Fax +603-7875 9833 E-mail corporate@kurnia.com Website www.kurnia.com

(GST Registration No.: 000789741598)



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

ZMQWC6BI


No. Pendaftaran : WNC9233
No. ID : 771108055915
Nama Pemunya Berdaftar : CHIA JIUNN MING
Alamat : BLOCK C1 # 08-01 TAMAN LARKIN IDAMAN JALAN IDAMAN
UTAMA
80350 JOHOR BAHRU JOHOR
No. Chasis/No. Enjin : PN111NV4008601083 / 1TR-6093017
Buatan>Nama Model : TOYOTA / INNOVA 2.0 G (A)
Keupayaan Enjin : 1998
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : PERSENDIRIAN-MOTOKAR INDIVIDU
Jenis Badan/Tahun Dibuat : MOTOKAR PELBAGAI UTILITI / 2005
Tarikh Pendaftaran : 19/07/2005
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -

0231184

NOTA PENTING

1. Semak butir-butir kenderaan di muka ini dan laporkan dengan segera kepada Pengarah JPJ jika terdapat sebarang perubahan.
2. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.
3. Jika alamat anda bertukar, sila kemaskini dalam tempoh dua bulan dari tarikh pertukaran ini.







**SINGAPORE
POLICE FORCE**



T/20170325/2114

1 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20170325/2114

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/03/2017 19:21		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: chia liang sim			Address:		
ID Type / ID No.: NEW MALAYSIAN IC / 540110105047			Contact No.: Home/Office:		Mobile: 0187671481
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 63	Date of Birth: 10/01/1954	Type of Informant: Driver		
Race: Chinese		Language: Malay		Institution / School Name:	
Occupation: RETIRED		Driving Licence Information: Class: 3		Date of Expiry: 10/01/2020	

General Information of the Accident				
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 24/03/2017 22:55	Type of Location: Straight Road
Location: Along Road 1 BUKIT TIMAH ROAD WHITLEY ROAD BUKIT TIMAH ROAD JUNG OF WHITLEY ROAD TWDS PIE				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB7982P	Car				Seriously Damaged	0
SHC5832Y	Car				Seriously Damaged	0
WNC9233	Car	TOYOTA	INNOVA	Brown	Slightly Damaged	1



**SINGAPORE
POLICE FORCE**



T/20170325/2114

2 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20170325/2114

CONTINUATION OF REPORT

Brief Details.

AT THE ABOVE STATED TIME AND LOCATION, I WAS DRIVING ALONG WHITELEY ROAD HEADING TOWARDS THE PIE AND THERE WAS A HEAVY TRAFFIC WHICH CAUSED THE TRAFFIC TO SLOW DOWN. WHEN SUDDENLY I HEARD A LOUD BANG AT THE BACK AND SOON AFTER THE CAR BEHIND ME COLLIDED ONTO MY REAR.



**SINGAPORE
POLICE FORCE**



T/20170325/2114

3 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20170325/2114

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
AZRUL AZWAN BIN MD SA'AD

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIA /
Staff Sgt TANG SIEW PING
Contact No.: 65476430

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
25/03/2017 19:21

Classification Of Case:

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 28 Mar 2017 / 16:08:22

Receipt Date/Time : 28 Mar 2017 / 16:08:22

Tax Invoice/Receipt

Receipt No. : ITNET-00000-170328-001464

Previous Receipt No. :

**S/N Item Description/
Business Transaction
Reference No.**

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
--	---------------------------------	---------------------------------------

Result of Insurance Enquiry - SHC5832Y

As at 24 Mar 2017/22:55:00

Insurance Co: AXA INSURANCE SINGAPORE PTE LTD

1 Insurance Enquiry - SHC5832Y
Enquiry Fee
20170328160741382093

5.00	0.35	5.35
------	------	------

Sub-Total	5.00	0.35	5.35
------------------	------	------	------

Total Before Rounding	5.00	0.35	5.35
------------------------------	------	------	------

Rounding Difference			0.00
----------------------------	--	--	------

Total Amount Payable			5.35
-----------------------------	--	--	------

Paid By

xxxxxxxxxxxx2392	Credit Card: Visa/MasterCard	5.35
------------------	---------------------------------	------

Total			5.35
--------------	--	--	------

Cash Change			0.00
--------------------	--	--	------

Tendered Amount			5.35
------------------------	--	--	------

Excess Refundable Amount			0.00
---------------------------------	--	--	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0434-17-TCA

30 October 2017

Chia Jiunn Ming
Blk B #03-12 Permasville Jln Permas 3
Bandar Bau Permas Jaya 81750 Masa Johor

INVOICE No. 0434-17-TCA

Vehicle No. WNC9233

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$683.00
Total amount payable		<u>\$683.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0434-17-TCA

30 October 2017

ACCIDENT VEHICLE SURVEY REPORT

Chia Jiunn Ming
Blk B #03-12 Permasville Jln Permas 3
Bandar Bau Permas Jaya 81750 Masa Johor

VEHICLE INFORMATION:

Vehicle Reg No.:	WNC9233	Odometer:	143221km
Make & Model:	Toyota Innova 2.0G A	Colour:	Silver
Chassis number:	PN111NV4008601083	Date of accident:	24/03/2017
Year of Regn.:	19/07/2005	Date inspected:	30/03/2017
Repairer at:	Twincar Automotive Pte Ltd	Date inspected (After Repair):	04/04/2017
	Blk 2 Kaki Bukit Ave 2 #01-17		
	Kaki Bukit Auto Hub		
	Singapore 417921		

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Falken	5mm/Falken	205/65R15
Rear:	5mm/Falken	5mm/Falken	205/65R15

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax 645 36131.

Report No: 0434-17-TCA

30 October 2017

ACCIDENT VEHICLE SURVEY REPORT

Chia Jiunn Ming

Blk B #03-12 Permasville Jln Permas 3

Bandar Bau Permas Jaya 81750 Masa Johor

VEHICLE INFORMATION:

Vehicle Reg No.:	WNC9233	Odometer:	143221km
Make & Model:	Toyota Innova 2.0G A	Colour:	Silver
Chassis number:	PN111NV4008601083	Date of accident:	24/03/2017
Year of Regn.:	19/07/2005	Date inspected:	30/03/2017
Repairer at:	Twincar Automotive Pte Ltd	Date inspected (After Repair):	04/04/2017
	Blk 2 Kaki Bukit Ave 2 #01-17		
	Kaki Bukit Auto Hub		
	Singapore 417921		

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
REAR BUMPER	1	squashed	591.60	591.60 /
REAR BUMPER LOWER SPOILER	1	deformed	374.25	374.25 /
REAR BUMPER RETAINER L/R	2	necessary	264.20	264.20 116.4
REAR BUMPER TOW HOOK COVER	1	reuse	43.75	0.00
REAR END PANEL	1	buckled	781.45	X 781.45 repair
REAR END PANEL TOP GARNISH	1	fractured	371.85	371.85 198.4
REAR EXHAUST SILENCER BOX	1	bent	781.90	X 781.90 NN
REAR SPARE TYRE BRACKET	1	bent	177.25	X 177.25 NN
REAR TAILGATE	1	buckled	1,218.45	1,218.45 1043.2
REAR TAILGATE '2.0' EMBLEM	1	necessary	61.10	61.10 { 40.4
REAR TAILGATE 'G' EMBLEM	1	necessary	63.90	63.90
REAR TAILGATE 'INNOVA' EMBLEM	1	necessary	63.10	63.10 42.2
REAR TAILGATE 'LOGO' EMBLEM	1	necessary	61.90	61.90 56.2
REAR TAILGATE 'TOYOTA' EMBLEM	1	necessary	51.10	51.10 /
REAR TAILGATE DAMPER L/R	2	bent	748.90	X 748.90 { NN
REAR TAILGATE MECHANISM LOCK	1	bent	381.90	X 381.90
REAR TAILGATE OUTER CHROME HANDLE	1	fractured	377.45	X 377.45
REAR TAILGATE WEATHERSTRIP	1	deformed	381.90	381.90 298.4
REAR TAILGATE WINDSCREEN MOULDING L/R	2	necessary	344.90	344.90 68.4
REAR TAILLAMP L/R	2	fractured	748.50	X 748.50 NN
Subtotal before discount			S\$ 7,889.35	S\$ 7,845.60 2880.55
Percentage discount 25% and 25%			S\$ 1,972.34	S\$ 1,961.40 2160.41
Sub-total 1			S\$ 5,917.01	S\$ 5,884.20
REAR BUMPER CLIPS - SET	1	necessary	30.00	30.00 /
REAR BUMPER REVERSE SENSOR - SET	1	shorted	350.00	350.00 220
REAR END PANEL TOP GARNISH CLIPS - SET	1	necessary	20.00	20.00 /
REAR NUMBER PLATE	1	necessary	50.00	X 50.00 NN
REAR TAILGATE WINDSCREEN SEALANT	1	necessary	100.00	100.00 50
REAR TAILLAMP CLIPS - SET	2	necessary	60.00	X 60.00 NN
Subtotal before discount			S\$ 610.00	S\$ 610.00 320
Sub-total 2			S\$ 610.00	S\$ 610.00
Parts-total			S\$ 6,527.01	S\$ 6,494.20

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

100.00 50.00 40

To remove, reinstall tailgate windscreen

150.00 120.00 /

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

100.00 60.00 /

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1,600.00 1,400.00 800

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

150.00 X 120.00 NN

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1,500.00 1,100.00 600

To apply anti-rust chemical on repaired and replaced panel.

100.00 60.00 /

Labour Total	SS 3,700.00	SS 2,910.00
Parts & Labour Total	SS 10,227.01	SS 9,404.20

1680

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 8,000.00 and the recommended number of working days for the repairs is within 8 day(s).

4160.41

20%: 3300

B J Loi (I Eng, MIMI, AIRTE)
Automotive Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. WNC 9233

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	SQUASHED	591.60	591.60
1	REAR BUMPER LOWER SPOILER	DEFORMED	374.25	374.25
2	REAR BUMPER RETAINER L/R	NECESSARY	264.20	116.40
1	REAR BUMPER TOW HOOK COVER	REUSE	43.75	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	781.45	-
1	REAR END PANEL TOP GARNISH	FRACTURED	371.85	198.40
1	REAR EXHAUST SILENCER BOX	NOT NECESSARY	781.90	-
1	REAR SPARE TYRE BRACKET	NOT NECESSARY	177.25	-
1	REAR TAILGATE	BUCKLED	1,218.45	1,043.20
1	REAR TAILGATE '2.0' EMBLEM }	NECESSARY	61.10	40.40
1	REAR TAILGATE 'G' EMBLEM }	NECESSARY	63.90	-
1	REAR TAILGATE 'INNOVA' EMBLEM	NECESSARY	63.10	42.20
1	REAR TAILGATE 'LOGO' EMBLEM	NECESSARY	61.90	56.20
1	REAR TAILGATE 'TOYOTA' EMBLEM	NECESSARY	51.10	51.10
2	REAR TAILGATE DAMPER L/R	NOT NECESSARY	748.90	-
1	REAR TAILGATE MECHANISM LOCK	NOT NECESSARY	381.90	-
1	REAR TAILGATE OUTER CHROME HANDLE	NOT NECESSARY	377.45	-
1	REAR TAILGATE WEATHERSTRIP	DEFORMED	381.90	298.40
2	REAR TAILGATE WINDSCREEN MOULDING L/R	NECESSARY	344.90	68.40
2	REAR TAILLAMP L/R	NOT NECESSARY	748.50	-
	LESS 25% DISCOUNT		-1,972.34	-720.14
			5,917.01	2,160.41
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	350.00	220.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	100.00	50.00

Report Ref No. CS3/AXA17006196/Gqbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	SET REAR TAILLAMP CLIPS (SN)	NOT NECESSARY	60.00	-
			610.00	320.00
	LABOUR			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		100.00	40.00
	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.		150.00	120.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		100.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,600.00	800.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	150.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,500.00	600.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		100.00	60.00
			3,700.00	1,680.00
GRAND TOTAL			10,227.01	4,160.41
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,300.00

Report Ref No. CS3/AXA17006196/Gqbs2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.