

22/03/2018

ASS. REC. BY:

REF: CS/FCI18001780/Gqd3ek

Special Instruction:

Surveyor: CWS

90

ASSIGNMENT (Office)

From (Person): Joanne Yong

of

FCI

Date/Time: 30/1/18 @ 9:34am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLV 73564

Insured:

SHB 4297D

at Workshop m/s

Kah Motor

Tel:

68465671

of

15 ubi Road 4

Policy No.:

Claim No.:

D18000876 MFSH

Sum Insured:

Excess:

Make of Veh.:

(Client's Record)

D.O.A. 25/01/2018

CA / REV / REP. / REV 24 HRS

'Ds'

H.O.D. Endorsement:

Date/Time:

9:40am @ 30/1/18

Person Contacted:

Mr. Lim

Vehicle IN/

OUT

Date/Time	Action/Instruction
	( <input checked="" type="checkbox"/> ) Estimate
	SLV 73564 - x
	SHB 4297D - collect back 241/Rtg
01/2/18 @ 3:29pm	revised to Joanne Yong by email.
20/2/18 @ 4:43pm	confirmed with Mr Lim final fig @ 5412.37, 5 days.
	(Ref. B 1782-48, 25%)

D.O.A. 18/04/2018





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001780/Gqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 30-01-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4297D	Veh. Inspected	SLV 7356U
Policy No.		Coverage (\$)	0.00
Claim No.	D18000876MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	30/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/01/2018	Inspection Date	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C  
GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

<b>Date</b>	29-01-2018	<b>Our Ref No.</b> D18000876MFSH
<b>Accident Date</b>	25-01-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHB4297D	<b>Third Party Vehicle.</b> SLV7356U
<b>Survey Location</b>	15 UBI ROAD 4	
<b>Contact Person.</b>	LIM CHOU SIONG	
<b>Contact No.</b>	68465671/ 68465671	<b>Fax No.</b> 67480770
<b>Survey Type</b>	DIRECT SETTLEMENT:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	KAH MOTOR CO SDN BHD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	JOANNEY	

### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234432)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18000876MFSH	<b>Policy No</b>	D-18088936MFSH	<b>Claimant S.No &amp; Name</b>	1 & KAH MOT
<b>Workshop Name</b>	KAH MOTOR CO SDN BHD (Contact Person : LIM CHOU SIONG)	<b>Survey Location &amp; Contact Details</b>	15 UBI ROAD 4 <b>Mobile:</b> 68465671 , <b>Phone:</b> 68465671 , <b>Fax:</b> 67480771 <b>EmailId:</b> CSLIM@HONDA.COM.SG		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	DIRECT SETTLEMENT:		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHB4297D	<b>TP Vehicle No</b>	SLV7356U
<b>PRI Recieved Date</b>	29-01-2018 06:21:34 PM	<b>Surveyor Appointed Date</b>	30-01-2018 09:33:33 AM	<b>Surveyor Accept Date</b>	30-01-2018 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>		<b>Surveyor Report Date</b>	30-01-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	--	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select Year"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
<b>File Name</b>	<b>Action</b>

## Surveyor Job Remarks

<b>Remarks</b>	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Tuesday, 20 March 2018 4:43 PM  
**To:** 'Lim Chou Siong'; SUR  
**Cc:** Liew Thye Wui; Faeaz  
**Subject:** RE: Pre-Invoice Of Vehicle No: SLV7356U For Finalising

Dear Mr Lim,

Confirm final fig \$5,412.37 before GST and 5 repair days.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Lim Chou Siong [mailto:[cslim@honda.com.sg](mailto:cslim@honda.com.sg)]  
**Sent:** Saturday, 17 March 2018 2:02 PM  
**To:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** Liew Thye Wui <[twliew@honda.com.sg](mailto:twliew@honda.com.sg)>; Faeaz <[faeaz@honda.com.sg](mailto:faeaz@honda.com.sg)>  
**Subject:** Pre-Invoice Of Vehicle No: SLV7356U For Finalising

Dear,

We enclosed the total final repair costs of...

Vehicle No. SLV7356U

Final Repair Costs (include GST) \$5,791.25

Repair Period\*( Working Day) 05

\*Note: Repair period does not include Sunday And Public Holiday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thanks & best regards,

Lim Chou Siong

Contact No: 81006303 HP

KAH MOTOR CO. SDN. BHD.

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

15 Ubi Road 4 Singapore 408610

Tel: +65 6841 3838 Fax: +65 6748 0770

This is a computer-generated e-mail no signature is necessary Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 1 February 2018 3:29 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18000876MFSH/1  
**Attachments:** CSFCI18001780Gqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SLV 7356U.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Admin-D (LKKAuto)

**Sent:** Tuesday, 30 January 2018 9:41 AM

**To:** 'Claim Workflow System' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** RE: SURVEY ASSESSMENT - D18000876MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

**Sent:** Tuesday, 30 January 2018 9:34 AM

**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)

**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [JOANNEYONG@MSFIRSTCAPITAL.COM.SG](mailto:JOANNEYONG@MSFIRSTCAPITAL.COM.SG)

**Subject:** PRI: SURVEY ASSESSMENT - D18000876MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18000876MFSH  
Our Ref: CS/FCI18001780/Gqd3

Date: 01 February 2018

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLV 7356U**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 31/01/2018 at the premises of M/s KAH MOTOR, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 7,166.72</u>
Revised Estimate Amount	: <u>S\$ 5,384.24</u>
"Check" Items Amount	: <u>S\$ 492.48</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

**Description of Damage:**

The vehicle sustained damages at the rear portion.



Yours faithfully

Guo Qiang  
Automotive Assessor

## Enquire Transfer Fee

### Vehicle Details

Vehicle No.:	SLV7356U
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 CVT
Chassis No.:	JHMGK5850JX202014
Propellant:	Petrol
Engine No.:	L15B33110815
Engine Capacity:	1498 cc
Maximum Power Output:	96.0 kW ( 128 bhp)
Maximum Laden Weight:	1490 kg
Unladen Weight:	1088 kg
Year Of Manufacture:	2017
Original Registration Date:	12 Jan 2018
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$42,339.00
COE Expiry Date:	11 Jan 2028
Road Tax Expiry Date:	11 Jan 2019
PARF Eligibility Expiry Date:	11 Jan 2028
Inspection Due Date:	11 Jan 2021
Intended Transfer Date:	01 Feb 2019
CO2 Emission:	127.00 (g/km)
CEV/VES Rebate Utilised Amount:	-
CO Emission:	0.105000 (g/km)
HC Emission:	0.002500 (g/km)
NOx Emission:	0.001000 (g/km)
PM Emission:	0.336000 (mg/km)

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable (From 12 Jan 2019 to 11 Jul 2019)

Amount Before GST  
(S\$)

GST Amount  
(S\$)

Amount After GST  
(S\$)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/01/2018 20:45
Date Of Accident	25/01/2018 16:45
Exact Location Of Accident	AMK AVE 1 CTE EXIT AND JUNC OF ANG MO KIO AVE 10
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV7356U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SEAH HOCK LEE
NRIC No	S7246697G
Email Address	127SEAHHL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93885311
Alternative Phone No	OFFICE-93885311
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	JAZZ 1.5 CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10806701
Cover Note Number	
<b>Driver</b>	
Name of Driver	SEAH HOCK LEE
NRIC No	S7246697G
Date Of Birth	18/12/1972
Occupation	INDOOR
Date Of Driving Pass	11/07/1991
Driving Experience	26 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93885311
Fax Number	
Contact Number	OFFICE-93885311
EMail Address	127SEAHHL@GMAIL.COM

Address NA  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes,Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes,against whom?

**Circumstances of Accident**

I SLV7356U was driving along exiting to CTE Ang Mo Kio ave 1 and junction of Ang mo Kio Ave 10 T-junction. While approaching the junction suddenly the traffic change to Amber light, so I stop my vehicle. Suddenly the other party SHB4297D did not manage to stop and bang onto my rear bumper. No injuries involved.


**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: WILL UPLOAD TO FILEZILA ONCE INSURED SEND  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SHB4297D  
 Vehicle Make/Model/Colour HYUNDAI/i40 1.7L CRDI /BLUE  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver TAY HAY LENG  
 NRIC/Passport Number  
 Contact Number 91918615  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver) 1

# Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I SLV7356U was driving along exiting to CTE Ang Mo Kio ave 1 and junction of Ang mo Kio Ave 10 T-junction. While approaching the junction suddenly the traffic change to Amber light, so I stop my vehicle. Suddenly the other party SHB4297D did not manage to stop and bang onto my rear bumper. No injuries involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MUHAMMAD SUMARDI BIN MOHD AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

25 January 2018 7:56 pm

Date/Time:

25 January 2018 7:56 pm

## CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP 189 OF THE REVISED EDITION)  
 (REPUBLIC OF SINGAPORE)  
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION  
 (REPUBLIC OF SINGAPORE) OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

**CERTIFICATE NUMBER. 10806701**

<p><b>1) VEHICLE REGISTRATION NO.</b>  <b>CHASSIS NO.</b>  <b>ENGINE NO.</b></p>	<p>SLV7356U                  JHMGK5850JX202014                  L15B33110815</p>
<p><b>2) NAME OF INSURED</b></p> <p>FAMILY NAME                  GIVEN NAME</p>	<p>SEAH                  HOCK LEE</p>
<p><b>3) EFFECTIVE DATE OF COMMENCEMENT OF INSURANCE FOR THE PURPOSE OF THE ACT</b></p>	<p>12-Jan-2018 00:00hours</p>
<p><b>4) DATE OF EXPIRY OF INSURANCE</b></p>	<p>11-Jan-2020 23:59hours</p>
<p><b>5) PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE</b></p> <p>Any driver</p> <p>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by any reason of any enactment or regulation in that behalf from driving the Motor Vehicle.</p> <p>And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been canceled at the time of accident or loss.</p> <p>Please refer to the policy document for full terms and conditions.</p>	
<p><b>6) LIMITATIONS AS TO USE*</b></p> <p>Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or reward, tuition or driving tests, racing, pace-making, reliability trials, speed-testing or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.</p> <p><i>* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.</i></p>	
<p><b>NAMED DRIVER</b></p>	
<p><b>7) FINANCE COMPANY</b></p>	<p>OCBC BANK LIMITED</p>

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia), or any amendment, act or acts passed in substitution thereof.

Issued in Singapore: 19-Jan-2018 at 08:33hours

Aviva Ltd.


**IMPORTANT NOTE:**

- If you want to cancel your policy at any time, you will need to return the certificate to us.
- You MUST report all accidents to Us within 24 hours of the occurrence regardless of whether You intend to claim on Your own policy or not, or whether Your car is damaged or not. Should You fail to do so, Your No Claims Discount could be affected and Your claim may be prejudiced.



\_\_\_\_\_  
 Nishit Majmudar  
 Chief Executive Officer

**In case of accident or windscreen damage, please call 6333 2222 (24 hours) immediately.**





**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Kindly Help to arrange  
Surveyor to Survey this  
Vehicle  
thanks

# QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877	<b>Document No.</b>	: SQT18000403	<b>Page</b>	1
<b>Registration No</b>	: SLV7356U	<b>Date</b>	: 26. Jan 2018	<b>Customer No.</b>	: WZF002
<b>Chassis No</b>	: JHMGK5850JX202014	<b>Svc Advisor</b>	: LIM CHOU SIONG	<b>Engine No</b>	: L15B33110815
<b>Model</b>	: JAZZ 1.5VTIR CVT 18YM (EURO 6)	<b>Date   Time</b>	: 26. Jan 2018 4:40:35 PM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: SEAH HOCK LEE	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 25/1/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST	
	TP DIRECT SETTLEMENT (J/NO:) OWNER: SEAH HOCK LEE OWNER INSURER: AVIVA LTD ACC DATE: 25/1/2018 SURVEYED BY: DATE: REF NO: TP INSURER: FIRST CAPITAL INSURANCE LTD TP VEH: SHB4297D							
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.20	25	8.40	0.59	8.99	
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.30	25	9.45	0.66	10.11	
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66	
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40	
68100-TAS-Z50ZZ	TAILGATE COMP	1	716.30	25	537.22	37.61	574.83	
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07	
75722-T5L-T01	EMBLEMRR.	1	10.50	25	7.87	0.55	8.42	
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40	
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	455.10	25	341.32	23.89	365.21	
71502-T5A-J60	COVER,R.RR.BUMPER	1	20.30	25	15.22	1.07	16.29	
71505-T5A-J50	GARNISH,RR.BUMPER	1	37.50	25	28.12	1.97	30.09	
71507-T5A-J60	COVER,L.RR.BUMPER	1	20.30	25	15.22	1.07	16.29	
71510-T5B-J50ZA	DIFFUSER ASSY,RR.PR	1	202.70	25	152.02	10.64	162.66	
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.60	25	12.45	0.87	13.32	
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.60	25	12.45	0.87	13.32	
91505-TM8-003	CLIPBUMPER	9	2.00	25	13.50	0.95	14.45	
38387-TZ5-A01	ANTENNA ASSYL.F.	1	58.10	25	43.57	3.05	46.62	
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30	25	44.47	3.11	47.58	
					<b>Sum Item</b>	<b>1756.72</b>	<b>122.99</b>	<b>1,879.71</b>
BOSUN	SUNDRIES	1	30.00	10	30.00	2.10	32.10	

*Handwritten notes:*  
- BT  
- NN  
- Cut  
- MC  
- NN



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
 (A Member of the Oriental Holdings Berhad)  
 Service and Body Repair  
 Tel: +65 6841 3838 Website: www.honda.com.sg  
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
 Company Ref. No.: S60FC1380G

<b>Customer</b> : FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877	<b>Document No.</b> : SQT18000403 <span style="float: right;">Page 2</span> <b>Date</b> : 26. Jan 2018 <b>Customer No.</b> : WZF002 <b>Svc Advisor</b> : LIM CHOU SIONG <b>Engine No</b> : L15B33110815 <b>Date   Time</b> : 26. Jan 2018 4:40:35 PM <b>Surveyor Name</b> : <b>Survey Date</b> : <b>Authorisation Date</b> :
<b>Registration No</b> : SLV7356U <b>Chassis No</b> : JHMGK5850JX202014 <b>Model</b> : JAZZ 1.5VTIR CVT 18YM (EURO 6) <b>Owner's Name</b> : SEAH HOCK LEE <b>Ins Policy No.</b> : <b>Date of Accident</b> : 25/1/2018	

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		300.00	21.00	321.00
BOMISC1	REMOVE, INSTALL AND RESET REAR VIEW CAMERA. (N)	1	320.00		320.00	22.40	342.40
BOMISC1	RESET SMART ENTRY SYSTEM AND REMOVE NECESSARY	1	320.00		320.00	22.40	342.40
BMI02D	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR1		350.00	28%	350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	380.00		380.00	26.60	406.60
BKBU02R	REPLACE RR BUMPER, REPAIR RR PANEL & OTHER DAMAGE	1	1500.00	9%	1500.00	105.00	1605.00
BP04R	SPRAY PAINTING ON TAILGATE, RR BUMPER, RR BUMPER (350)	1	2000.00	14%	2000.00	140.00	2140.00
<b>Sum Labor</b>					<b>5410.00</b>	<b>378.70</b>	<b>5,788.70</b>

Survey By	<u>Lim Chou Siong (82880282)</u>			
Date & Time	<u>31/1/18</u>	81006303 (UEP)	<b>Total Amount</b>	7,166.72 501.69 7,668.41
Excess			<b>Total (Inclusive of GST)</b>	<b>7,668.41</b>
Status				
Signature				7194.85

before paint photos.  
 5 Days.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



17/03/2018

Page 1/3

**SERVICE PRE-INVOICE****KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Attn: Guo Qiang (L.K.K.)

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

5 days

**Customer:** WZF002 / FIRST CAPITAL  
**Chassis No:** JHMGK5850JX202014  
**License No:** SLV7356U  
**Mileage:** 2515  
**Engine No:** L15B33110815

**Document No:** SVO18012569  
**Printed By:** CSLIM  
**Order Date:** 5. March 2018  
**Order Time:** 8:59:39 AM  
**Service Advisor:** LIM CHOU SIONG

ITEM	DESCRIPTION	QTY.	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70056) OWNER: SEAH HOCK LEE OWNER INSURER: AVIVA LTD ACC DATE: 25/1/2018 SURVEYED BY: GUO QIANG (L.K.K.) DATE: 31/01/2018 @ 15:00PM REF NO: TP INSURER: FIRST CAPITAL INSURANCE LTD TP VEH: SHB4297D						
35070	04715-T5B-J50ZZ(FACE,RR. BUMPER)	1	492.60	25	369.45	25.86	395.31
			<b>SUM EXCESS:</b>		<b>369.45</b>	<b>25.86</b>	<b>395.31</b>
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.20	25	8.40	0.59	8.99
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.30	25	9.45	0.66	10.11
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
68100-TAS-Z50ZZ	TAILGATE COMP	1	716.30	25	537.22	37.61	574.83
75722-T5L-T01	EMBLEMRR.	1	10.50	25	7.87	0.55	8.42
71606-T5A-J50	GARNISH,RR.BUMPER	1	37.50	25	28.12	1.97	30.09
71507-T5A-J80	COVER,L.RR.BUMPER	1	20.30	25	15.22	1.07	16.29
71510-T5B-J50ZA	DIFFUSER ASSY,RR.PR	1	202.70	25	152.02	10.64	162.66
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.60	25	12.45	0.87	13.32
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.60	25	12.45	0.87	13.32
91505-TM8-003	CLIPBUMPER	9	2.00	25	13.50	0.95	14.45
			<b>SUM PARTS:</b>		<b>922.92</b>	<b>64.62</b>	<b>987.54</b>
BOSUN	0672 SUNDRIES	1	10.00		10.00	0.70	10.70
BML02I	EXT-YJ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	80.00		80.00	5.60	85.60
BA02R	EXT-YJ REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	300.00		300.00	21.00	321.00
BOMISC1	EXT-YJ REMOVE, INSTALL AND RESET REAR VIEW CAMERA.(N)	1	320.00		320.00	22.40	342.40
BOMISC1	0672 RESET SMART ENTRY SYSTEM AND REMOVE NECESSARY COMPONENT.(N)	1	320.00		320.00	22.40	342.40
BMI02D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS, RR SEATS, TRUNK LININGS, GARNISHES & ETC.(N)	1	280.00		280.00	19.60	299.60
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	380.00		380.00	26.60	406.60



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022  
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

<b>Customer:</b>	WZF002 / FIRST CAPITAL	<b>Document No:</b>	SVO18012569			
<b>Chassis No:</b>	JHMGK5850JX202014	<b>Printed By:</b>	CSLIM			
<b>License No:</b>	SLV7356U	<b>Order Date:</b>	5. March 2018			
<b>Mileage:</b>	2515	<b>Order Time:</b>	8:59:39 AM			
<b>Engine No:</b>	L15B33110815	<b>Service Advisor:</b>	LIM CHOU SIONG			
<b>BKBU02R</b>	EXT-YJ REPLACE RR BUMPER, REPAIR RR PANEL & OTHER DAMAGE PARTS.	1	900.00	900.00	63.00	963.00
<b>BP04R</b>	EXT-YBH SPRAY PAINTING ON TAILGATE, RR BUMPER, RR BUMPER PR DIFFUSER ASSY. & RR PANEL	1	1,400.00	1,400.00	98.00	1,498.00
			<b>SUM LABOUR:</b>	<b>4,120.00</b>	<b>288.40</b>	<b>4,408.40</b>
			<b>TOTAL SGD</b>	<b>5,412.37</b>	<b>378.88</b>	<b>5,791.25</b>
			<b>Total Payable (SGD)</b>			<b>5,791.25</b>

GST Amount is calculated from individual line(s)



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: MS FIRST CAPITAL INSURANCE 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877	<b>Document No.</b>	: SQT18001018	<b>Page</b>	1
<b>Registration No</b>	: SLV7356U	<b>Date</b>	: 10. Mar 2018	<b>Customer No.</b>	: WZF002
<b>Chassis No</b>	: JHMGK5850JX202014	<b>Svc Advisor</b>	: LIM CHOU SIONG	<b>Engine No</b>	: L15B33110815
<b>Model</b>	: JAZZ 1.5VTIR CVT 18YM (EURO 6)	<b>Date   Time</b>	: 10. Mar 2018 8:18:53 AM	<b>Surveyor Name</b>	: GUO QIANG ( L.K.K. )
<b>Owner's Name</b>	: SEAH HOCK LEE	<b>Survey Date</b>	: 31/1/2018	<b>Authorisation Date</b>	: 2/2/2018
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 25/1/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incd GST
	TP DIRECT SETTLEMENT (J/NO: 70056) OWNER: SEAH HOCK LEE OWNER INSURER: AVIVA LTD ACC DATE: 25/1/2018 SURVEYED BY: GUO QIANG ( L.K.K. ) DATE: 31/01/2018 @ 15:00PM REF NO: D18000876MFSH TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SHB4297D SUPPLEMENTARY LABOUR & PARTS						
04715-T5B-J50ZZ	FACE,RR.BUMPER	1	492.60	25	369.45	25.86	395.31
				<b>Sum Item</b>	<b>369.45</b>	<b>25.86</b>	<b>395.31</b>

Survey By	_____						
Date & Time	_____			<b>Total Amount</b>	369.45	25.86	395.31
Excess	_____			<b>Total (Inclusive of GST)</b>			<b>395.31</b>
Status	_____						
Signature	_____						

Printed on 10/3/2018 8:26:18 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001780/Gqd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-03-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4297D	Veh. Inspected	SLV 7356U
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18000876MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	30/01/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA JAZZ	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JHMGK5850JX202014	Colour	WHITE
Odometer	933	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/55 R16	DUNLOP	9 mm
L/H Front Tyre	185/55 R16	DUNLOP	9 mm
R/H Rear Tyre	185/55 R16	DUNLOP	9 mm
L/H Rear Tyre	185/55 R16	DUNLOP	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/01/2018	Inspection Date	31/01/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 7356U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	RUBBER CWINDSHIELD DAMPER (SN)	NECESSARY	8.40	8.40
2	RUBBERWINDSHIELD DAMPER (SN)	NECESSARY	9.45	9.45
1	DAMPERSTD 5X5 (SN)	NECESSARY	6.22	6.22
2	WINDSCREEN SEALANT (SN)	NECESSARY	120.00	120.00
1	TAILGATE COMP (SN)	BENT	537.22	537.22
1	WEATHERSTRIPTAILGATE (SN)	NOT NECESSARY	69.22	-
1	EMBLEMRR (SN)	NECESSARY	7.87	7.87
4	ACT RR.SENSOR (SN)	NOT NECESSARY	320.00	-
1	FACE,RR.BUMPER (SN)	DEFORMED	369.45	369.45
1	COVER,R.RR.BUMPER (SN)	NOT NECESSARY	15.22	-
1	GARNISH,RR.BUMPER (SN)	CUT	28.12	28.12
1	COVER,L.RR.BUMPER (SN)	CUT	15.22	15.22
1	DIFFUSER ASSY,RR.PR (SN)	CUT	152.02	152.02
1	SPACER,R.RR.BUMPER SIDE (SN)	NECESSARY	12.45	12.45
1	SPACER,L.RR.BUMPER SIDE (SN)	NECESSARY	12.45	12.45
9	CLIPBUMPER (SN)	NECESSARY	13.50	13.50
1	ANTENNA ASSYL.F (SN)	NOT NECESSARY	43.57	-
1	BUZZER ASSYSMART (SN)	NOT NECESSARY	44.47	-
1	SUNDRIES (SN)	NECESSARY	30.00	10.00
			<b>1,814.85</b>	<b>1,302.37</b>
<b>LABOUR</b>				
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		80.00	80.00
	REMOVE & RENEW REVERSE SENSORS - 4 PCS.		130.00	130.00
	REMOVE & INSTALL RR WINDSCREEN.		300.00	300.00
	REMOVE, INSTALL AND RESET REAR VIEW CAMERA.		320.00	320.00
	RESET SMART ENTRY SYSTEM AND REMOVE NECESSARY.		320.00	320.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR.		350.00	280.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST & .		380.00	380.00

Report Ref No. CS/FCI18001780/Gqd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACE RR BUMPER, REPAIR RR PANEL & OTHER DAMAGE.		1,500.00	900.00
	SPRAY PAINTING ON TAILGATE, RR BUMPER, RR BUMPER.		2,000.00	1,400.00
			5,380.00	4,110.00
<b>GRAND TOTAL</b>			<b>7,194.85</b>	<b>5,412.37</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>5,412.37</b>

Report Ref No. CS/FCI18001780/Gqd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.