

23/03/2001

ASS. REC. BY:

REF: CS/FCI18001793/ T1rd3n2 Special Instruction:

Surveyor:

CWS

Taufik

ASSIGNMENT (Office)

From (Person):

Serene Ler

of

FCI

Date/Time:

30/1/18 @ 12:08 pm

Estimated Cost:

Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SJN 684J

Insured:

SHA 4179S

at Workshop m/s

Charm's Customcraft

Tel:

62717054

of

Blk 1010, Bkt Merah Lane 3 # 01-105

Policy No:

Claim No:

D18000726 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/01/2018

CA / REV / REP. / REV 24 HRS

'wp'

31/1/2018 @ Morning

H.O.D. Endorsement:

Date/Time:

12:17pm @ 30/1/18

Person Contacted:

Sharon

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJN 684J-X

SHA 4179S-NS/INC16610532/Hivbd1

D.O.A: 05/06/16

6/2/18

Sent preli thru email

Turpin

REF:

ASSIGNMENT

Region: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bel. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Date Time Action / Instruction

Van No: **5JW6845** In Page: **2009 Jun**
 Type: **MCycle** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover
 Truck / Trailer or

Make: **Lia Pianto** cc **1086**
 Colour: **Silver** A/C Insured / Std / NI / NA
 So Reading: **166004** T/Radio: Insured / Std / NI / NA

Eng No: _____
 C.No: **KNABA24329 T693524**

Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Modl: **Nil** / S/Rim / STD A/Rim or

Tyre Size: **R: 175/65R14**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Rydz**

Front: **6** mm Rear: **6** mm
 R/Bal: **6** mm L/Bal: **6** mm

D.O.A: _____ D.O.I: **5/2/18 3pm**

Survey held at: **Charns Custom.**

Des. of Damages: **Fr** / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

16/7/18 Confirm LIs \$3150 @ 6 days
 led: \$ 2631.61, 46%

RECEIVED 16 JUL 2018

Date/Time File Pass to: ☐ : Prel. Report

typist

☒ : Final Report

Date/Time File Return to:

Days Of Repair: **6**

Resurvey No. of Trip: **1**

Survey Fee

Transportation

6 HRS

Phone

Notes

Notes

Add Fee: ☐ Site Insp: \$

☐ Interview: \$

☐ Tech Insp: \$

☐ Repairs: \$

Report Format: **TP**

Lump Sum: **2150**

140

50

50

62

302



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18001793/T1rd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 30-01-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 4179S	Veh. Inspected	SJN 684J
Policy No.		Coverage (\$)	0.00
Claim No.	D18000726MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	30/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/01/2018	Inspection Date
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18000726MFSH

Our Ref: CS/FCI18001793/T1rd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJN 684J.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05/02/2017 at the premises of M/s CHARN'S CUSTOMCRAFT PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,633.75</u> .
Revised Estimate Amount	: S\$ <u>2,229.65</u> .
"Check" Items Amount	: S\$ <u>161.10</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at front and rear portion.



Yours faithfully
TAUFIKH
Automotive Assessor

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	23-01-2018	Our Ref No. D18000726MFSH
Accident Date	22-01-2018	Claim Type. Third Party
Insured Vehicle	SHA4179S	Third Party Vehicle. SJN684J
Survey Location	BLK 1010 BUKIT MERAH LANE 3 #01-105	
Contact Person.	SHARON LEE	
Contact No.	62717054/ 0	Fax No. 62736676
Survey Type	DIRECT SETTLEMENT: EST. COR - \$3,888.11	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHARN'S CUSTOMCRAFT	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234227)



PRI Documents



Close



PRI Header Details

Claim No	D18000726MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CHARN'S
Workshop Name	CHARN'S CUSTOMCRAFT (Contact Person : SHARON LEE)	Survey Location & Contact Details	BLK 1010 BUKIT MERAH LANE 3 #01-105 Mobile: 0 , Phone: 62717054 , Fax: 62736676 EmailId: CHARNS@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT: EST. COR - \$3,888.11		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA4179S	TP Vehicle No	SJN684J
PRI Recieved Date	29-01-2018 08:57:39 PM	Surveyor Appointed Date	30-01-2018 12:07:01 PM	Surveyor Accept Date	30-01-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	30-01-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Janice Lee (LKKAUTO)

From: Charn's Customcraft <charns@singnet.com.sg>
Sent: Wednesday, June 27, 2018 5:27 PM
To: Taufikh (LKKAUTO)
Cc: SUR
Subject: Finalization - SJN 684 J - Kia Picanto
Attachments: FINALIZATION.pdf; IMG_7577.JPG; IMG_7578.JPG; IMG_7579.JPG; IMG_7645.JPG; IMG_7646.JPG; IMG_7649.JPG

Importance: High
Sensitivity: Confidential

Hi




Kindly find attached for finalization.

Lumpsum @ \$3150.00 (before GST/Excess)

Please confirm

Thanks & Regards,
Sharon Lee
Charn's Customcraft
Tel: 6272 5429 Fax: 6273 6676
Email: charns@singnet.com.sg
GST Reg. No: M90367863L
Company Reg No: 25151300M

manjaniwithilan@gmail.com



Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
5 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 - 17:00
UEN: S66500200 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MCCC18011152 Vehicle Registration No: SJN 688J
Name(as shown in NRIC) : Nallaperumal Palaniyandran NRIC/FIN/Passport No : S7284360F
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : B1K280 Choa Chu Kang Ave #07364 Singapore(680289)
Contact (Tel) : _____ Mobile No. : 9722 3013
Email Address : manjariniithilan@gmail.com
Date of Accident : 22/01/18 Time of Accident : 0725
Place of Accident : AYE After Clementi
Insurance Company : Direct Asia Insurance (S) Pte Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To attach additional photos.

J Maniella
Policyholder / Driver's Signature
Date: 22/01/18
Nallaperumal Palaniyandran

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

DA/FC(SHA4179S)

DOA: 22/01/2018@0725

FIRST CAPITAL INSURANCE PTE LTD

26/01/2018

ATTN: THE MOTOR CLAIM DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SJN 684 J - KIA PICANTO 1.1(M)

CHASSIS NO: KNABA24329T693524 (2009)

1 pc	Front grille	\$	166.60	cut
1 pc	Front bumper lower ctr grille	\$	58.50	cut
1 pc	Rear boot emblem 'PICANTO'	\$	36.50	net
1 pc	Rear boot logo	\$	42.50	net
1 pc	Rear taillamp LH	\$	240.00	2x ny
1 pc	Rear bumper	\$	285.10	do
1 pc	Rear bumper reinforcement	\$	179.00	? x ny
1 pc	Rear bumper retainer LH	\$	26.50	net
6 pcs	Rear bumper clips @\$3.80	\$	22.80	net
1 pc	Rear end panel	\$	230.00	2x x
		\$	1,287.50	
	LESS 10%	\$	128.75	
		\$	1,158.75	
1 pc	Front no.plate (S/NETT)	\$	35.00	bt
1 pc	Reverse sensor (S/NETT)	\$	200.00	x ny
	Check wiring function	\$	40.00	20
FRONT	Remove necessary parts: jacking, panel beating, repair, straighten, align front inner panel, front support panel, front bonnet, front bumper and affected areas.	\$	500.00	300
	Putty and respray front inner panel, front support panel, front bonnet and front bumper.	\$	500.00	400



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

SJN 684 J - KIA PICANTO 1.1(M)

REAR Remove necessary parts: jacking, panel beating, repair,
straighten, align rear inner panel, rear end panel, rear boot,
rear fender LH, rear bumper and affected areas.

\$ 600.00 ⁴⁰⁰

Putty and respray rear inner panel, rear end
panel, rear boot, rear fender LH and rear
bumper.

\$ 600.00 ⁵⁰⁰

\$ 3,633.75

\$ 254.36

\$ 3,888.11

5527.25

ADD 7% GST

~~578161~~

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

Page 2 of 2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjong 97495749
WP

5/2/18 @ 3pm

Unpin

Resurvey after repair.

sure 1 week on

6 days

12/2/18



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

DA/FC(SHA4179S)
DOA: 22/01/2018@0725

FIRST CAPITAL INSURANCE PTE LTD

6/2/2018

ATTN: THE MOTOR CLAIM DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
S/N 684 J - KIA PICANTO 1.1(M)
CHASSIS NO: KNABA24329T693524 (2009)

Supplementary

1 pc Front bumper reinforcement
1 pc Front support panel
1 pc Air-con condenser

\$ 195.00 *bt* ✓
\$ 550.00 *ana* ✓
\$ 820.00 *bt* ✓
\$ 1,565.00
\$ 156.50
\$ 1,408.50

1 pc Radiator coolant (S/NETT)

\$ 35.00 *acc* ✓
\$ 100.00 ✓

Remove and replace front support panel & air-con condenser.

\$ 350.00 *200*
\$ 1,893.50
\$ 132.55
\$ 2,026.05

ADD 7% GST

CHARN'S CUSTOMCRAFT

.....

Tanpin 6/2/18 0130



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-B2, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62738676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

DA/FC(SHA4179S)

DOA: 22/01/2018@0725

FIRST CAPITAL INSURANCE PTE LTD

6/2/2018

ATTN: THE MOTOR CLAIM DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SJN 684 J - KIA PICANTO 1.1(M)
CHASSIS NO: KNABA24329T693524 (2009)

Supplementary

- 1 pc Front bumper reinforcement
- 1 pc Front support panel
- 1 pc Air-con condenser

\$ 195.00 *bt*
\$ 550.00 *am*
\$ 820.00 *bt*
\$ 1,565.00
\$ 156.50
\$ 1,408.50

- 1 pc Radiator coolant (S/NETT)

\$ 35.00 *rec*
\$ 100.00 *✓*

To remove & reinstall a/c assy and refill gas

Remove and replace front support panel & air-con condenser.

\$ 350.00 *200*
\$ 1,893.50
\$ 132.55
\$ 2,026.05

ADD 7% GST

CHARN'S CUSTOMCRAFT

Tanpin 6/2/18 @ 1130

Parts - 574.65
Supp - 1408.50
SPN - 70.00
Lab - 1920.00
3973.15

less 20% - 3178.52

4/5 - \$3150/-



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

DA/FC(SHA4179S)
DOA: 22/01/2018@0725

FIRST CAPITAL INSURANCE PTE LTD

26/01/2018

ATTN: THE MOTOR CLAIM DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SJN 684 J - KIA PICANTO 1.1(M)
CHASSIS NO: KNABA24329T693524 (2009)

1 pc	Front grille	\$ 166.60	cut
1 pc	Front bumper lower ctr grille	\$ 58.50	cut
1 pc	Rear boot emblem 'PICANTO'	\$ 36.50	cut
1 pc	Rear boot logo	\$ 42.50	cut
1 pc	Rear taillamp LH	\$ 240.00	R
1 pc	Rear bumper	\$ 285.10	do
1 pc	Rear bumper reinforcement	\$ 179.00	?
1 pc	Rear bumper retainer LH	\$ 26.50	cut
6 pcs	Rear bumper clips @\$3.80	\$ 22.80	cut
1 pc	Rear end-panel	\$ 230.00	R
		\$ 1,287.50	
	LESS 10%	\$ 128.75	
		\$ 1,158.75	
1 pc	Front no.plate (S/NETT)	\$ 35.00	bt
1 pc	Reverse sensor (S/NETT)	\$ 200.00	X
	Check wiring function	\$ 40.00	20

638.50
63.85
574.65

FRONT Remove necessary parts: jacking, panel beating, repair, straighten, align front inner panel, front support panel, front bonnet, front bumper and affected areas.

\$ 500.00 300

Putty and respray front inner panel, front support panel, front bonnet and front bumper.

\$ 500.00 400

700



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736876 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

SJN 684 J - KIA PICANTO 1.1(M)

REAR Remove necessary parts: jacking, panel beating, repair,
straighten, align rear inner panel, rear end panel, rear boot,
rear fender LH, rear bumper and affected areas.

\$ 600.00 ⁴⁰⁰ } 900

Putty and respray rear inner panel, rear end
panel, rear boot, rear fender LH and rear
bumper.

\$ 600.00 ⁵⁰⁰

\$ 3,633.75

\$ 254.36

\$ 3,888.11

ADD 7% GST

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

Page 2 of 2

Tanjik 97495749
- WP

5/2/10 @ 3pm

Unyson

Respray after repair.

sure 1 hour to 1.5 hrs

6 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001793/T1rd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-07-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4179S	Veh. Inspected	SJN 684J	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18000726MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	30/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA PICANTO	c.c	1086	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KNABA24329T693524	Colour	SILVER	
Odometer	166004	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/65 R14	RYDANZ	6 mm	
L/H Front Tyre	175/65 R14	RYDANZ	6 mm	
R/H Rear Tyre	175/65 R14	RYDANZ	6 mm	
L/H Rear Tyre	175/65 R14	RYDANZ	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/01/2018	Inspection Date	05/02/2018	
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 684J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT GRILLE	CUT	166.60	166.60
1	FRONT BUMPER LOWER CTR GRILLE	CRACKED	58.50	58.50
1	REAR BOOT EMBLEM "PICANTO"	NECESSARY	36.50	36.50
1	REAR BOOT LOGO	NECESSARY	42.50	42.50
1	REAR TAILLAMP LH	NOT NECESSARY	240.00	-
1	REAR BUMPER	DEFORMED	285.10	285.10
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	179.00	-
1	REAR BUMPER RETAINER LH	NECESSARY	26.50	26.50
6	REAR BUMPER CLIPS @\$3.80	NECESSARY	22.80	22.80
1	REAR END PANEL	TO REPAIR SEE LABOUR	230.00	-
1	FRONT BUMPER REINFORCEMENT (ADDITIONAL)	BENT	195.00	195.00
1	FRONT SUPPORT PANEL (ADDITIONAL)	CRACKED	550.00	550.00
1	AIR-CON CONDENSER (ADDITIONAL)	BENT	820.00	820.00
	LESS 10% DISCOUNT		-285.25	-220.35
			2,567.25	1,983.15
SPECIAL NETT ITEMS				
1	FRONT NO PLATE (SN)	BENT	35.00	35.00
1	REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
1	RADIATOR COOLANT (SN)(ADDITIONAL)	NECESSARY	35.00	35.00
			270.00	70.00
LABOUR				
	CHECK WIRING FUNCTION.		40.00	20.00
	REMOVE NECESSARY PARTS;JACKING,PANEL BEATING,REPAIR,STRAIGHTEN,ALIGN FRONT INNER PANEL,FRONT SUPPORT PANEL,FRONT BONNET,FRONT BUMPER AND AFFECTED AREAS.		500.00	300.00
	PUTTY AND RESPRAY FRONT INNER PANEL,FRONT SUPPORT PANEL,FRONT BONNET AND FRONT BUMPER.		500.00	400.00
	REMOVE NECESSARY PARTS;JACKING,PANEL BEATING,REPAIR,STRAIGHTEN,ALIGN REAR INNER PANEL,REAR END PANEL,REAR BOOT,REAR FENDER LH,REAR BUMPER AND AFFECTED AREAS.		600.00	400.00

Report Ref No. CS/FCI18001793/T1rd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND RESPRAY REAR INNER PANEL, REAR END PANE, REAR BOOT, REAR FENDER LH AND REAR BUMPER.		600.00	500.00
	TO REMOVE & REINSTALL A/C ASSY AND REFILL GAS (ADDITIONAL).		100.00	100.00
	REMOVE AND REPLACE FRONT SUPPORT PANEL & AIR-CON CONDENSER (ADDITIONAL).		350.00	200.00
			2,690.00	1,920.00
GRAND TOTAL			5,527.25	3,973.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,150.00

Report Ref No. CS/FCI18001793/T1rd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.