



# 創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M

DA/FC(SHA4179S)

DOA: 22/01/2018@0725

FIRST CAPITAL INSURANCE PTE LTD

6/2/2018

ATTN: THE MOTOR CLAIM DEPT

THIRD PARTY CLAIM  
ESTIMATE COST OF REPAIR FOR VEHICLE NO:  
SJN 684 J - KIA PICANTO 1.1(M)  
CHASSIS NO: KNABA24329T693524 (2009)

## Supplementary

|      |                                                             |             |       |
|------|-------------------------------------------------------------|-------------|-------|
| 1 pc | Front bumper reinforcement                                  | \$ 195.00   | bt ✓  |
| 1 pc | Front support panel                                         | \$ 550.00   | ana ✓ |
| 1 pc | Air-con condenser                                           | \$ 820.00   | bt ✓  |
|      |                                                             | \$ 1,565.00 |       |
|      | LESS 10%                                                    | \$ 156.50   |       |
|      |                                                             | \$ 1,408.50 |       |
| 1 pc | Radiator coolant (S/NETT)                                   | \$ 35.00    | rec ✓ |
|      | To remove & reinstall a/c assy and refill gas               | \$ 100.00   | ✓     |
|      | Remove and replace front support panel & air-con condenser. | \$ 350.00   | 200   |
|      |                                                             | \$ 1,893.50 |       |
|      | ADD 7% GST                                                  | \$ 132.55   |       |
|      |                                                             | \$ 2,026.05 |       |

CHARN'S CUSTOMCRAFT

.....

Tanpin 6/2/18 2130