

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

30-Jan-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6053 Y

1 pc	Front bumper ✓	\$	531.00
1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper o/s side retainer @ \$16.00 ✓	\$	16.00
1 pc	Front o/s wheel cover ✓	\$	116.00
1 pc	Front o/s fender X <i>Hydi</i>	\$	384.00
1 pc	Front o/s fender inner shield X	\$	120.00
1 pc	o/s mirror assy ✓	\$	590.00
		\$	<u>1,801.00</u>
		Less 10%	\$ 180.10
		\$	<u>1,620.90</u>

S/NETT

1 set	Front o/s fender inner shield clips X	\$	28.00
1 set	Front bumper clips ✓	\$	48.00
1 pc	Front o/s fender sticker X	\$	30.00
1 set	o/s door sticker ✓	\$	100.00

Sundry

\$ ~~50.00~~ 20

To check wheel alignment

\$ ~~80.00~~ 60

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ ~~180.00~~ X

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper, o/s windscreen pillar

\$ ~~700.00~~ ⁵⁰⁰ ~~400~~

To putty and spray painting on front bumper, front o/s fender, o/s side mirror, front o/s door, o/s windscreen pillar

\$ ~~1,000.00~~ ⁶⁹⁰ ~~390~~

To apply rustproofing on the repaired and replaced panels.

\$ ~~200.00~~ 50

\$ 4,036.90

LKK Auto Consultants hence notify the Repairer of the following:
(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalvin LKK
30/1/18 1545h
3 071.
4/5
After Repair photo