



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CS/EQI18001801/Uvd3e2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 11-04-2018



Code : EQI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	FBL 4918P
Policy No.	DMMCHQ17-000005	Coverage (\$)	0.00
Claim No.		Excess (\$)	300.00
Assign From	BAZLIN AHMAD	Assign Date	30/01/2018

2. Vehicle Particulars & Condition

Make & Model	ADIVA AR3	c.c	171
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RGVTC40AAGA000093	Colour	RED
Odometer	19547	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70-14	MAXXIS	8 mm
L/H Front Tyre			mm
R/H Rear Tyre	120/80-12	PIRELLI	8 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND THE BODY STRUCTURE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/01/2018	Inspection Date	30/01/2018
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

5a. Remarks

- A)THE MARKET VALUE IS S\$15,000.00(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
--	-----------------------