



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC6/EQ18001804/Kwa3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 30-01-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 1775K	Veh. Inspected	SLP 3471C
Policy No.	DMCPHQ17-003586	Coverage (\$)	0.00
Claim No.	DM18HO00071-JG	Excess (\$)	0.00
Assign From		Assign Date	30/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	05/01/2018	Inspection Date	25/01/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

H.H.H. Kenneth
Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

06
SLP3471C
TP/EG

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

Claim No: ES1890080
Estimate No: ES1890080/YISHUN
Date: 24 Jan 2018
Policy No: 5092056922
Veh Reg No: SLP3471C
Make/Model: SUZUKI SWIFT 1.3A
Chassis No: ZC11S191845
Engine No: M13A1918830
Reg. Date: 04/08/2007

TEL: 62239433
ATTN: Motor Claim Department
WS Ref: TP/EQ/YS
Claim Type: Third Party
Accident Date: 05/01/2018
TP Veh Reg No: GBF1775R

FAX: 62243903

Not Authorized
As 61 Day @ 1300
Passing After Paint 4 days

Estimate Repair Cost to Vehicle No : SLP3471C

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
Cost Plus				
1 FRONT BUMPER	450.00	1 PC	<i>Re</i> 450.00	✓
2 FRONT BUMPER RH SIDE RETAINER	20.00	1 PC	<i>Re</i> 20.00	✓
3 FRONT BUMPER TOP BEAM	120.00	1 PC	<i>Re</i> 120.00	X
4 FRONT BUMPER CLIPS	1.50	6 PCS	<i>Re</i> 9.00	✓
5 FRONT BUMPER RH FOG LAMP GARNISH	18.00	1 PC	<i>Re</i> 18.00	X
6 RH HEADLAMP	240.00	1 PC	<i>Re</i> 240.00	✓
7 FRONT RH FENDER	105.00	1 PC	<i>Re</i> 105.00	X
8 FRONT WIPER TANK	45.00	1 PC	<i>Re</i> 45.00	X
			1,007.00	
	Add 20%		201.40	1,208.40
Labour				
9 REMOVE & REFIX FRT BUMPER ASSY, HEADLAMP, FRT RH FENDER, KNOCK & REPAIR FRT SUPPORT PANEL & REALIGN THE SAME	500.00	1 LA	500.00	<i>400</i>
10 PUTTY & RESPRAY ON FRT RH FENDER, FRT SUPPORT PANEL, FRT BUMPER	480.00	1 LA	480.00	<i>400</i>
11 RUSTPROOFING	30.00	1 LA	30.00	X
				1,010.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total	SS 2,218.40
Add GST @ 7%	155.29
Total Amount payable	<u>SS 2,373.69</u>

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/EQI18001804/Kwa3

Date: 31.01.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.


SLP 3471C

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25.01.2018 at the premises of M/s Cheng Hoe Motor Pte Ltd (Yishun) and have the following to report:-

Workshop Estimate Amount	: S\$	2,218.40
Revised Estimate Amount	: S\$	1,300.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
O/S Front portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 4.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2713G
Vehicle Details	
Vehicle No.:	SLP3471C
Vehicle to be Exported:	Yes
Intended De-registration Date:	05 Jan 2018
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT 1.3 A
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	M13A1918830
Chassis No.:	ZC115191845
Maximum Power Output:	67.0 kW (89 bhp)
Open Market Value:	\$10,694.00
Original Registration Date:	04 Aug 2007
First Registration Date:	04 Aug 2007
Transfer Count:	1
Actual ARF Paid:	\$11,764.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$24,100.00
COE Rebate Amount:	\$22,026.00
Total Rebate Amount:	\$22,026.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 05 Jan 2018

OK

Mei Kwan (LKKAuto)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Friday, 9 March, 2018 3:52 PM
To: Mei Kwan (LKKAuto)
Cc: Vivian Lau (LKKAuto); Joy Irene (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving GBF1775K (OI : EQI - DM18HO00071-JG) AND SLP3471C (TP : LKK REF - CC6/EQI18001804/Kwa3) on 05/01/2018
Attachments: GBF1775K.PDF
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Mei Kwan

Attached our insured's accident report for your attention.
Please take note that our insured's vehicle is GBF1775K

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, March 7, 2018 10:02 AM
To: Joel Goh
Cc: Vivian Lau (LKKAuto); Joy Irene (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving GBF1775R (OI : EQI - TBA) AND SLP3471C (TP : LKK REF - CC6/EQI18001804/Kwa3) on 05/01/2018

Dear Joel,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

Date:

22 FEB 2019

EQ Insurance Co Ltd
C/O LKK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. SLP3471C & GBF1775R ON 05/01/2018
BLK 407 YISHUN AVE 6 OPEN CAR PARK.**

We are authorized by SLP3471C for their above matter.

Record reveals that you are the insurer of GBF1775R. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 1391.00
2. Loss of Use	S\$ 150.00
3. Hire of Vehicle	S\$ 0.00
4. LTA Search Fee/GIA Reports	S\$ 8.00
TOTAL	S\$ 1549.00

Please let us have your reply soonest possible.

Thank you.

Yours faithfully





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/EQ118001804/Kwa3

03 April 2018

Advance Pest Management

7 Soon Lee Street

#05-29 iSpace

Singapore 627608

Dear Sir/Madam,

ACCIDENT INVOLVING GBF 1775K AND SLP 3471C ON 05/01/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau

Case Handler

DID: 6841 8625

FAX: 6741 4108

EMAIL: Vivianlau@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)

LETTER OF AUTHORISATION

(FOR PROPERTY DAMAGE CLAIM ONLY)

Re: Motor Insurance Claim SLP3471C
in respect of the traffic accident on 5/1/2018
at/along Blk 407 Yishun Ave 6 Open Carpark

I/We, Goh Meng Yam
NRIC S1302713G of Blk 407 Yishun Ave 6 #12-1294
Singapore 760407
owner of motor vehicle SLP3471C, insured by NIUC Income Insurance
Co-operative Ltd under policy no. 5092056922

hereby authorise **M/s CHENG HOE MOTOR PTE LTD** on Blk 1019 Yishun Industrial Park A #01-374 Singapore 768761, to act as my/our representative in my/our claim against the owner /driver of motor vehicle GBF1775R in respect of the above-mentioned accident.

I/We further authorise that any payment due to me/us from the aforesaid claim is to be directed to my/our abovenamed representative.

And I/We hereby indemnify my/our abovenamed representative against any claim and/or damage which may arise from any action taken on my/our behalf.

I/We affirm all the above by my/our signature below.

Signed : 
Date : 5/1/2018

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department
WS Ref: TP/EQ/YS
Claim Type: Third Party
Accident Date: 05/01/2018
TP Veh Reg No: GBF1775R

NO: CL8190032
Date: 23 Jan 2019
Policy No: 5092056922
Veh Reg No: SLP3471C
Make/Model: SUZUKI SWIFT 1.3A
Job No: JC1599039

Description	Quantity	List Price	PAGE:1
			Amount
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	SS 1,300.00	SS 1,300.00

Total	SS 1,300.00
Add GST @ 7%	91.00
Total Amount payable	SS 1,391.00

For Cheng Hoe Motor Pte Ltd

E. & O. E.


AUTHORISED SIGNATURE

A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS
COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 058358

TEL : 6538 7411 & FAX : 6534 1011

TO : CHENG HOE MOTOR PTE LTD		BILL NO: B018 / 2018	
YOUR REF:			
OUR REF : ACS.CH.LTA.2018 (JAN 2018)		DATE : 5/2/18	
TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary consultations, attendance preparation examination of documents relating thereto; correspondence, attendance, perusals, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.			
LTANET SEARCHES FOR THE MONTH JAN 2018			
S/NO	TP NO.	CHM	DOA
1	2/1/2018	SJS7547A	GY5366Y 30/12/2017
2	2/1/2018	SKL4956Y	SJR4742C 29/12/2017
3	2/1/2018	SKQ6059Y	SKW7049M 1/1/2018
4	3/1/2018	SKE1673U	SJR2885L 3/1/2018
5	3/1/2018	YP6455B	SJU4191B 30/12/2017
6	3/1/2018	SGF3587P	SJG2424S 27/12/2017
7	3/1/2018	SKU8016L	SKS1610C 30/12/2017
8	5/1/2018	GBC1376U	SLP6769A 4/1/2018
9	8/1/2018	SKD5999J	SJJ4139L 6/1/2018
10	8/1/2018	GBF1775K	SLP3471C 5/1/2018
11	8/1/2018	SFM9595B	SJR592U 30/12/2017
12	8/1/2018	FBL3571L	SLH9325U 5/1/2018
13	11/1/2018	SFY4710E	SCZ1001T 10/1/2018
14	11/1/2018	GBB2710L	GBG5663T 11/1/2018
15	12/1/2018	SLJ4826M	SGY1911A 11/1/2018
16	12/1/2018	YL6367T	SKP9455A 9/1/2018
17	12/1/2018	GBC4242C	SJZ3236L 22/12/2017
18	13/1/2018	SKN5668L	SJL2414U 13/1/2018
19	14/1/2018	SJX1232X	SLF4986E 11/1/2018
20	14/1/2018	GU4511Y	SJX9477D 11/1/2018
21	14/1/2018	SLK1743H	SJF4726M 11/1/2018
22	14/1/2018	SJQ8960T	SJK2043L 11/1/2018
23	15/1/2018	SLG964P	GBG821L 10/1/2018
24	15/1/2018	SKP8802K	SJU8089M 13/1/2018
		sub-total c/f	<u>S 192.00</u>
			
M/s. A C SYED & PARTNERS ADVOCATES & SOLICITORS SINGAPORE			
We reserved the right to forward a subsequent bill for any disbursements omitted herein.			
E. & O.E.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 03/05/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBF 1775K (Insd Veh)	Your Ref. No. : DM18HO00071-JG
	SLP 3471C (TP Veh)	Our Ref. No. : CC6/EQI18001804/Kwa3q2
Date of Accident	5/1/2018	

Liability	100% ✓	
Final Repair Cost	: \$ 1,391.00	
Loss of Use	: \$ 150.00	3 days
Rental (if any)	: \$ ✓	days
Others:	: \$ 8.00	
	: \$ ✓	
	1,549.00 ✓	
Final Settlement Sum	: \$ 1,549.00	
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	CHENG HOE MOTOR PTE LTD	: \$ 1,549.00
		: \$

JOANNE LEE
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQ18001804/Kwa3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 03-05-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 1775K	Veh. Inspected	SLP 3471C
Policy No.	DMCPHQ17-003586	Coverage (\$)	0.00
Claim No.	DM18HO00071-JG	Excess (\$)	0.00
Assign From		Assign Date	25/01/2018

2. Vehicle Particulars & Condition

Make & Model	SUZUKI SWIFT (A)	c.c	1328
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	ZC11S191845	Colour	METALLIC SILVER
Odometer	133934	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R14	CONTINENTAL	8 mm
L/H Front Tyre	175/65 R14	CONTINENTAL	8 mm
R/H Rear Tyre	175/65 R14	CONTINENTAL	8 mm
L/H Rear Tyre	175/65 R14	CONTINENTAL	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/01/2018	Inspection Date	25/01/2018
Survey held at	CHENG HOE/MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 3471C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (WCP)	BUCKLED	450.00	450.00
1	FRONT BUMPER RH SIDE RETAINER (WCP)	DISTORTED	20.00	20.00
1	FRONT BUMPER TOP BEAM (WCP)	TO REPAIR SEE LABOUR	120.00	-
6	FRONT BUMPER CLIPS @\$1.50 (WCP)	NECESSARY	9.00	9.00
1	FRONT BUMPER RH FOG LAMP GARNISH (WCP)	SERVICEABLE	18.00	-
1	RH HEADLAMP (WCP)	CUT	240.00	240.00
1	FRONT RH FENDER (WCP)	TO REPAIR SEE LABOUR	105.00	-
1	FRONT WIPER TANK (WCP)	SERVICEABLE	45.00	-
	COST PLUS 20%		201.40	143.80
			1,208.40	862.80
LABOUR				
	REMOVE & REFIX FRT BUMPER ASSY ,HEADLAMP ,FRT RH FENDER ,KNOCK & REPAIR FRT SUPPORT PANEL & REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER TOP BEAM AND FRONT RH FENDER .		500.00	400.00
	PUTTY & RESPRAY ON FRT RH FENDER ,FRT SUPPORT PANEL ,FRT BUMPER.		480.00	400.00
	RUSTPROOFING.	NOT NECESSARY	30.00	-
			1,010.00	800.00
GRAND TOTAL			2,218.40	1,662.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,300.00

Report Ref No. CC6/EQ18001804/Kwa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Friday, 10 May 2019 3:53 PM
To: 'Joel Goh'
Subject: TP Direct Settlement - Accident Involving GBF 1775K (OI) and SLP 3471C (TP) on 05/01/2018
Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933