

Attm Kenneth
Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

06
SLP3471C
TP/ED

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

Claim No: ES1890080
Estimate No: ES1890080/YISHUN
Date: 24 Jan 2018
Policy No: 5092056922
Veh Reg No: SLP3471C
Make/Model: SUZUKI SWIFT 1.3A
Chassis No: ZC11S191845
Engine No: M13A1918830
Reg. Date: 04/08/2007

TEL: 62239433
ATTN: Motor Claim Department
WS Ref: TP/EQ/YS
Claim Type: Third Party
Accident Date: 05/01/2018
TP Veh Reg No: GBF1775R

FAX: 62243903

Not available
As b/sy @ 1300
Passing After Pain
4 days

Estimate Repair Cost to Vehicle No : SLP3471C

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 FRONT BUMPER	450.00	1 PC	450.00	✓
2 FRONT BUMPER RH SIDE RETAINER	20.00	1 PC	20.00	✓
3 FRONT BUMPER TOP BEAM	120.00	1 PC	120.00	X
4 FRONT BUMPER CLIPS	1.50	6 PCS	9.00	✓
5 FRONT BUMPER RH FOG LAMP GARNISH	18.00	1 PC	18.00	X
6 RH HEADLAMP	240.00	1 PC	240.00	✓
7 FRONT RH FENDER	105.00	1 PC	105.00	X
8 FRONT WIPER TANK	45.00	1 PC	45.00	X
			1,007.00	
	Add 20%		201.40	1,208.40
Labour				
9 REMOVE & REFIX FRT BUMPER ASSY, HEADLAMP, FRT RH FENDER, KNOCK & REPAIR FRT SUPPORT PANEL & REALIGN THE SAME	500.00	1 LA	500.00	400
10 PUTTY & RESPRAY ON FRT RH FENDER, FRT SUPPORT PANEL, FRT BUMPER	480.00	1 LA	480.00	400
11 RUSTPROOFING	30.00	1 LA	30.00	X
				1,010.00
			Total	S\$ 2,218.40
			Add GST @ 7%	155.29
			Total Amount payable	<u>S\$ 2,373.69</u>

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE