195/2010 INS. GASE OWNER		CC 3/EQ11800	1809,K	1 104 1	KK: DAC:	
4134	^	ASSIGN 7	MENT			
Sunfeyor:	Ank	DOI:	107-18	Date / Time :	29-01-18	
Pre-assign / CCU	1881	4501 L Bodullay	Claim No. Policy No.	Registered in Merime	FINIS	psodrb3
Insured Tel No. Excess Sec II :SS Is driver the owner	8	HP: 43813183 D.O.A.: 26-01-18 Nature of Accident:	Make / Model Place of Accide	tone	a chyon)
If NO, Driver Nan	No. :	(V/L: YES / NO)	OI GIA REPOR	RT: YES / NO; TP GI y: % F	IA REPORT: YES inal? Yes/No	/ NO
SHB 6711	<u> </u>				•	
INSRS: WSP: Tel: Liability: RMKS:	INSRS: WSP: Tel: Liabilit RMKS:	,	INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel; Liability; RMKS:	0
Date/ Time	(M. AMIL X	TRE UNITE X		STAGE	DVZ	E/PIC
7576	OID HIT	TT FROM	Rtak	Non-Reporting ltr (1st) Non-Reporting ltr (2nd) Non-Reporting ltr (Fina):	E/PIC
	BOLA 27		KC///K	Notification ltr (if non- Call Ol:		-6-18
26-6-18	@ 210 - 0	IND ANS	WER	After call ltr to Ol: Documentation Check	List: Handler	Typist
	@ 204 PM -	OI NO BUCY	TONE	Notification ltr (if non-	pickup) 😾	
28-6-18	0 2041	01 70- 6007	(01-0	After call ltr to OI: Authorisation To Act:		
29-6-18	@ 1107 - 0	1 JAID HE W	AS	Release Voucher:		
	CH	ALGED FOR	TD E	Final Repair Bill: Car Rental Invoice:		
	A	ARGED FOR AWARE NOD	ISJUE .	Towing Invoice	X	
	F	Norne 1-0		LTA / GIA :	- 4	
				Medical Bill: PIR:		
RECEIVE	D 1 8 JUL 2018			Mandate/Reject Instru	uction:	
				Payment Breakdown	Form:	
PRELIMINARY ADVICE	Date/Time: 71/1	Sent By:		Post-Repair Photos: Others: \(\frac{1}{2}\)\(\frac{1}{2}\)		
FINALIZATION	Date/Time:	Confirm with:		Confirm by:		
Repair Cost:	55 (8.75.18	days) Reduction:	96		mail Call	
FINAL SETTLEMENT Final Liability:	The state of the s	Assessed) BOLA S/N No. :	DIO NIL	Email Call If NO or B 28, Ass. I	int	
Repair Cost: 65T	ss 3. C84. Co	Assessed) BOLA S/N No.:	PIR	11 NO 01 B 20, ASS. I	.045 ;	
Loss of Rental (LOR):	SS 400.78(2.	5 days) (60.31	×TP		RIVER	
Loss of Use (LOU):	SS (S X		VIDED		1	
Loss of Income (LOI): LOR only LOU only		OR + LOI [Tick only on	8. 199	(b) ()	19/18	_
GIA/LTA Search	ss 7.49	THEK ONLY ON	c ₁			
Medical:	SS -			1) Claim status: Norn	nal/Reject/Private	Settle
Disbursement:	S\$ -	(e.g. Tow/ Independe	nt)	2) Report Format:		*.
Legal Cost Total:	ss 4 117 77;	Global Sum SS: 4, 115	· X 1	3) Survey fee:		
FINAL PAYMENT	Date/Time:	Confirm with:		Email Call		
Payee 1:	ss 4,115-xx	Name 1: COMFORT	ELGRO E	HGINEERI	NG PIE	LTD
Payee 2: (Strike if N.A.)	SS 4	Name 2:				
Payee 3: (Strike if N.A.)	ss	Name 3:				

Syrvenic Kalvin REF.	
A.	SSIGNMENT
From Date Estimated Cost	SHB 6411 L 29 Apr 2019 Type M.Car / M.Cycle / Bus / Van / Lorry / Tai / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	7,0000
	Make Murcher Prot Viono
To inspect Vehicle No	1-/16
at Workshop m/s	Colcur = C Insy ed / Std / NI / NA
of	Sp Reading 5 67 611 Radio Institled / Std / Nt / NA
insured	Eng/No
Policy No.	CNO. WOF 6398132381134
Claims No	Gen Cond. Good / Fago Poor / Burnt
Sum Insured. Excess	Steering Inorgy / Jammed / Leaked / Burnt or
(Client's Record)	Brake Inorder Jammed Leaked Burnt or
Make of Veh	Modi: Nil / S/Rim / STD Rim or
	Tyre Size F: 225/60116c
(Policy Condition)	R.
Remark: The veh had commenced its N/S 0.5	BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOTYOKO OF Hankerk.
Sal or Market Value.	Front Rear
DAC Accident Rport Consistent? Yes or No	RBal 7 mm RBal 3
GIA PR Seen: Consistent? Yes or No	LBai 7 mm Lbai 7 mm
Est Repairs 3 days Res Yes or No	DOA 26/1/18 DOI 29/1/8
Lum Sum: % 3 Val. Yes or No	Survey held at CPSE (G-1
CA / REV / REP. / 24 HRS	Des. of Damages Frt / Bear / Q/S / N/S / U/C / Rooftop or
Vehicle IN/Ou	7 10 11
Date. Person Contacted	The U/C / Chassis frame / Body Structure affected due to collision
Date Time Action Instruction 2/1/15 - While 45 \$3750/ 3/1/2	EQ 41
	P(\$1,898.58/367.)
	The color was
Constitute File Pass IST Prelli, Report	Days Of Repair:
: Final Report	Resurvey No. of Trip:
Cate/Tune File Raturn (C)	Transcotutor
Add Fe	
	Inter Ex S
Report Format	Test S
Lump Sum / I.B.I: 3	Western S

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305111471 ComfortDelGro Engineering Pte Ltd 59 Loyang Drive: Singapore 508969 Fax: 6546 8156 01/02/18 Date FINALIZATION FORM LKK Fax: To KALVIN ANG Attn : Vehicle Reg No. : SHB6711L Date of Accident : 26-Jan-18 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:---- FBB4561L The repair job shall bill to: EQ INS 2. The finalized amount shall be: (a) Spare Parts after List discount (b) Labour Charges Total for Part-By-Part Repair Cost (c.) Lumpsum Repair (if applicable) \$3,350.00 Total for Lumpsum repair cost after Less: 20% \$3,350.00 Final Lumpsum Repair cost Estimated normal period for repairs: _____3 ___working days. 3. We shall treat the above amount as Correct and Confirmed if there is no reply from you 4 within 7 working days We confirm the estimates and 5. Thank you for your assistance. finalized amount Signature Signature: KALVIN : LIMTS Name Name 62148398 Date Tel Fax 65468156 For Official Use Only Document Confirm By Attached Remarks Item Amount (Signature) Yes or No 1. Rental Rate P/Day YES 2. Loss of Income Paid 3. Survey Fees LTA Search Fee 5. Medical Fees (on behalf of driver, if applicable) Overrun Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHB 6711L

MAKE

MODEL : MERCEDES BENZ VIANO (REAR)

EQ-HS

DATE 29/1/2018 15:21

LKK-Kalvin

Type Unit Price Amount	Parts Description/ Labour
\$ 473.6	Bumper R/H Side, RR
\$ 61.9	Tail Lamp Lower Garnish, RH XM
\$ 105.7	Tail Lamp Reflector Upper, RH
\$ 3,188.0	Rear Fender (RH)
\$ 56.4	Rear Fender Protector (RH) × 5
SUB TOTAL \$ 3,885.7	SUB TOTAL
LESS 20% S 777.1	LESS 20%
	DISCOUNTED TOTAL
600	Labour Charge
S 1,000.0	Panel Beating
\$ 500.0	Spray Painting Charge
\$ 50.0	Wiring Charge
\$ 59.0	Tuff Kote
- 1 1000	Remove/Refix Cushion & Upholstery Rear
ealant) \$ 150:0	Remove/Refix Rear Windscreen Glass (sealant)
\$ 120.0	Remove/Refix Reverse Sensor
\$ 120.0	Rear Wheel Alignment
AL LABOUR \$ 2,140.0	TOTAL LABOUR
S 5,248.5	ESTIMATE TOTAL
	Kahi (CKK)
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey beforelafter spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurant Acknowledged by Repairer Signature: Date:	1 29/1.8 1545hs. 3 Pays 4/1 Athe Ry-pll
To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary items) must be resurveyed and is subject to final approval from Insurant Acknowledged by Repairer Signature: Date:	1 29/18 1545/2

Mei Kwan (LKKAuto) From: Francis Ng <francis.ng@eqinsurance.com.sg> Friday, 22 June, 2018 11:46 AM Sent: To: Mei Kwan (LKKAuto) Vivian Lau (LKKAuto); Admin A; Joy Irene (LKKAuto); Janet Tan Cc: Subject: RE: Direct Settlement - Accident Involving FBB4561L (OI: CTI - DM18HO00556) AND SHB6711L (TP: LKK REF - CC3/EQI18001809/K1ja3) on 26/01/2018 Attachments: FBB4561L 26.01.2018.PDF Follow Up Flag: Follow up Flag Status: Completed Categories: HMK Dear Mei Kwan, Our insured's report is attached. Regards, Francis Ng Executive | Claims × EQ Insurance Company Limited 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190 www.eqinsurance.com.sg × Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Friday, June 22, 2018 11:15 AM

To: Francis Ng <francis.ng@eqinsurance.com.sg>

Cc: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto)

<Joylrene@lkkauto.com>; Janet Tan <janet.tan@eqinsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving FBB4561L (OI: CTI - DM18HO00556) AND SHB6711L (TP: LKK

REF - CC3/EQI18001809/K1ja3) on 26/01/2018

Dear Sir /Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

From: Bazlin Ahmad [mailto:bazlin.ahmad@eqinsurance.com.sg]

Sent: Tuesday, 13 March, 2018 5:20 PM

To: Mei Kwan (LKKAuto) < Meikwan@lkkauto.com>

Cc: Joy Irene (LKKAuto) < Joylrene@lkkauto.com >; Vivian Lau (LKKAuto) < vivianlau@lkkauto.com >; Admin A < admin-

a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving FBB4561L (OI : CTI - DM18HO00556) AND SHB6711L (TP : LKK

REF - CC3/EQI18001809/K1ja3) on 26/01/2018

Dear Mei Kwan

We refer to the above claim reference.

Our insured has yet lodge the GIA report.

Traffic Police has yet release his bike from TP compound.

In the meantime, can you kindly request and forward us video footage from SHB6711L.

Thank You.

Regards, Lynn Ahmad Executive | Claims

eqnsurance

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190 www.eqinsurance.com.se.



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

you've got a friend

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Tuesday, February 6, 2018 10:31 AM

To: Bazlin Ahmad

Cc: Joy Irene (LKKAuto); Vivian Lau (LKKAuto); Admin A

Subject: RE: Direct Settlement - Accident Involving FBB4561L (OI : CTI - TBA) AND SHB6711L (TP : LKK REF

CC3/EQI18001809/K1ja3) on 26/01/2018

Dear Lynn,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

OMFORTDELGRO ENGINEERING

member of COMFORTDUCKO		Date/Time	: 29.01.2018	14:04	Page	: 1	
am: ARC Repair TP(CLSO)1	JOE	CARD Sal	les Order:		JC NO.305	111471	
MER			REGN NO SHB6711L		MILEAGE		
COMFORT TRANSPORTATION 7010045	PTE LTD		MAKE MERCEDES BI	ENZ	FUEL E	1/2 F	
Singapore SINGAPORE 575	5717		MODEL VIANO CDI 2	2.2L 29			
(P) 65508755 (O)			24.04.2014		TARGET DA	\$TE	
UNT CARD NO.			CHASSIS CODE 98132	3811341	COMPLETIC	N DATE/TIME:	
cident Date: 26.01.2018 TURE: 3P 26.01.18/C	JOB D	ESCRIPTION					
NO LABOR CODE		DESCRIP	TION				
				3			
4							
KED & PASSED OUT BY:							
SERVICE ADVISOR		*		USTOMER'S S	SIGNATURE		
edgement Slip	*	xit Pass					
SHB6711L LIMTS	Ň	ehicle No.:	6711L				

urned to Service Reception upon collection

Service Advisor

Signature/Date

Name of Service Advisor

Date

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHB 6711L

MAKE :

MODEL

: MERCEDES BENZ VIANO (REAR)

EQ-45

DATE 29/1/2018 15:21

LKK-Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Aı	mount
	Bumper R/H Side, RR			\$	473.60
	Tail Lamp Lower Garnish, RH XM			S	61.90
	Tail Lamp Reflector Upper, RH /			\$	105.74
	Rear Fender (RH)			\$	3,188.00
	Rear Fender Protector (RH) ×			S	56.48
	SUB TOTAL			s	3,885.72
	LESS 20%			S	777.14
	DISCOUNTED TOTAL			\$	3,108.58
	Labour Charge Panel Beating Spray Painting Charge Wiring Charge Tuff Kote Remove/Refix Cushion & Upholstery Rear Remove/Refix Rear Windscreen Glass (sealant) Remove/Refix Reverse Sensor		*	\$ \$ \$ \$ \$ \$	1,000.00 500.00 50.00 50.00 150.00 150.00 120.00
	Rear Wheel Alignment			S	120.00
	TOTAL LABOUR			\$	2,140.00
	ESTIMATE TOTAL			S	5,248.58
	Kaki (CKK) 1 29/18 1545hs				
	Kahi ((KK) A 29/1/8 1545hs. 3 Pays Hh Rywyll	the Repair To resurvey To display a Parts prices Third party No illegal in Supplement is subject to Acknowledge	Consultants hence notify or of the following: before/after spray painting amaged part(s) during resurvey are subject to confirmation survey is on a Without Prejudice oddicate the safe wed are item(s) in a renurveyed a final approval part in courance to Prepudice to		
		Signature: Date:			
	This is an initial estimate based on a visual inspection of the a be prepared after the vehicle is surveyed by a motor Surveyor				

Auto Consultants Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

TBA

Our ref:

CC3/EQI18001809/K1ja3

Date:

31.01.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SHB 6711L

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29.01.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd (Loyang) and have the following to report:-

Workshop Estimate Amount	: S\$	5,248.58
Revised Estimate Amount	: S\$	4,183.87
"Check" Items Amount	: S\$	(a)
Market Value	: S\$	
LTA Reimbursement Value	: S\$	(#)
Nett Value	: S\$	5.0

Description of Damage:

The vehicle sustained damages at the

O/S Rear portion

rear from

Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0

3.0 days

Yours faithfully,

KALVIN ANG

Licensed Appraiser





e-Services (/content/policehubhome/homepage.html)

Log in *

Status of Driving Licence

Qualified Driving Licence

Qualified Driving Licence Number

S9431073C

Status of Qualified Driving Licence

Valid

Class(es) of Qualified Driving Licence

2A.2B

Expiry Date

Valid for life unless revoked, suspended or disqualified

Provisional Driving Licence

Provisional Driving Licence Number

S9431073C

Status of Provisional Driving Licence

Expired (Click here for explanation)

Classias of Provisional Driving Licence

HOME (https://www.police.gov.sg/)

ABOUT US (https://www.police.gov.sg/about-us)

SGSECURE (https://www.police.gov.sg/sgsecure)

I-WITNESS (https://www.police.gov.sg/iwitness)

COMMUNITY PROGRAMMES (https://www.police.gov.sg/community-programme)

RESOURCES (https://www.police.gov.sg/resources)

NEWS & PUBLICATIONS (https://www.police.gov.sg/news-and-publications)

JOIN US (https://www.police.gov.sg/join-us)

FAQS (https://va.ecitizen.gov.sg/cfp/CustomerPages/SPF/explorefaq.aspx)


CONTACT US (https://www.police.gov.sg/content/contact-us)

E-FEEDBACK (/content/policehubefeedback/efeedback.html)

SITEMAP (https://www.police.gov.sg/sitemap)

Privacy Statement (https://www.police.gov.sg/content/privacy-statement) | Terms of Use (https://www.police.gov.sg/content/terms-of-use) . © 2018 Singapore Police Force. A Member of The Home Team •(https://www.mha.gov.sg).





Jim Wong See Pah to: Joylrene

05/04/2018 11:57 AM

From:

Jim Wong See Pah/cdge/delgronotes

To:

Joylrene@lkkauto.com

Dear Joy

We refer the attached mail of 19.03.2018.

We further attached police investigation result whereby action taken against your client, together with video footage.

Look forward your favourable reply soon.

Thank you.

Best Regards Jim Wong

Claims Department / ComfortDelgro Engineering Pte Ltd

Off: 62148374 / Fax: 62141843

img-405112030-0001.pdf

img-405112016-0001.pdf

SHB6711L VC (TS).avi

1800 Mes

COMFORTDELCRO ENGINEERING

Our Ref :T 0118 / SHB6711L /JV	V(st)	ENG	NEEKING
Your ref :	CDGE Taxi Claims Dep		Engineering Pte L ad Singapore 5797
EQ Insurance Company Limited	59 Loyang Drive 4th Fli Singapore 508969	. Ma	Inline +65 6353 62 imilie +65 6250 97
5 Maxwell Road, MND Complex			www.cdge.com.
#17-00 Tower Block		Company 1	Registration Nat. 10050504
Singapore 069110			Worksho
Attn: Motor Claims Department	WITHOUT PREJUDICE		Bradd 205 Braddell Ro Singapore 5797
Dear Sir ACCIDENT INVOLVING OUR TAXI SH	B6711L YOUR INSURED	FBB4561L	59 Loyang On Singapore 5089
AND OTHER	ON <u>26.01.18</u>		Sin Min 383 Sin Ming Dri Singapore \$757
We are the authorised repair workshop for of Vehicle No: SHB6711L which was involve vehicle. The vehicle owner and the taxi drive assist them in presenting their claims again arising from the damage to the vehicle.	ed in the captioned accident with er concerned have requested a	h your insured and authorized us to	Panda 45 Pandah Ro- Singapore 6092 U 320 Ubi Road Singapore 4086
As the accident was caused by the neglige we are submitting these claims for your con			Seno 24 Senoko Lo Singapore 7 581
TAXI OWNER'S CLAIM 1 Cost of Repair 23 days Loss of Rental @\$_ 3 Survey Report Fees (Surveyed by M/s III 4 LTA Search Fees 5 GIA / Police Report Fees 6 Towing / Medical / Transporation Fees HIRER'S CLAIM 73 days Loss of Income @\$ We enclosed herewith the following docume a) Original repair bill and photocopies of policy and policy in the pair bill and photocopies of policy in the	Sub Total: 80.00 per day Total Claims: ents to support the claims: -	\$ - \$ 7.49 \$ - \$ 4,072.92 \$ 240.00	7 Sungei Kadut W Singapore 7287 Yish shun Industrial Pari Singapore 7687
c) GIA / Police report/s of : SH d) Letter of authority from owner / hirer / c () Witness statement/s () Towing/Med (X) Photograph/s of Accident Scene (x)	HB6711L operator dical bill/receipts () Certificate of Downtime/Mileage record	(x) Rental Rate letter	
Kindly look into the matter and let us hear fr soon as possible.			
Please note that it is a condition of any settl to any personal injury claim (if any) of the ta		without prejudice	
Yours faithfully			

Jim Wong
Deputy Manager

CDGE Claims Department

Tel: 6214 8374 Fax: 6214 1843 Email: jimwong@cdge.com.sg

This is a computer generated letter. No signature is required.

COMFORTDELGRO







Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)

Sent: Tuesday, 26 June 2018 2:18 PM
To: 'iwanchubby@hotmail.com'

Cc: Admin A

Subject: ACCIDENT INVOLVING FBB 4561L AND SHB 6711L ON 26/01/2018 ALONG PIE

(JURONG)

Our Ref: CC3/EQI18001809/Kja3

REDUAN BIN ABDULLAH

Policy Holder

Dear Sir/Madam,

ACCIDENT INVOLVING FBB 4561L AND SHB 6711L ON 26/01/2018 ALONG PIE (JURONG)

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: <u>joyirene@lkkauto.com</u> Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

VIANO (Maxi Cab) SHB6711L , FBB 4561 L ON 26-Jan-18 19:30

ALONG

PIE TOWARDS JURONG BEFORE TOH GUAN RD EXIT

I / We

SABTU B SAWAM

(Hirer) NRIC No.: S1371697H

kni

and/or

(Relief) NRIC No.:

Taxi Number

SHB6711L

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

27-Jan-2018

Name of Hirer

SABTU B SAWAM

Hirer NRIC

S1371697H

Signature:

Address

191 BOON LAY DRIVE 08-210

640191

Contact No.

92386663

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

8010325

EO INSURANCE COMPANY LIMITED

#17-00 5 MAXWELL ROAD TOWER BLOCK SINGAPORE 069110

CONTACT NO: 62239433

Description: 3P 26.01.18

ComfortDelGro Engineering Pte Ltd

Mainline + 65 5383 6280 Facsimile + 85 6380 9755 Workshops

59 Loyang Drive Singapore 608009 383 Sin Mire Drive Engapore 575717 45 Pendan Fload Singapore 609266

24 Benska Loop Strappore 758156 2 Burgel Kadul Way Snigspore 72879 6 Cefu Avenue 1 Snigspore 329537

COMPANY REG. NO.: 199506045W

Page: 1

TAX INVOICE

VEHCLE NO SHB6711L

INV. NO/DATE 91355735 05.02.2018

MAKE MERCEDES BENZ JOB NO. 305111471

MODEL

VIANO CDI Z.ZL

ODOMETER READING

DATE OF REG 24.04.2014

CHASSIS CODE WDF63981323811341

JOB TYPE

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt

Total Invoice amount

3,584.50

CHEWBEELENG 05.02,2018 16:07:23

Issued by : CHEWBEELENG 05.0 Repair Type : CLSO/57/57 Payment Type/Term : /Credit 30 days

medicinametry con gant on grant protestates and example to outposon and sense and example the travel COMPANY OF THE CONTROLS AND BUT MICHIEF THE THE TAIL OF STREET AND ATTER MICHIGAN THE PERSON.

ComfortDelGro Engineering Pte Ltd A member of COMFORTDELGRO

Head Office:

205 Braddell Road Singapore 579701

ACCOUNT No. INVOICE No. AMOUNT BANK/CHO No

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref:

CT18010827

Date: 05 February 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

26/01/2018 @ 19:30 hrs

ALONG

PIE TOWARDS JURONG BEFORE TOH GUAN RD EXIT

INVOLVING

FBB 4561 L

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHB6711L (the "Taxi"). The Taxi was hired to SABTU B SAWAM IC NO S1371697H a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$160.31 per day (inclusive of GST).

Please be advised that the Taxi was insured with India International Insurance Pte Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

			MILEAGE	HOOMS OF EVENTER 12		DATE	NAME OF DRIVER
DATE	NAME OF DRIVER	MILEAGE HEADING	TRAVELLED (KM)	FROM	TO	-	
0 1	SARCE		J	18.30	1.30A		
2 - 1 - 2 - C	25.84.8			18.10	2.35		
27. 1-15	S And.	- F88	12	15.50	12.6		
2000	SA3.1v	5475	770	19 145	2 00		
1	5 4-4-1.			51.7	16.50		
0 01 10 0		SUR	SUR KALL	1360	ţ.		
7 10.10.10) r J. v		V	7	13.51		
3 .01.18	MCCOGNA NO MA		1				

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time

Search Status Insurance Company Code Insurance Company Name

FBB4561L

26 Jan 2018 / 19:30:00

Successful

E04

EQ INSURANCE COMPANY LTD

Previous OK
SHB6711L



TAXI BUSINESS

05 APR 7015

FLEET SAFETY

Traffic Police 10 Ubi Avenue 3 Singapore 408865 Tel +68 6547 0000 Fax +85 6847 6259 www.police.gov.sg

Our Ref

: TP/IP/06131/2018

Date

: 29 March, 2018

SABTU BIN SAWAM BLK 191 BOON LAY DRIVE #08-210

SINGAPORE 640191



C18010827

3days LOI \$240 paid on 13.04.18

Dear Sir/Madam

ACCIDENT INVOLVING SHB6711L / FBB4561L / JPT8246 ON 26/01/2018 AT 1926 HRS ALONG PIE

I refer to the above accident.

- Please be informed that we have completed our investigations which shows that the rider of FBB4561L has committed an offence of Careless Driving under Rule 29 Road Traffic Rules. Action has been initiated against the rider for the said offence.
- If you have any queries, please contact the Investigation Officer, T.JEYATHESH at telephone number 6547 6232 or email at Thabagesh JEYATHESH@spf.gov.sg.

Yours faithfully

Roslan Ahmad, Stn Insp For Head Investigation Traffic Police

Singapore Police Force

Plant seleons Lot bases of



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To: M/s EQ INSURANCE COMPANY LTD

Date: 19/07/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No	FBB 4561L	(Insd Veh)	Your Ref. No. : DM18HO00556
Vehicle No.	SHB 6711L	(TP Veh)	Our Ref. No. : CC3/EQI18001809/K1ja3q2
Date of Accident	26/1/2018		

Remarks	2		
Final Settlement Sum	: \$	4,115.00	GLOBAL SUM
		4,117.77	
	: \$		
Others:	: \$	7.49	
Rental (If any)	: \$	400.78	2.5 days
Loss of Income	: \$	125.00	2.5 days
Final Repair Cost	: \$	3,584.50	
Liability		100%	

11	COMFORTDELGRO ENGINEERING PTE LTD	· ¢	4 115 00
"	COMI CIVIDEECINO ENGINEERING PIE EID	. Ψ	4,115.00
		: \$	

JOANNE LEE LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to	Federation	Internationale	Des Experts	En Automobile	
---------------	------------	----------------	-------------	---------------	--

EQ INSURANCE COMPANY LTD

Ref : CC3/EQI18001809/K1ja3q2

5 MAXWELL ROAD #17-00 TOWER BLOCK

Date: 19-07-2018

	OCOMPLEXSING		Date: 19-07-2018			
		- Company and the Company and	Code: EQI			
1.		Policy Particular	s :- THIRD PARTY CLA	IM		
	Insured Veh.	FBB 4561L	Veh. Inspected	SHB 6711L		
	Policy No.	DMMPHQ17-000943	Coverage (\$)	0.00		
	Claim No.	DM18HO00556	Excess (\$)	0.00		
	Assign From		Assign Date	29/01/2018		
2.		Vehicle Par	ticulars & Condition			
	Make & Model	MERCEDES BENZ VIANO	c.c	2143		
Engine No.		HIDDEN	Year of Reg.	2014		
	Chassis No.	WDF63981323811341	Colour	WHITE		
	Odometer	547699	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM		
	General	FAIR				
3.		Cond	itions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	225/60 R16C	HANKOOK	7 mm		
	L/H Front Tyre	225/60 R16C	HANKOOK	7 mm		
	R/H Rear Tyre	225/60 R16C	HANKOOK	7 mm		
	L/H Rear Tyre	225/60 R16C	HANKOOK	7 mm		
4.			tion of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE C	S REAR PORTION.			
	DAMAGES SEE D	ETAILS.				
5.	General Information					
	Accident Date	26/01/2018	Inspection Date	29/01/2018		
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969					
5a.	Remarks					
		ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS,				
5b.	Man see	Estimate Days of Repair				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Working Day	ys		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 6711L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER R/H SIDE ,RR	DEFORMED	473.60	473.60
1	TAIL LAMP LOWER GARNISH ,RH	TO REPAIR SEE LABOUR	61.90	
1	TAIL LAMP REFLECTOR UPPER ,RH	MISSING	105.74	105.74
1	REAR FENDER (RH)	DENTED	3,188.00	3,188.00
1	REAR FENDER PROTECTOR (RH)	SERVICEABLE	56.48	
	LESS 20% DISCOUNT		-777.14	-753.47
			3,108.58	3,013.87
	LABOUR			
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF TAIL LAMP LOWER GARNISH ,RH .		1,000.00	600.00
	SPRAY PAINTING CHARGE		500.00	360.00
	WIRING CHARGE		50.00	20.00
	TUFF KOTE.		50.00	20.00
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR		150.00	50.00
	REMOVE/REFIX REAR WINDSCREEN GLASS (SEALANT).		150.00	100.00
	REMOVE /REFIX REVERSE SENSOR.		120.00	20.00
	REAR WHEEL ALIGNMENT.	NOT NECESSARY	120.00	
			2,140.00	1,170.00
	GRAND TOTAL		5,248.58	4,183.87

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	3,350.00

Report Ref No. CC3/EQI18001809/K1ja3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report in whols or in part, does so at his or her own risk.