

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHB 6711L

DATE 29/1/2018 15:21

MAKE :

MODEL : MERCEDES BENZ VIANO (REAR)

LKK - Kalvin

| Qty | Parts Description/ Labour                       | Type | Unit Price | Amount                    |
|-----|---|------|------------|---------------------------|
|     | Bumper R/H Side, RR ✓                           |      |            | \$ 473.60                 |
|     | Tail Lamp Lower Garnish, RH <del>x repair</del> |      |            | \$ 61.90                  |
|     | Tail Lamp Reflector Upper, RH ✓                 |      |            | \$ 105.74                 |
|     | Rear Fender (RH) ✓                              |      |            | \$ 3,188.00               |
|     | Rear Fender Protector (RH) ✗                    |      |            | \$ 56.48                  |
|     | <b>SUB TOTAL</b>                                |      |            | <b>\$ 3,885.72</b>        |
|     | <b>LESS 20%</b>                                 |      |            | <b>\$ 777.14</b>          |
|     | <b>DISCOUNTED TOTAL</b>                         |      |            | <b>\$ 3,108.58</b>        |
|     | <b>Labour Charge</b>                            |      |            |                           |
|     | Panel Beating                                   |      |            | \$ <del>1,000.00</del> 36 |
|     | Spray Painting Charge                           |      |            | \$ <del>500.00</del> 20   |
|     | Wiring Charge                                   |      |            | \$ <del>50.00</del> 20    |
|     | Tuff Kote                                       |      |            | \$ <del>50.00</del> 20    |
|     | Remove/Refix Cushion & Upholstery Rear          |      |            | \$ <del>150.00</del> 50   |
|     | Remove/Refix Rear Windscreen Glass (sealant)    |      |            | \$ <del>150.00</del> 100  |
|     | Remove/Refix Reverse Sensor                     |      |            | \$ <del>120.00</del> 20   |
|     | Rear Wheel Alignment                            |      |            | \$ <del>120.00</del> ✗    |
|     | <b>TOTAL LABOUR</b>                             |      |            | <b>\$ 2,140.00</b>        |
|     | <b>ESTIMATE TOTAL</b>                           |      |            | <b>\$ 5,248.58</b>        |

Kalvin LKK  
 29/1/18 1545 hrs.  
 3 Days  
 4/5  
 After Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) not a resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.