



Chia

SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park E4  
Singapore 757105  
Tel: 65 6362 3427  
Fax: 65 6366 7420

### SMRT Vehicle Repair Estimate

Group : Buses / Taxis / Commercial

Reg. No. : GBB1479L Ref. No. : \_\_\_\_\_

Make / Model : TOYOTA HIACE Reg. Date : \_\_\_\_\_

Chassis No. : JTFHT02P800029905 Mileage : \_\_\_\_\_

Name of Driver : SAZLINDA BTE HASHIM Rental/Replacement Vehicle : Yes / No

Date/Time of Accident : 13/01/18 0945

Surveyer is Required? YES

If Yes, VICOM / LKK / AIS / Others MSIG : AXA

Vehicle is Towed Back? YES Date / Time : \_\_\_\_\_

Accident reporting date : 23/1/2018 0925

Type of Accident : Skid / Head-Rear / Head-On / Side Swipe / Others

Special Instruction to ARC, if any :  
176 Sin Ming Drive, Sin Ming Autocare, #04-13,16, S(575721)

The damages on the vehicle are as indicated in the following diagram.



Signed : \_\_\_\_\_ Date : \_\_\_\_\_

Accident Repair Job Card No: \_\_\_\_\_ Date Prepared : \_\_\_\_\_

Summary of Repair Estimates Repair Complete : \_\_\_\_\_

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ <u>4,930.00</u>	\$ <u>-</u>
Total Spray Painting Charges :	\$ <u>2,800.00</u>	\$ <u>-</u>
Total Material Charges :	\$ <u>13,140.00</u>	\$ <u>-</u>
Other Charges :	\$ <u>150.00</u>	\$ <u>-</u>
<b>TOTAL</b> :	<b>\$ <u>21,020.00</u></b>	<b>\$ <u>-</u></b>

Lump Sum Repair if any : \_\_\_\_\_

No. of Repair Days : [ 21 ] days [ \_\_\_\_\_ ] days

Signature : Prepared by  Adjusted by

QN No \_\_\_\_\_ Invoice No \_\_\_\_\_ Invoice Date \_\_\_\_\_

Signed : \_\_\_\_\_ Date : \_\_\_\_\_

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	
To top up a/c gas	\$ <del>150.00</del> 100	
to check wiring & system function	\$ <del>100.00</del> 60	
To transfer door mechanisam	\$ <del>300.00</del> 180	
To remove & refix a/c condenser , radiator fan assy	\$ <del>300.00</del> 180	
To remove & refix exhaust system	\$ <del>200.00</del> 120	
To remove & refix reverse sensor	\$ <del>80.00</del> 60	
To cutting welding knocking accident area front bumper , front bonnet , front door lh & rh , front door pillar lh & rh , side door lh & rh , support panel , radiator lower support panel , rear rh fender , front door pillar 2nd layer rh & lh	\$ <del>3,800.00</del> 1520	
<b>Total Labour</b>	\$4,930.00	\$0.00

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	
To respray front bumper , front bonnet , front door lh & rh , front door pillar lh & rh , side door lh & rh , support panel , radiator lower support panel , rear rh fender , front door pillar 2nd layer rh & lh side door floor panel	\$ <del>2,800.00</del> 1600	
<b>Total Spray Painting &amp; Panel Beating</b>	\$2,800.00	\$0.00

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	
TOWING FEE	\$ <del>150.00</del> 120	
<b>Total Other Costs</b>	\$150.00	\$0.00

11190.40

13988  
2797.60  
3920

Part 4 - Spare Parts / Material Usage

Ref No:

To be completed by Service Advisor, ARC							
Part Number	Parts Description	Qty	COST Price (\$)	Discount (%)	Final Price (\$)	Repair (R) / Replace (F)	Not given (X) / Repair (R) / Replace (F)
	FRONT BUMPER	1	\$ 220.00	✓	to be deleted		
	FRONT BUMPER BRACKET LH	1	\$ 80.00	✓	dis		
	FRONT BUMPER BRACKET RH	1	\$ 80.00	✓	dis		
	FRONT BUMPER TOW HOCK COVER LH	1	\$ 10.00	✓	dis		
	FRONT BUMPER TOW HOCK COVER RH	1	\$ 10.00	✓	dis		
	FRONT BUMPER FOG LAMP LH	1	\$ 80.00	X	acc		
	FRONT BUMPER FOG LAMP RH	1	\$ 80.00	X	acc		
	FRONT BONNET HINGE LH	1	\$ 40.00				
	FRONT BONNET HINGE RH	1	\$ 40.00				
	FRONT BONNET	1	\$ 280.00	X	R		
	FRONT DOOR LH	1	\$ 650.00	✓	dt		
	FRONT DOOR RH	1	\$ 650.00	X	Repair		
	FRONT DOOR PILLAR LH	1	\$ 330.00	✓	dt		
	FRONT DOOR PILLAR 2ND LAYER	1	\$ 290.00	X	R		
	FRONT DOOR HINGE UPPER LH	1	\$ 55.00	X	R		
	FRONT DOOR HINGE LOWER LH	1	\$ 55.00	X	R		
	FRONT DOOR CHECK LH	1	\$ 85.00	X	svc		
	FRONT DOOR PILLAR RH	1	\$ 290.00	X	R		
	FRONT DOOR HINGE UPPER RH	1	\$ 55.00	X	R		
	FRONT DOOR HINGE UPPER LH	1	\$ 55.00	X	R		
	FRONT DOOR STEP COVER LH		\$ 95.00	✓	dis		
	FRONT DOOR STEP COVER RH		\$ 95.00	✓	dis		
	FRONT DOOR STEP PANAL RH		\$ 125.00	✓	dt		
	LH SIDE DOOR		\$ 750.00	✓	dt		
	RH SIDE DOOR		\$ 750.00	✓	dt		



Part Number	Parts Description	Qty	cost price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace(/)	Not given (X) Repair (R) Replace(/)
	AIR COND SUCTION HOSE	1	\$ 210.00	—	WA		
	AIR COND DISCHARGE HOSE	1	\$ 195.00	—	WA		
	AIR FILTER BOX ASSY	1	\$ 340.00	—	dis		
	REAR BUMPER	1	\$ 230.00	—	det		
	REAR BUMPER BRACKET LH	1	\$ 45.00	—	WA		
	REAR BUMPER BRACKET RH	1	\$ 45.00	—	WA		
	REVERSE SENSOR	1	\$ 180.00	—	WA		
	REAR FENDER RH	1	\$ 1,200.00	X	R		
	FRONT EXHAUSE PIPE	1	\$ 2,600.00	—	WA		
	REAR EXHAUST PIPE	1	\$ 495.00	X	R		
	NUMBER PLATE <i>FRWA</i>	1	\$ 30.00	—	dis		
	DOOR COMPANY STICKER	2	\$ <del>100.00</del>	20	WA		
TOTAL MATERIALS			\$ 14,040.00		\$		

Surveyor Remark:

*12585  
2017  
10.068.*