



Cher.

SMRT Vehicle Repair Estimate

Group : Buses / Taxis / **Commercial**

Reg. No. : GBB1479L

Make / Model : TOYOTA HIACE

Chassis No : JTFHT02P800029905

Name of Driver : SAZLINDA BTE.HASHIM

Ref. No. : _____

Reg. Date : _____

Mileage : _____

Rental/Replacement Vehicle : Yes / No

Date/Time of Accider : 13/01/18 0945

Surveyer is Required ? **YES**

If Yes, VICOM / LKK / AIS / Others MSIG : AXA


Vehicle is Towed Back ? YES Date / Time : _____

Accident reporting date : 23/1/2018 0925

Type of Accident : Skid / Head-Rear / Head-On / Side Swipe / **Others**

Special Instruction to ARC, if any :

176 Sin Ming Drive, Sin Ming Autocare, #04-13,16, S(575721)



Signed : _____ Date : _____

Accident Repair Job Card No. : _____ Date Prepared : _____

Summary of Repair Estimates Repair Complete : _____

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Charges :	\$	4,930.00	\$	-
Total Spray Painting Charges	\$	2,800.00	\$	-
Total Material Charges :	\$	13,140.00	\$	-
Other Charges :	\$	150.00	\$	-
TOTAL :	\$	21,020.00	\$	-

21,920

Lump Sum Repair, if any : _____

No. of Repair Days : [21] days [] days

Signature : Prepared by: _____

Adjusted by: _____

QN No. _____ Invoice No. _____ Invoice Date _____

Signed : _____ Date : _____

Part 1 - Labour Works

Job Scope	Quotation from ARC	
To top up a/c gas	\$ 150.00	100
to check wiring & system function	\$ 100.00	60.
To transfer door mechanisam	\$ 300.00	180.
To remove & refix a/c condenser , radiator fan assy	\$ 300.00	180
To remove & refix exhaust system	\$ 200.00	120.
To remove & refix reverse sensor	\$ 80.00	60.
To cutting welding knocking accident area front bumper , front bonnet , front door lh & rh , front door pillar lh & rh , side door lh & rh , support panel , radiator lower support panel , rear rh fender ,front door pillar 2nd layer rh & lh	\$ 3,800.00	1500.
Total Labour	\$4,930.00	\$0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	
To respray front bumper , front bonnet , front door lh & rh , front door pillar lh & rh , side door lh & rh , support panel , radiator lower support panel , rear rh fender ,front door pillar 2nd layer rh & lh side door floor panel	\$ 2,800.00	1600
Total Spray Painting & Panel Beating	\$2,800.00	\$0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	
TOWING FEE	\$ 150.00	120.
Total Other Costs	\$150.00	\$0.00

Part 4 - Spare Parts / Material Usage

Ref No.:

To be completed by Service Advisor, ARC							
Part Number	Parts Description	Qty	COST Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (/)	Not given (X) Repair (R) Replace (/)
	FRONT BUMPER	1	\$ 220.00	✓	not def		
	FRONT BUMPER BRACKET LH	1	\$ 80.00	✓	dis		
	FRONT BUMPER BRACKET RH	1	\$ 80.00	✓	dis.		
	FRONT BUMPER TOW HOCK COVER LH	1	\$ 10.00	✓	dis		
	FRONT BUMPER TOW HOCK COVER RH	1	\$ 10.00	✓	dis		
	FRONT BUMPER FOG LAMP LH	1	\$ 80.00	X	acc		
	FRONT BUMPER FOG LAMP RH	1	\$ 80.00	X	acc		
	FRONT BONNET HINGE LH	1	\$ 40.00				
	FRONT BONNET HINGE RH	1	\$ 40.00				
	FRONT BONNET	1	\$ 280.00	X	R.		
	FRONT DOOR LH	1	\$ 650.00	✓	dt		
	FRONT DOOR RH	1	\$ 650.00	X	Repair		
	FRONT DOOR PILLAR LH	1	\$ 330.00	✓	dt		
	FRONT DOOR PILLAR 2ND LAYER	1	\$ 290.00	X	R,		
	FRONT DOOR HINGE UPPER LH	1	\$ 55.00	X	R		
	FRONT DOOR HINGE LOWER LH	1	\$ 55.00	X	R.		
	FRONT DOOR CHECK LH	1	\$ 85.00	X	svc		
	FRONT DOOR PILLAR RH	1	\$ 290.00	X	R		
	FRONT DOOR HINDE UPPER RH	1	\$ 55.00	X	R		
	FRONT DOOR HINGE UPPER LH	1	\$ 55.00	X	R		
	FRONT DOOR STEP COVER LH		\$ 95.00	✓	dis		
	FRONT DOOR STEP COVER RH		\$ 95.00	✓	dis		
	FRONT DOOR STEP PANAL RH		\$ 125.00	✓	not		
	LH SIDE DOOR		\$ 750.00	✓	dt		
	RH SIDE DOOR		\$ 750.00	✓	dt		

