

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 29/1/2018

Reference: SKL608D
OPEL INSIGNIA
Make: 2.0AT

To Whom It May Concern

Dear Sir,

TPAIG.
Xiao Tong.

RE: VEHICLE :SKL608D
CHASSIS NO.:W0LGM5ED3D1103326
ENGINE NO.:A20NFT0N042770

Name of insured :Alpine Car Rental Pte Ltd
Date of accident.: 23/01/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	RHF Headlamp <i>new</i>	\$ 840.00
2	1	Front Bumper <i>Repair</i>	\$ 1,387.00
3	1	RHF Foglamp Cover <i>3 new</i>	\$ 83.00
4	1	RHF Foglamp	\$ 282.00
5	1	LHF Bumper Bracket - Guide <i>part</i>	\$ 65.00
6	1	RHF Bumper Bracket - Guide <i>part</i>	\$ 65.00
7	1	RHF Fender <i>crushed</i>	\$ 644.00
8	1	RHF Fender Liner <i>crushed</i>	\$ 110.00
9	1	RHF Fender Lamp <i>new</i>	\$ 45.00
10	1	RHF Absorber	\$ 413.00
11	1	RHF Wheel Hub <i>part</i>	\$ 768.00
12	1	RHF Control Arm <i>part</i>	\$ 934.00
13	1	RHF Knuckle Arm Assy	\$ 437.00
14	1	RH Wind Mirror Assy <i>part</i>	\$ 534.00
15	1	RH Wind Mirror Cover <i>missing</i>	\$ 83.00
16	1	RH Wind Mirror Glass <i>new</i>	\$ 618.00
17	1	RHF Door <i>dented</i>	\$ 2,061.00
18	1	RHF Door Upper Hinge	\$ 58.00
19	1	RHF Door Lower Hinge <i>part</i>	\$ 35.00
20	1	RHF Door Limiter	\$ 93.00
21	1	RHR Door <i>part</i>	\$ 2,061.00
22	1	RHR Fender <i>Repair</i>	\$ 497.00
23	1	RHR Taillamp <i>part</i>	\$ 420.00

3432

3088.80

Parts Total: \$ 12,533.00
Less 10%: \$ 1,253.30
Total : \$ 11,279.70

Labour

Labour Description

No.

Price (SGD)

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 per day)	\$ 3,900.00	1950
2	Carry out spray painting on accident affected area (\$550 per day)	\$ 3,300.00	2750
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 130.00	30
4	To remove and replace LHF/RHF under carriage parts	\$ 650.00	+
5	To conduct 4 wheel alignment	\$ 180.00	80
6	To refocus headlamp	\$ 130.00	+
7	To remove and refit front sensor	\$ 130.00	+
8	Remove and refit rear windscreen	\$ 260.00	+
9	To conduct transfer door mechanism to new door panel	\$ 260.00	!

4910 Labour Total : \$ 8,940.00

Others

Other Description

No.	Qty	Description	Price (SGD)
1	10	Front bumper clip <i>Not in</i>	\$ 65.00
2	3	Front fender liner clip <i>in</i>	\$ 19.50
3	1	Front sensor 1 set <i>Not in</i>	\$ 440.00
4	1	RHF Tyre <i>Not in</i>	\$ 180.00
5	1	RHF Rim <i>in</i>	\$ 260.00
6	10	RHF Door Inner Trim Clips <i>in</i>	\$ 65.00
7	10	RHR Door Inner Trim Clips <i>Not in</i>	\$ 65.00
8	3	Rear fender liner clips <i>Not in</i>	\$ 19.50

3095 Other Total: \$ 1,114.00

GRAND TOTAL: \$ 21,333.70

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully



Suhaimi Ong

Service Executive

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before and/or spray painting
- To display damaged parts during resurvey
- Parts price subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Limy
29/01/18
h/s. 06 Days
total: 8308.30
h/s: 6.6k